

January 2026

# Powerlink 2027-32 Revenue Proposal

## Project Pack

### CP.02800 Alligator Creek Substation Reinvestment



# Forecast Capital Expenditure - Capital Project Summary

Powerlink 2027-32 Revenue Proposal

January 2026

*Project Status: Unapproved*

## Network Requirement

The Alligator Creek Substation was established in the early 1980s. It is a 132/33kV bulk supply point for the southern Mackay region providing supply to the Aurizon Oonooie and Mackay Ports connections, the Hay Point and Dalrymple Bay coal loading terminals and surrounding communities via the Ergon network. The substation was subsequently expanded and reconfigured in the mid-2000's.

Some of the primary plant dates from the original substation establishment and is now over 40 years old. Selected circuit breakers are now operating with reduced reliability due to age related condition issues, including recurring SF6 leaks. Instrument transformers are porcelain-housing type, and based on available statistical data have increased probability of catastrophic failure presenting high safety risk. A number of disconnectors and earth switches have high contact resistance and corrosion of various parts requiring increased maintenance. There are also electrical clearance issues in bay D05, necessitating replacement of the transformer circuit breaker and the current transformers with a Dead Tank Circuit Breaker [1].

A condition assessment indicates that most secondary systems devices are reaching the end of their technical asset life, recommending replacement by 2025. It further notes that the field cables are suitable for a further 15 to 20 years of service and that the secondary systems panels are in good condition and may be retained [2]. The driver for replacing secondary systems is the obsolescence and end of manufacturer support for the existing relays. Ageing secondary systems, which are no longer supported by the manufacturer, and primary plant showing signs of deterioration at Alligator Creek Substation are increasingly at risk of failing to comply with Schedule 5.1.9(c) of the National Electricity Rules, AEMO's Power System Security Guidelines and the reliability standard included in Powerlink's Transmission Authority.

Powerlink's 2025 Central scenario forecast confirms there is an enduring need to maintain electricity supply into the southern Mackay area. The removal or reconfiguration of the Alligator Creek 132/33kV Substation due to secondary system or primary plant failure or obsolescence would violate Powerlink's N-1-50MW/600MWh Transmission Authority reliability standard [3].

## Recommended Option

As this project is currently 'Unapproved', project need and options will be subjected to the public RIT-T consultation process to identify the preferred option closer to the time of investment.

The current recommended option is for in-situ replacement of all secondary systems in the existing control building by 2028 together with replacement of selected primary plant [4].

Options considered but not proposed include:

- Replacement of all secondary systems in a new demountable building – expected to be greater overall cost.


Figure 1 shows the current recommended option reduces the forecast risk monetisation profile of the Alligator Creek Substation primary and secondary systems from around \$10.3 million per annum in 2029 to less than \$0.2 million from 2030 [6].

# Forecast Capital Expenditure - Capital Project Summary

Powerlink 2027-32 Revenue Proposal

January 2026

Figure 1 Annual Risk Monetisation Profile (\$ Real, 2025/26)



## Cost and Timing

The estimated cost to replace selected primary plant and all secondary systems at Alligator Creek Substation is \$26.3 million (\$2025/26) [5].

Target Commissioning Date: October 2028.

## Documents in CP.02800 Project Pack

### Public Documents

1. T065 Alligator Creek Condition Assessment Report
2. T065 Alligator Creek Secondary System Condition Assessment Report
3. CP.02800 Alligator Creek Substation Reinvestment – Planning Statement
4. CP.02800 Alligator Creek Substation Reinvestment – Project Scope Report
5. CP.02800 Alligator Creek Substation Reinvestment – Concept Estimate
6. CP.02800 Alligator Creek Substation Reinvestment – Risk Cost Summary Report



## Alligator Creek

# PRIMARY PLANT CONDITION ASSESSMENT REPORT

Report requested by:	[REDACTED]	Request Date:	23/05/2024
Report Prepared by:	[REDACTED]	Date of site visit:	18/06/2024
AUTHOR/S:	[REDACTED]		
Report Approved by:	[REDACTED]	Report Approval Date:	10/04/2025
Report Reviewed by:	[REDACTED]	Review Date:	21/10/2024
Issue Approved by:		Issue Date:	

Date	Version	Objective ID	Nature of Change	Author	Authorisation
16/09/2024	1	A5631242	-	[REDACTED]	

**Note:** Where indicator symbol ☀# is used (# referring to version number) it indicates a change/addition was introduced to that specific point in the document. If the indicator symbol ☀# is used in a section heading it means the whole section was added/changed.

**IMPORTANT:** - The condition assessment report provides an overview of the condition of all structures and equipment (excluding protection relays, control systems and telecommunication equipment) as stated in the scope and high level recommendations for their timely replacement. As it is snapshot in time and subject to the accuracy of prediction methodology, it is valid for 3 years from site visit date stated above.

© Copyright Powerlink Queensland

All rights reserved

Powerlink Queensland owns copyright and the confidential information contained in this document. No part of the document may be reproduced or disclosed to any person or organisation without Powerlink Queensland's prior written consent.

Page 1 of 30

OBJECTIVE ID (A5631242)  
CONFIDENCE

COMMERCIAL IN

1 (30)

ANY PRINTED VERSION OF THIS DOCUMENT IS UNCONTROLLED

## Contents

<b><u>EXCECUTIVE SUMMARY</u></b>	<b>4</b>
<b><u>1. INTRODUCTION</u></b>	<b>4</b>
1.1 SYSTEM INFORMATION	4
1.2 RATINGS	7
1.3 ASSET AGE	8
1.4 SCOPE OF SITE CONDITION ASSESSMENT	9
<b><u>2. CONDITION ASSESSMENT</u></b>	<b>9</b>
2.1 SUBSTATION	9
2.2 132kV SWITCHING BAYS	9
2.2.1 T065 - D06 - 7175 – 7175 FEEDER BAY	9
2.2.2 CORRECTIVE MAINTENANCE COST	19
2.2.3 FUTURE OPERATION REQUIREMENTS	20
2.2.4 T065-D01-7319- 7139 FEEDER BAY	20
2.2.1 T065-D05-442- 132kV 2 TRANSF BAY (SPECIAL RECOMMENDATIONS- COMPLIANCE BASED)	24
<b><u>3. RECOMMENDATION:</u></b>	<b>25</b>
3.1 T065 - D06 - 7175 – 7175 FEEDER BAY	25
3.2 T065-D01-7319- 7139 FEEDER BAY	26
3.3 T065-D05-442- 132kV 2 TRANSF BAY	26
<b><u>4. ASSET CONDITION ASSESSMENT OVERVIEW</u></b>	<b>26</b>
<b><u>5. REFERENCE INFORMATION</u></b>	<b>28</b>
<b><u>6. APPENDIX</u></b>	<b>30</b>
6.1 REPLACEMENT INDEX METHODOLOGY	30

---

## List of Figures

Figure 1: Single Line Diagram .....	5
Figure 2- T065 Alligator Creek Substation Electrical Plant General Arrangement .....	6
Figure 3: Overview of T065 Alligator Creek HV Supply Network.....	7
Figure 4- Repair of Air Leaks at Multiple Locations.....	11
Figure 5- Overview of 71752 indicate multiple corrosion.....	12
Figure 6- Operation Counter Corrosion .....	12
Figure 7- Grade 1 to Grade 3 Corrosion .....	12
Figure 8- Mid points bolts and nuts corrosion .....	13
Figure 9- Insulation UV damage .....	13
Figure 10- Corrosion on 132kV Bus Isolator 71753 Components .....	15
Figure 11- Key Dissolved Gases in Oil-PH-A.....	15
Figure 12- Key Dissolved Gases in Oil-PH-B.....	15
Figure 13- Key Dissolved Gases in Oil-PH-C .....	16
Figure 14- Moisture in Oil-PH-A.....	16
Figure 15- Moisture in Oil-PH-B.....	16
Figure 16- Moisture in Oil-PH-C .....	16
Figure 17-Current Transformers overall View .....	17
Figure 18- Corrosion on CT Fittings.....	17
Figure 19- Corrosions on bolts and nuts .....	17
Figure 20- C- Voltage Transformer with Clear Oil .....	18
Figure 21- A- Voltage Transformer with Dark Oil .....	18
Figure 22- B- Voltage Transformer with Dark Oil .....	18
Figure 23- Corrosion at surge arrestor bolts and steel work .....	19
Figure 24 - H065-D06 Corrective Maintenance Cost .....	20
Figure 25- Corrosion on 132kV ES 73190 Pivot arm .....	22
Figure 26- Corrosion on 132kV ES 73190 fixed contact supports and guides.....	22
Figure 27- Corrosion on 132kV Isolator 73191 .....	24

## List of Tables

Table 1 – T065 Substation equipment ratings .....	7
Table 2 – T065-D06-7175 Equipment.....	9
Table 3 – T065-D01-7319 Equipment.....	21
Table 4 – T065-D05-442- Equipment .....	25
Table 5 - Recommendations .....	26

## List of Photos

Photo 1: Aerial Photograph of T065 Alligator Creek Substation.....	6
--	---

## EXCECUTIVE SUMMARY

This report provides an overview of the condition of the high voltage equipment only in some limited parts of this site, the whole feeder bay T065-D06 7175 and CVTs in T065-D01-7319-7139 feeder bay. In addition, it explains compliance issues in T065-D05-442-4422. The condition and status of all other high voltage equipment is in satisfactory condition.

The report aims to identify asset condition and compliance triggers and forecasted risks associated with the current state of high voltage substation equipment, their supporting structures, and related infrastructure. Based on these findings, recommendations for refurbishment or replacement are provided.

The assessment has been formulated based on the data extracted from computerised maintenance management system (SAP) including:

- Notifications and work orders, dissolved gas analysis (DGA) and other test and measurement results;
- Equipment age information combined with available photos;
- Historical data analysis;
- Enhanced with the engineering understanding of the functions and engineering judgement of expected service life.

The summary of recommendations is contained in Table 3 presented in section 5 of this report.

## 1. INTRODUCTION

This condition assessment is based on a site visit conducted on 18/06/2024, available design data and drawings, updated SAP data (as of Jun 2024), and recommendations from the civil condition assessment report dated 16-07-2024 (A5579008).

### 1.1 System information

T065 Alligator Creek substation was established in the early 1980s. It is a 132/33kV bulk supply point for the southern Mackay region providing supply to the Aurizon Oonooie and Mackay Ports connections, the Hay Point and Dalrymple Bay coal loading terminals and surrounding communities via the Ergon network.

T065 Substation consists of:

- 3 x 132kV buses;
- 6 x 132kV feeder bays;
- 2x132kV bus section bays;
- 1 x 132kV capacitor bay;
- 1 x 132kV static compensator bay;
- 2 x 132kV transformer bays;
- 2 x 132/33/11kV transformers;
- 1 x 132kV shunt capacitor;
- 2x33kV buses (owned by Ergon), and
- 1x33kV bus section bay (owned by Ergon).




Figure 1: Single Line Diagram




Figure 2- T065 Alligator Creek Substation Electrical Plant General Arrangement



Photo 1: Aerial Photograph of T065 Alligator Creek Substation



Figure 3: Overview of T065 Alligator Creek HV Supply Network

## 1.2 Ratings

The maximum fault levels calculated in June 2024 are:

- 132kV L-G – 5.9 kA
- 33kV L-G – 13.36 kA
- 26.2kV 3ph – 13.31 kA
- 11kV 3ph – 13.82 kA

Below table provides overview of continuous current and fault current ratings of all high voltage bays in Strathmore substation, incl. recommendations.

Table 1 – T065 Substation equipment ratings

Functional Loc.	Description	Start-up date	Bay Continuous Rating	Bay Fault Current rating	Fault Current Period	Comments on Rating
T065-D01-7319	7319 FEEDER BAY 132kV	14/09/2008	1,250 A	25kA	1s	Transmission line winter emergency rating is 800 A.
T065-D02-482-	132kV 2 STATIC COMPENSATOR BAY	01/07/2009	1000A	25kA	1s	-
T065-D03-411-	132kV 1-2 BUS SECTION BAY	21/03/2018	2000A	31.5kA	1s	Unable to check, planning to confirm, unlikely

						limiting full load flow for both transformers.
T065-D04-7119	7119 FEEDER BAY	01/07/1982	773A	25kA	1s	Transmission line winter emergency rating is 767.3 A.
T065-D05-442-	132kV 2 TRANSF BAY	01/07/1982	1250A	25kA	1s	Adequately rated, limited by the disconnector, but not limiting use of full short term loading of power transformer.
T065-D06-7175	7175 FEEDER BAY	01/07/1986	773A	31.5kA	1s	Transmission line winter emergency rating is 400 A.
T065-D51-7336	7336 FEEDER BAY 132kV	01/07/2009	1000A	40kA	1s	Transmission line winter emergency rating is 623.4 A.
T065-D52-481-	132kV 1 CAPACITOR BAY	27/01/2004	1,046A	40kA	1s	-
T065-D53-412-	1-3 BUS SECTION BAY 132kV	11/04/2008	3000A	40kA	1s	Unable to check, planning to confirm, unlikely to be limiting any flows.
T065-D54-7152	7152 FEEDER BAY 132kV	28/03/2008	1600A	40kA	1s	Transmission line winter emergency rating is 777.9 A.
T065-D55-443-	3 TRANSFORMER BAY 132kV	28/03/2008	1600A	40kA	1s	Adequately rated, not limiting use of full short term loading of power transformer.
T065-D56-7320	7320 FEEDER BAY 132kV	28/03/2008	1600A	40kA	1s	Transmission line winter emergency rating is 800 A.
T065-KD-KD1-	132kV 1 BUS	05/07/1999	2,425A	25kA	1s	Unable to check, planning to confirm
T065-KD-KD2-	132kV 2 BUS	05/07/1999	2,425A	25kA	1s	Unable to check, planning to confirm.
T065-KD-KD3-	132kV 3 BUS	05/07/1999	2,400A	40kA	1s	Unable to check, planning to confirm.
T065-M02-444-	2 SVC 132kV 4 TRANSFORMER BAY	31/07/2009	1,838A	-	-	-

All equipment at this substation is rated adequately for the calculated fault levels at present.

### 1.3 Asset age

The Alligator Creek 132 kV substation was established in 1982. Some of the high voltage equipment has been replaced in 2008, 2009, and 2014. However, there are still high voltage equipment in service that was originally installed during the substation's establishment, making it 42 years old.

Major upgrades in the last 20 years include:

- CP.02695 T065 Alligator Creek 1-2 Bus Section Bay
- CP.01346 – Alligator Creek Substation Extension (QR Mackay Port)
- CP.01080 – Alligator Creek 132 kV Capacitor Bank
- CP.01251 – Alligator Creek 132 kV SVC
- CP.02800 – Alligator Creek 2T Primary Plant Replacement
- CP.01344 - Alligator Creek Substation Extension Louisa Creek

And a number of other projects related to power transformers, access road, circuit breaker replacements, oil separation systems, etc.

## **1.4 Scope of site condition assessment**

The site condition assessment is restricted to the following high voltage equipment and associated support structures owned by Powerlink:

- T065-D06-7175 - 7175 FEEDER BAY
- T065-D01-7319 - 7319 FEEDER BAY (Desktop Condition Assessment)
- T065-D05-442 - 2T transformer bay (Desktop Compliance Assessment)

## **2. CONDITION ASSESSMENT**

### **2.1 Substation**

With respect to the civil and structural aspects of this bay no intervention is required, however, some minor maintenance is recommended.

During this investigation it was confirmed that according to the Asbestos Register, there are asbestos containing materials in this site. The Asbestos Register shall be consulted before any maintenance work or project activities are planned & performed.

### **2.2 132kV Switching Bays**

#### **2.2.1 T065 - D06 - 7175 – 7175 FEEDER BAY**

This bay, constructed in 1986, has retained all its original equipment except for the Phase-C capacitor voltage transformer, which was replaced in 2015 due to secondary voltage failure. The equipment for this bay, along with their condition assessment health indices, is detailed in Table 2.

**Table 2 – T065-D06-7175 Equipment**

Functional Loc.	Description	Model number	Start-up date	Manufacturer	Equipment	HI
T065-D06-7175-5VTA	CAPACITOR VOLTAGE TRANSFORMER	CVE145/650	30/09/1986	HAEFELY	20008298	9
T065-D06-7175-5VTB	CAPACITOR VOLTAGE TRANSFORMER	CVE145/650	30/09/1986	HAEFELY	20008296	9

T065-D06-7175-5VTC	CAPACITOR VOLTAGE TRANSFORMER	TCVT145C	04/11/2015	TRENCH LIMITED	20077313	3
T065-D06-7175-71750	EARTH SWITCH	AMB145	30/09/1986	SIEMENS	20011658	7
T065-D06-7175-71751	ISOLATOR	SSBIII-145	30/09/1986	SIEMENS	20011675	7
T065-D06-7175-71752	CIRCUIT BREAKER	120-SFM-32A	31/01/1985	MITSUBISHI	20008248	8
T065-D06-7175-71753	ISOLATOR	SSBIII-145	30/09/1986	SIEMENS	20011676	7
T065-D06-7175-7175CTA	CURRENT TRANSFORMER	MODEL325	10/02/1983	MODERN PRODUCTS	20008257	9
T065-D06-7175-7175CTB	CURRENT TRANSFORMER	MODEL325	10/02/1983	MODERN PRODUCTS	20008256	9
T065-D06-7175-7175CTB	CURRENT TRANSFORMER	MODEL325	10/02/1983	MODERN PRODUCTS	20008255	9
T065-D06-7175-7175SAA	SURGE ARRESTOR (GAPLESS)	ZLA-X15S	01/07/1987	HITACHI	20011709	9
T065-D06-7175-7175SAB	SURGE ARRESTOR (GAPLESS)	ZLA-X15S	01/07/1987	HITACHI	20011710	9
T065-D06-7175-7175SAC	SURGE ARRESTOR (GAPLESS)	ZLA-X15S	01/07/1987	HITACHI	20011711	9

### 2.2.1.1 T065 - D06 - 7175 – 71752 CIRCUIT BREAKER

The MITSUBISHI live tank circuit breaker (CB) unit is a GAS-insulated breaker with a porcelain housing. It features a pneumatic operating mechanism with a spring for energy storage and uses SF6 gas for insulation. This CB has been in operation for 37 years and has recorded 300 operations on its counter. This model is no longer in production, complicating spare parts sourcing. Currently, there are 30 of these circuit breakers still in service, with three scheduled for replacement under projects CP.02100 and CP.01015. Majority of these circuit breakers including this one also have internal wiring insulation deterioration due to the UV exposure. Currently, a spare breaker is available.

The maintenance records indicate a single air leak which has been fixed by the maintenance crew. During the site visit, repairs of air leaks at multiple locations were noted, as shown in figure 4.

In addition to the fixed air leak, multiple rusted bolts and washers on all three poles were reported and are scheduled to be addressed during the 2025 service. The operation counter also exhibits significant corrosion and needs replacement. These issues were observed during the site inspection, as indicated in figures 5 through 8. There is also internal wiring deterioration as per figure 9.

Although there is no major maintenance concern, the obsolescence of the **Kaji** air compressor and the unavailability of spare parts pose significant risks.

**Considering the current equipment strategy preference for Dead Tank Circuit Breaker (DTCB), it is recommended to replace this CB along with current transformers (CTs) with DTCB within two years to ensure safety risks associated with current transformers**

remain acceptable. Additionally, the foundation and support structure will also need to be replaced.



Figure 4- Repair of Air Leaks at Multiple Locations



Figure 5- Overview of 71752 indicate multiple corrosion



Figure 7- Grade 1 to Grade 3 Corrosion



Figure 6- Operation Counter Corrosion



Figure 8- Mid points bolts and nuts corrosion



Figure 9- Insulation UV damage

### 2.2.1.2 T065 - D06 - 7175 - 71750 EARTH SWITCH

The Earth switch, manufactured by Siemens (Model AMB145), was installed in 1986 and has been in continuous operation for 38 years. Maintenance records document number of notifications concerning worn bushings stopping correct travel, which required replacement of the bushing in 2019. Additionally, corrosion was reported on the main operating arm and U-bolt nuts in 2016, with remedial actions completed in 2018. At present, the U-bolts on the drive arms exhibit significant corrosion and require replacement. This issue remains unresolved to date.

### 2.2.1.3 T065 - D06 - 7175 - 71751/3 ISOLATOR

The line and bus isolators are Siemens model SSBIII-145 and have been in service for 38 years. Maintenance records indicate that both the bus isolator 71753 and line isolator 71751 have experienced reoccurring issues, primarily related to corrosion and high contact resistance. For bus isolator 71753, surface rust has been detected on various components, including bolts and nuts holding the fixed insulators to the post plates. These issues were noted in 2012, 2016, 2022, and 2023, leading to periodic treatments and replacements. High contact

resistance was identified in phases A, B, and C of the bus isolator in 2016, which has been addressed by maintenance interventions.

Similarly, line isolator 71751 has been subjected to ongoing maintenance due to rust and operational stiffness. Surface rust on bolts and components was reported in 2009, 2012, and 2021, with treatments planned during scheduled outages. In 2017, stiffness in the operation of the isolator led to cleaning and lubrication of its components. Additionally, high contact resistance was also found in the line isolator, which was fixed by contacts removal and cleaning. A hot joint on the C phase of line isolator 71751 was reported in October 2023, requiring further investigation and repairs. Ongoing monitoring and future scheduled repairs are planned, with actions deferred until the next major outage in 2025.

Siemens has stopped manufacturing these disconnectors and earth switches, leading to significant challenges in obtaining product support and spare parts. **It is recommended to replace the disconnectors and earth switches, along with their foundations if necessary, within the next two years, in conjunction with the circuit breaker replacement.**






Figure 10- Corrosion on 132kV Bus Isolator 71753 Components

#### 2.2.1.4 T065 - D06 - 7175 - 7175CT CURRENT TRANSFORMERS

The current transformers are Modern Products MODEL325, oil-filled, porcelain insulated, hermetically sealed design utilizing a gas cushion. Installed in 1986, these current transformers have been in continuous operation for 41 years. Seven identical units were replaced mainly due to oil leaks, with no catastrophic failures recorded. Additionally, nine units have been retired or mothballed along with their respective bays.

Routine oil sample analysis has not detected any abnormalities, and levels of key dissolved gases and moisture remain within acceptable limits.



Figure 11- Key Dissolved Gases in Oil-PH-A




Figure 12- Key Dissolved Gases in Oil-PH-B



**Figure 13- Key Dissolved Gases in Oil-PH-C**



**Figure 14- Moisture in Oil-PH-A**



**Figure 15- Moisture in Oil-PH-B**

Maintenance records indicate no issues with these current transformers since their installation. The oil levels for all three phases were noted to be normal during the site inspection. Minor corrosion was observed on several bolts and nuts across the three phases (Figures 16-18).



**Figure 16- Moisture in Oil-PH-C**



Figure 17-Current Transformers overall View



Figure 18- Corrosion on CT Fittings



Figure 19- Corrosions on bolts and nuts

While they appear to be in reasonable condition and their DGA analyses are satisfactory, it is known considering their age that there is increased probability of explosive failures. Considering these are oil filled CTs in porcelain housing the potential safety consequences of catastrophic failure represent an unacceptable risk.

**It is recommended that these current transformers be replaced within two years.**

### 2.2.1.5 T065 - D06 - 7175 – 5VT VOLTAGE TRANSFORMER

The capacitive voltage transformers (CVTs) are of HAEFELY make, featuring porcelain housing construction, and have been in service for 38 years. Notably, the original porcelain-housed C phase voltage transformer (VT) was replaced with a polymer-housed VT in 2015 and is currently in good condition. Except for the reported oil leak from the A phase gauge since 2022, maintenance records indicate no significant concerns. The oil colour in phases A and B has changed to reddish-brown, indicating potential moisture ingress whereas the oil in phase C remains clear.



Figure 20- C- Voltage Transformer with Clear Oil



Figure 21- A- Voltage Transformer with Dark Oil



Figure 22- B- Voltage Transformer with Dark Oil



**Given the observed condition, it is recommended to replace the A and B phase voltage transformers within the next two years.**

### 2.2.1.6 T065 - D06 - 7175 – 7175SAA SURGE ARRESTORS

The surge arrestors are of Hitachi make, gapless type in porcelain housing and have been in service for 37 years. Apart from corrosion at the steel work at the base of phase A and some rusty bolts require replacement, the arrestors are in reasonable condition. **Considering they**


are in porcelain housing and the need to renew almost all other equipment in this bay, it is recommended to have these replaced. Their potential failure can result in safety risk, damage to the surrounding equipment, causing outages and either supply disruptions or supply to the customer being put on risk.



Figure 23- Corrosion at surge arrestor bolts and steel work

## 2.2.2 Corrective Maintenance Cost

### 2.2.2.1 T065-D06-7175 Bay Maintenance Cost






Figure 24 - H065-D06 Corrective Maintenance Cost

The corrective maintenance costs associated with this bay have exhibited an increasing trend over time. Critical components contributing to these increasing costs include the CVTs (Capacitive Voltage Transformer) and the isolators. Notably, a significant expenditure was incurred in 2015 for the replacement of the C phase voltage transformer. From 2016 onwards, the corrective maintenance costs were predominantly influenced by the bus and line isolators, addressing corrosion and high contact resistance defects.

### 2.2.3 Future Operation Requirements

- Feeder 7175 is sole supply to T105 Oonooie which remains an active Aurizon site.
- Network studies confirm an enduring need for Oonooie substation while the Aurizon connection remains active, consequently there is a need for corrective action.
- Currently, a new project, CP.02320, is being estimated, the objective of this project is to undertake necessary works for Oonooie substation primary plant and secondary systems to extend the life of the substation from 2022 to 2042. Which emphasise the criticality of maintaining the reliability of the feeder bay (T065-D06-7175) as the single supply to the substation.

### 2.2.4 T065-D01-7319- 7139 FEEDER BAY

Since its construction in 1983, this bay has seen several upgrades. In 2008, a new circuit breaker was installed, transforming it into a fully switchable bay. Additionally, the phase A Capacitor Voltage Transformer (CVT) was replaced that same year. In 2022, the gapless surge arrestors were also replaced. These newer pieces of equipment are not included in the scope of the condition assessment.

The original phase B and C voltage transformers, alongside the isolators and earth switches are the original equipment and have been in service for 42 years. Table 3 details the equipment for this bay, including their condition assessment health indices.

**Table 3 – T065-D01-7319 Equipment**

Functional Loc.	Description	Model number	Start-up date	Manufacturer	Equipment	HI
T065-D01-7319-1VTA	CAPACITOR VOLTAGE TRANSFORMER	TEMP138C	23/04/2008	TRENCH LIMITED	20055236	7
T065-D01-7319-1VTB	CAPACITOR VOLTAGE TRANSFORMER	TEMS138	10/02/1983	TRENCH ELECTRIC	20008302	8
T065-D01-7319-1VTC	CAPACITOR VOLTAGE TRANSFORMER	TEMS138	10/02/1983	TRENCH ELECTRIC	20008295	8
T065-D01-7319-73190	EARTH SWITCH	TYPE KL	10/02/1983	BONAR STANGER	20011657	7
T065-D01-7319-73191	ISOLATOR	RDB	10/02/1983	BONAR STANGER	20008265	7
T065-D01-7319-73192	CIRCUIT BREAKER	HS145 ITEM 2GD 6CORE	28/03/2008	GE HITACHI HVB	20058117	5
T065-D01-7319-73193	ISOLATOR	RDB	10/02/1983	BONAR STANGER	20008272	7
T065-D01-7319-7319SAA	SURGE ARRESTOR (GAPLESS)	PEXLIM R120-XH145	01/07/2022	ABB SWITCHGEAR	20132227	3
T065-D01-7319-7319SAB	SURGE ARRESTOR (GAPLESS)	PEXLIM R120-XH145	01/07/2022	ABB SWITCHGEAR	20132228	3
T065-D01-7319-7319SAC	SURGE ARRESTOR (GAPLESS)	PEXLIM R120-XH145	01/07/2022	ABB SWITCHGEAR	20132229	3

#### 2.2.4.1 T065 - D05 - 7319 – 73190 EARTH SWITCH

The Earth switch, manufactured by Bonar Stanger (TYPE KL), was installed in 1983 and has been in continuous operation for 42 years. In 2021, SAP records indicated the development of corrosion, specifically at the threaded linkage, as shown in Figure 24 from the SAP notification. This issue was addressed by replacing the A and C phases pivot arms in 2022 and the C phase in 2023. Currently, the fixed contact supports and guides exhibit G1 corrosion (Figure 25) and are planned to be attended to during the next planned outage in 2027.



Figure 25- Corrosion on 132kV ES 73190 Pivot arm



Figure 26- Corrosion on 132kV ES 73190 fixed contact supports and guides

#### 2.2.4.2 T065 - D01 - 7319 – 73191/3 ISOLATOR(s)

The line and bus isolators are Bonar Stager model RDB and have been in service for 42 years. Maintenance records indicate that the line isolator 73191 has experienced ongoing corrosion issues over an extended period of time. Initial concerns date back to 2013, with multiple observations noting significant rust development on bolts, pivot pins, and contact areas. Over the years, rust severity has varied, with some components requiring immediate replacement while others were monitored for gradual deterioration. In August 2023, rusted bolts and nuts,

were replaced during scheduled outage. Despite these efforts, rust remains a recurring issue, prompting continued monitoring. The next scheduled outage for comprehensive maintenance is planned for February 2027, with provisions to address severe cases beforehand if necessary.





Figure 27- Corrosion on 132kV Isolator 73191

Similarly, the structural nuts, bolts, and pivot pins of the bus isolator 73193 have exhibited persistent corrosion issues over several years, requiring multiple maintenance interventions. Initial reports from 2009 highlighted corrosion on structural bolts and auxiliary switch linkage, with further deterioration noted in subsequent assessments. Various maintenance activities, including bolt replacements and rust treatment, have been performed, notably in 2013, 2019, and most recently in September 2023, when the crew replaced rusted pivot pins. Despite these efforts, periodic inspections continue to identify rust-related concerns, necessitating ongoing monitoring and maintenance planning. The issue has been bundled with other defect notifications to align with future bus outages for efficient rectification.

**Although the various corrosion issues reported in the isolators and earth switch being repairable and/or replaceable components, Feeder F7319 is the only supply for Mackay Ports and Louisa Creek substations which are relatively new and expected to be required for many years. Therefore, it is recommended to replace these isolators and earth switches together with replacement of CVTs, to ensure long-term reliability of the feeder.**

#### 2.2.4.3 T065 - D01 - 7319 – 1VT VOLTAGE TRANSFORMER

The capacitive voltage transformers (CVTs) are manufactured by TRENCH and feature porcelain housing construction. The phase A CVT was replaced in 2008 with a new model featuring a polymer housing, while phases B and C are the original equipment and have been in service for 42 years. These CVTs do not have a sight glass or an oil level indicator to visually inspect the oil level or oil colour.

Powerlink's Trench CVTs have a high failure rate, with only about 60% of the installed equipment still in service. Due to this high failure rate, it is recommended that all three CVTs be replaced within the next two years.

#### 2.2.1 T065-D05-442- 132kV 2 TRANSF BAY (Special Recommendations- Compliance Based)

The pieces of equipment for this bay are detailed in the below Table 4.

**Table 4 – T065-D05-442- Equipment**

Functional Loc.	Description	Model number	Start-up date	Manufacturer	Equipment	HI
T065-D05-442--2SAA	SURGE ARRESTOR (GAPLESS)	3HSRCP120L27E27M3-22	19	BOWTHORPE EMP	20058107	2.00
T065-D05-442--2SAB	SURGE ARRESTOR (GAPLESS)	3HSRCP120L27E27M3-22	19	BOWTHORPE EMP	20058108	2.00
T065-D05-442--2SAC	SURGE ARRESTOR (GAPLESS)	3HSRCP120L27E27M3-22	19	BOWTHORPE EMP	20058109	2.00
T065-D05-442--2TRFCTA	CURRENT TRANSFORMER	TG145	6	ABB	20125528	2.00
T065-D05-442--2TRFCTB	CURRENT TRANSFORMER	TG145	6	ABB	20125529	2.00
T065-D05-442--2TRFCTC	CURRENT TRANSFORMER	TG145	6	ABB	20125530	2.00
T065-D05-442--4420	EARTH SWITCH	KL-R	43	BONAR STANGER	20008264	5.00
T065-D05-442--4422	CIRCUIT BREAKER	LTB145D1/B	19	ABB SWEDEN	20060436	4.00
T065-D05-442--4423	ISOLATOR	RDB	43	BONAR STANGER	20008268	6.00

However, the current transformers in this bay were replaced in 2020. These current transformers, along with the circuit breaker, do not meet the electrical clearances required for 132kV equipment according to Powerlink specifications. **Therefore, they should be replaced. The only way to meet these clearance requirements is to replace the circuit breaker with a dead tank circuit breaker, which will eliminate the need for post-type current transformers. Additionally, the decommissioned equipment should be recovered and maintained as spares.**

### 3. RECOMMENDATION:

#### 3.1 T065 - D06 - 7175 – 7175 FEEDER BAY

F7175 connects Alligator Creek to Oonooie substation, supplying the Aurizon network (CAA extended to 2032 with two provisions for five-year extensions). Due to the critical operational role of F7175 as the sole supply to Oonooie, a comprehensive replacement strategy should be considered for both T065-D06 and the associated equipment at T105-D04.

It is recommended that all critical bay equipment at T065-D06, including the circuit breaker, current transformers, voltage transformers, isolators, earth switch, and surge arrestors at T105-D04 be replaced as part of a comprehensive project. This recommendation is based on observed conditions such as corrosion, oil degradation, and the obsolescence of components, which pose significant reliability risks.

### 3.2 T065-D01-7319- 7139 FEEDER BAY

Replace the CVTs at this T065-D01 to mitigate the consequences of in-service failure and unplanned shutdown on the network.

Despite the various corrosion issues reported in the isolators and earth switch being repairable and/or replaceable components, it is recommended to replace them as this bay is a single source of supply for Mackay Port and Louisa Creek substations. Therefore, it is likely that these will be required longer than their expected estimated remaining service life of 10-15 years.

It is recommended to continue monitoring the condition of the equipment, associated structures, and foundations in this bay for the next 10 years. Regular visual inspections and any necessary maintenance actions should be undertaken to ensure continued reliable operation.

### 3.3 T065-D05-442- 132kV 2 TRANSF BAY

Given the noncompliance with Powerlink specifications for electrical clearances, it is advisable to replace the circuit breakers and current transformers with a dead tank circuit breaker.

## 4. ASSET CONDITION ASSESSMENT OVERVIEW

Table 5 - Recommendations

Asset	Asset Replc. Recom. (Y/N)	Recom. Replc. timing (yrs)	Refurb. Recom. (Y/N)	Corr. Maint. Rec. (Y/N)	Recommendations
T065 - D06 - 7175 – 71752	Y	2	N	Y	Continue essential maintenance, but plan for replacement within 2 years.
T065-D06-71751/3 Isolators	Y	2	N	Y	Continue with essential maintenance until replacement
T065-D06-7175CT	Y	2	N	Y	Monitor closely for potential emergency replacement. The CTs are oil-filled porcelain, increasing the risk of catastrophic failure after 41 years of service. Replacement within 2 years is recommended.
T065-D06-7175 5VT	Y	2	N	Y	Monitor closely for potential emergency replacement. Plan to

Asset	Asset Replc. Recom. (Y/N)	Recom. Replc. timing (yrs)	Refurb. Recom. (Y/N)	Corr. Maint. Rec. (Y/N)	Recommendations
					replace phases A&B within 2 years is recommended.
T065-D06-7175SAA	Y	2	N	Y	Consider replacing the surge arrestors within 2 years, as their failure could impact surrounding equipment. Continue maintenance in the interim.
T065-D06-7175-71750	Y	2	N	Y	Significant corrosion noted on U-bolts and operating arms. Plan for replacement within 2 years while continuing maintenance in the interim.
T065-D01-7319-1VTA	Y	2	N	Y	Continue essential maintenance, but plan for replacement within 2 years.
T065-D01-7319-1VTB	Y	2	N	Y	Continue essential maintenance, but plan for replacement within 2 years.
T065-D01-7319-1VTC	Y	2	N	Y	Continue essential maintenance, but plan for replacement within 2 years.
T065-D01-7319-73190	Y	2	N	Y	Continue monitoring the condition of the equipment, associated structures, and foundations in this bay, but plan their replacement along with CVTs to ensure continued reliable operation for longer than 10-15 years.
T065-D01-7319-73191	Y	2	N	Y	Continue monitoring the condition of the equipment, associated structures, and foundations in this bay, but plan their replacement along with CVTs to ensure continued reliable operation for longer than 10-15 years.

Asset	Asset Replc. Recom. (Y/N)	Recom. Replc. timing (yrs)	Refurb. Recom. (Y/N)	Corr. Maint. Rec. (Y/N)	Recommendations
T065-D01-7319-73193	Y	2	N	Y	Continue monitoring the condition of the equipment, associated structures, and foundations in this bay, but plan their replacement along with CVTs to ensure continued reliable operation for longer than 10-15 years.
T065-D05-442--2TRFCTA	Y	2	N	Y	Continue with routine maintenance as necessary until the circuit breaker is replaced with a Dead Tank Circuit Breaker (DTCB). Decommission, recover and maintain as spare
T065-D05-442--2TRFCTB	Y	2	N	Y	Continue with routine maintenance as necessary until the circuit breaker is replaced with a Dead Tank Circuit Breaker (DTCB). Decommission, recover and maintain as spare
T065-D05-442--2TRFCTC	Y	2	N	Y	Continue with routine maintenance as necessary until the circuit breaker is replaced with a Dead Tank Circuit Breaker (DTCB). Decommission, recover and maintain as spare
T065-D05-442--4422	Y	2	N	Y	Continue with routine maintenance as necessary until the circuit breaker is replaced with a Dead Tank Circuit Breaker (DTCB). Decommission, recover and maintain as spare

## 5. REFERENCE INFORMATION

- Condition Assessment Photos

<K:\SubstationPhotos\Alligator Creek - needs photos\Sub-CA-20240618>


- *Equipment list (SAP)*
- *Notifications, work orders and measurement documents (SAP)*
- *Operating diagram*
- *132, 33, 26.2 & 11 kV bay ratings*
- *Powerlink drawings*

## 6. APPENDIX

### 6.1 Replacement Index Methodology

Replacement index for bays and other substation assets is based on the condition of the equipment in the bay, condition of structures and foundations (all being assigned health index as condition indicator), bay voltage level and type, bay location criticality and bay compliance with legislation and standards. It provides an indication of the remaining life based on its condition and criticality, rather than based on its time in service.

RI	Estimated Remaining Life(yrs)	Action	Comment	Comment
10	1 - 2	condition assessment required on annual basis (or special maintenance regime)	project scoped and approved, included in the current Reset period	<b>Poor condition needs urgent action.</b>
9	2-3	condition assessment required on annual basis (or special maintenance regime)	project scoped and in final approval stages, included in the current Reset period	Poor condition, needs prompt, planned action.
8	3 - 5	condition assessment required on annual basis (or special maintenance regime)	project scoping, options analysis	
7	5 - 10	high level project scoped	high level project scoped for regulator, condition assessment done	
6	10 - 20	condition assessment trigger	Condition assessment to be done within 1 year and ready for next Reset, scope project before next Reset	Deteriorating condition, future replacement required, but in a planned fashion.
5	20 - 25	plan condition assessment in 5 yrs		Aged condition, but satisfactory.
4	25 - 30	mid life condition assessment (desktop)	Desktop assessment of notified issues	Needs some replacements, typically only few, minor components
3	30 - 35	annual review of HI and RI begins	aging - good condition	
2	35-40	good condition, annual review of notifications, dealing with infant mortality issues		
1	≥40	New		



# T065 Alligator Creek 132kV Substation and SVC Secondary Systems Condition Assessment

<b>Date of Site Visit:</b>	30/10/2023		
<b>Authored by:</b>	Senior Digital Asset Strategies Engineer	[REDACTED]	RPEQ:08244
<b>Reviewed by:</b>	Senior Secondary System Strategies Engineer	[REDACTED]	RPEQ:13131
<b>Approved by:</b>	Team Leader SS&TS		

## Version history

Version	Date	Section(s)	Summary of amendment	Author	Approver
1.0	30/05/2024	All	Original Document	[REDACTED]	[REDACTED]

## Table of Contents

<b>1 Purpose .....</b>	<b>3</b>
<b>2 Scope .....</b>	<b>3</b>
<b>3 Condition Assessment Boundary and Methodology .....</b>	<b>3</b>
3.1 <i>Inclusions and Exclusions</i> .....	3
3.1.1 Inclusions.....	3
3.1.2 Exclusions .....	3
3.2 <i>Secondary System Condition Assessment Principles and Methodology</i> .....	4
<b>4 References .....</b>	<b>4</b>
<b>5 Monitoring and Compliance.....</b>	<b>5</b>
<b>6 Condition Assessment .....</b>	<b>5</b>
6.1 <i>Introduction</i> .....	5
6.2 <i>Buildings</i> .....	7
6.3 <i>Outdoor Marshalling Kiosks</i> .....	10
6.3.1 Bay Marshalling Kiosks .....	11
6.3.2 Voltage Transformer Marshalling Kiosks.....	11
6.3.3 Other Marshalling Kiosks .....	12
6.3.4 Control Building Termination Racks .....	12
6.4 <i>Outdoor secondary system multicore cables</i> .....	12
6.5 <i>Indoor Secondary Systems</i> .....	12
6.5.1 Indoor Secondary systems panels and cabling .....	12
6.5.2 Control, Protection, Auxiliary and Ancillary Equipment .....	14
6.6 <i>Revenue Metering Equipment</i> .....	17
6.7 <i>SCADA and Automation</i> .....	18
6.8 <i>Power System Monitoring</i> .....	19
6.8.1 High Speed Monitoring and Power Quality Monitoring.....	19
6.8.2 WAMPAC – Wide Area Monitoring Protection And Control.....	20
6.9 <i>Integrated Operation and Network Service (IONS, former OpsWAN)</i> .....	20
6.10 <i>Auxiliary Supply</i> .....	22
6.10.1 AC Auxiliary Supply .....	22
6.10.2 DC Systems .....	24
<b>7 Foreseeable Primary Plant Replacement Plan .....</b>	<b>25</b>
<b>8 Conclusion.....</b>	<b>25</b>

Current version: 1/08/2022	INTERNAL USE	Page 1 of 27
	<b>HARDCOPY IS UNCONTROLLED</b>	© Powerlink Queensland



9	Appendix A .....	27
10	Distribution List.....	27

Current version: 1/08/2022	INTERNAL USE	Page 2 of 27
	<b>HARDCOPY IS UNCONTROLLED</b>	© Powerlink Queensland

## 1 Purpose

This condition report covers T065 Alligator Creek 132kV substation secondary systems and associated site infrastructure. It is produced to assist with determining the future asset strategies and the scope for refurbishment and replacement work of T065 Alligator Creek secondary system assets.

## 2 Scope

The report is based on the site inspection conducted on 18/04/2023 and with inputs from the following attendees:

Team	Position	Name
Secondary Systems & Telecommunications Strategies	Senior Secondary System Strategies Engineer	[REDACTED]
Secondary Systems & Telecommunications Strategies	Senior Digital Asset Strategies Engineer	[REDACTED]

The report also considers data extracted from SAP, SPF, the Forced Outage Database (FOD) and discussion with maintenance staff. Photographs of items taken during the site visit have been stored in the folder,

[REDACTED]

## 3 Condition Assessment Boundary and Methodology

### 3.1 Inclusions and Exclusions

#### 3.1.1 Inclusions

Secondary systems and associated equipment provide monitoring, supervision, control and protection functions. The condition assessment of the following systems and equipment will be covered in this report.

- Secondary system cables – All cables that are associated with secondary systems and equipment, including:
  - Cables between control and protection panels and termination racks;
  - Cables between termination racks and yard marshalling kiosks, AC and DC kiosks.
- OpsWAN panels, system and equipment;
- Secondary system AC and DC supply – Low voltage (LV) AC Panel heaters and lights, DC batteries and chargers;
- Secondary system panels and associated ancillary parts, including links, terminals, Input / output modules, signal converters, transducers and power supplies;
- Indoor and outdoor secondary systems marshalling kiosks, AC and DC kiosks, termination racks, including internal links, terminals, MCBs and fuses;
- Indoor and outdoor control cables to outdoor secondary systems kiosks or cables from indoor secondary systems panels directly connected to primary equipment control kiosks;
- Secondary system equipment and systems, including protection relays, HMI computers, RTUs, data acquisition units, Programmable Logic Controllers (PLCs), Intelligent Electronic Devices (IED);
- Available space in existing control buildings to accommodate new secondary system panels.
- Telecommunication assets, including 50VDC batteries and chargers.
- OpsWAN cameras.
- AC auxiliary supply systems (> 230/400VAC), including transformers, diesel generators and building power and light circuits;

#### 3.1.2 Exclusions

The condition assessment of the following assets are not in the scope of this report:

Current version: 1/08/2022	INTERNAL USE	Page 3 of 27
	HARDCOPY IS UNCONTROLLED	© Powerlink Queensland

- Condition of control buildings and associated light and power circuits;
- Civil structures, cable trenches and foundations;
- Substation flood lights;
- Primary equipment and associated components e.g. transformer and circuit breaker control cubicles;
- Primary equipment kiosks and associated components, e.g. Power transformer, circuit breaker control kiosks;
- Cables from secondary systems outdoor kiosks (e.g. bay marshalling kiosks) to primary plant control kiosks;
- Cables from primary plant control kiosks to primary plant equipment;

### 3.2 Secondary System Condition Assessment Principles and Methodology

Principles of secondary systems condition assessment were based on Powerlink's Secondary Systems Asset Risk Model and Powerlink – Asset Risk Management – Framework.

The methodology consists of two main parts – Desktop assessment based and a site visual inspection.

The desktop assessment is limited only to assets recorded in SAP asset database, e.g. protection relays, RTUs and IEDs. It is important to note that a significant number of secondary systems equipment, including cables, kiosks, terminals, links, panels, termination racks, auxiliary equipment and some IEDs are not recorded in SAP. The condition assessment of these depends solely on the site visual inspection. Site visual inspection also provides moderation and manual update of desktop assessments to reflect the actual condition of operational equipment at site.

The desktop assessment models the equipment health indices based on the optimisation of risk, cost and performance of Powerlink's secondary assets since 1999. The health index is the key condition measurement for each equipment in service. The model takes into account equipment failure rates calculated based on operational data, environmental conditions where the equipment is installed and the mean physical ages of a group of equipment at bay and system (fleet) levels.

Health indices are modelled in the range from zero (0) to ten (10), where zero represents newly installed equipment and ten indicates equipment that have reached the end of their technical service life. Equipment with a health index close to ten represents only a moderate increased risk of functional failures, but significantly longer outage duration and higher risk of impacting system's availability and reliability.

The key outcome of this report is the recommended replacement timing for secondary systems assets and equipment detailed in the Appendix section based on their health indices and condition assessment data. It also takes into account of the criticality of equipment that are (or are not) directly associated with the performance of secondary systems. For example, OpsWAN equipment with health indices are close to ten may not need to be replaced urgently because their functions are considered to be non-critical to the secondary systems performance and as such may be replaced as the opportunity arises.

---

## 4 References

Document code	Document Details
<a href="#">A3348092</a>	Modelling Substation control and Protection Asset Condition for Optimal reinvestment Decision Based on Risk, Cost and Performance, CIGRE PARIS 26-31 August 2018, T Vu, M. Pelevin, D. Gibbs, J.Horan, C. Zhang
<a href="#">A3348084</a>	Powerlink – Asset Risk Management – Framework, ASM-I&P-FRA-A2417558, Powerlink Queensland, 21/12/2020
<a href="#">A527892</a>	ASM-STD-A527892 Secondary Systems Design Standard, Powerlink Queensland, 10/01/2022
<a href="#">A533375</a>	ASM-STD-A533375 OSD SCADA Requirements for Operational Purposes Standard, Powerlink Queensland, 24/04/2022

Current version: 1/08/2022	INTERNAL USE	Page 4 of 27
	HARDCOPY IS UNCONTROLLED	© Powerlink Queensland



Document code	Document Details
<a href="#">A3372626</a>	ASM-ID&TD-STD-A3372626 SU0049 New Physical Disconnect Terminal for CT Circuits Supersedes SU0031, Powerlink Queensland, 12/06/2020
<a href="#">A3385483</a>	ASM-SPE-A3385483 AM Substation Design Principles – Specification, Powerlink Queensland, 15/07/2021
<a href="#">A4982111</a>	ASM-FRM-A4982111 ETR 10434011 OpsWAN camera lowering device task report.

## 5 Monitoring and Compliance

Compliance with this document is mandatory and will be actively monitored by the Secondary Systems and Telecommunications Strategies Team.

## 6 Condition Assessment

### 6.1 Introduction

T065 132kV Alligator Creek Substation is located approximately 22km south of Mackay and was established in 1982. The switchyard includes a 132kV Powerlink section and a 33kV EnergyQld section. The substation provides supply to the EnergyQld distribution network (directly from the substation, but also at Louisa Creek), and Aurizon (at Oonooie and Mackay Ports substation).

The 132kV connected Powerlink SVC was established in 2009.

Current version: 1/08/2022	INTERNAL USE	Page 5 of 27
	HARDCOPY IS UNCONTROLLED	© Powerlink Queensland



## 132kV Alligator Creek Substation Operational Diagram

T065 Alligator Creek Substation Powerlink owned primary equipment bays are showed in following table.

Table 1 – T065 Alligator Creek Substation Network Elements

Local Substation (T065 Alligator Creek)					Remote Substation
	Voltage (kV)	Quantity	Bay Designation	Operational Element	
Feeders	132	6	=D06	7175	T105 Oonooie (Powerlink)
			=D04	7119	H011 Nebo (Powerlink)
			=D01	7319	Louisa Creek (EnergyQld)
			=D51	7336	QR Mackay Ports (A, C ph only)
			=D54	7152	T141 Pioneer Valley
			=D56	7320	Louisa Creek (EnergyQld)
			=D52	1 CAP	
Cap Bank	132	1			
SVC	132	1	=D02	2 SVC	

Busbars	132	3		1Bus, 2Bus, 3Bus	
Bus Couplers	132	2	=D03, =D53	4112, 4122	

The secondary systems design at T065 Alligator Creek is based on the SDM7 standard modular approach where each protection panel has its own RTU for bay control and alarming. Standard swing frame panels are used, and all CT and VT signals are derived from primary plant and connected to protection/control panels via associated marshalling kiosks.

## 6.2 Buildings

There are two Powerlink buildings at T065 Alligator Creek switching substation. The SVC yard pictured below has its dedicated combined building.



T065 132kV Alligator Creek Substation Aerial View

Current version: 1/08/2022	<b>INTERNAL USE</b>	Page 7 of 27
	<b>HARDCOPY IS UNCONTROLLED</b>	© Powerlink Queensland

- Combined Amenities Building +1 (refer drg. N-408512-001)

This building was commissioned in 1982 and includes a control section with Ergon 33kV panels, Communications Room, Battery Room, Storage facility, Workshop, Amenities Room and toilet. Some parts of the building are air-conditioned: Control Room, Communications Room and a Battery Room. This building includes an AC distribution board.



Combined Amenities and Control building +1


- Control Building +2 (refer drg. -H-132588-001)

The single level demountable control building established in 2008 under CP.01326 includes Powerlink protection and control panels, communications, revenue metering, an AC distribution board and a dual 125V DC System. 50V DC Telecommunications equipment is powered-off 125/50V DC converters. The control building is air-conditioned, free from dust, clean and is located within the substation perimeter fence. The building has been well maintained and is in good condition. There is satisfactory access to all panels. Details of control building +2 are summarised in Table 2.



Control building +2

Current version: 1/08/2022	<b>INTERNAL USE</b>	Page 8 of 27
	<b>HARDCOPY IS UNCONTROLLED</b>	© Powerlink Queensland



T065 Alligator Creek control building +2 equipment layout, refer H-132588-001.

**Table 2 – Alligator Creek Substation Secondary System Building +2**

Building Description	Designation	Functional Use	Spare Sec Sys Panel Spaces
Substation Secondary System & Communications Site Building	+2	Secondary Systems Feeder Bay =D01 panel Secondary Systems Feeder/CB Mgmt Bay =D02 panel (SVC connection) Secondary Systems Feeder Bay =D04 panel Secondary Systems Feeder Bays =D06 panel Secondary Systems Feeder Bays =D51 panel Secondary Systems Feeder Bays =D54 panel Secondary Systems Feeder Bays =D56 panel Secondary Systems Coupler Bay =D03 panel Secondary Systems Coupler Bay =D53 panel Secondary Systems Cap Bank Bay =D52 panel Secondary Systems 2 T Bay =D05 panel Secondary Systems 3 T Bay =D53 panel Secondary Systems 1 BZ panel Secondary Systems 2 BZ panel Secondary Systems 3 BZ panel Power Quality Monitoring panel Station Cubicle - Station SCADA (NSC, LCF), Common RTU Metering panel 1 Metering panel 2 Communications cubicle AC distribution panel 125V DC X&Y System Air Conditioning Units Optical Fiber Junction Box	4 x spare panels: +2A11, +2A12 +2B11, +2B12

Current version: 1/08/2022	INTERNAL USE	Page 9 of 27
	HARDCOPY IS UNCONTROLLED	© Powerlink Queensland

- SVC Building +3

The SVC Building has been commissioned in 2009. It includes an air conditioned room for SVC control and protection panels and DC/AC distribution and a separate non air-conditioned room for the SVC switching equipment (thyristor valves, related equipment, valve cooling system). The building has been well maintained and is in good condition. There is also satisfactory access to all panels.



SVC Building +3

### 6.3 Outdoor Marshalling Kiosks

All substation existing marshalling kiosks were installed following a refurbishment in 2008. The kiosks are in serviceable condition and can be kept in service until 2048.

Some door seals and mesh filters, show signs of degradation and should be replaced as part of substation routine maintenance. Degraded door seals and air filters can lead to premature failures of internal components, e.g. links, terminals, follower relays etc. It is recommended that all outdoor marshalling kiosks be monitored as part of the substation routine inspection to identify any aggressive deterioration. An operational project (or maintenance work order) should be initiated to replace the internal components if they show signs of deterioration beyond Powerlink's safety standards.

Health Indices of secondary system outdoor marshalling kiosks and recommended replacement timeframe have been detailed in Section 9 [Appendix A](#). Physical appearance of typical outdoor marshalling kiosks are illustrated in Section 3.5.1- Section 3.5.5.

Although there is no condition driven replacement required on substation outdoor marshalling kiosks, all associated CT links shall be replaced to mitigate safety risks according to SU0049 New physical disconnect terminal for CT circuits.

In addition, all CT links associated with HV plant interface kiosks (for Pass M0, CBs in general, transformers, etc.) shall to be replaced according to SU0049.

Current version: 1/08/2022	<b>INTERNAL USE</b>	Page 10 of 27
	<b>HARDCOPY IS UNCONTROLLED</b>	© Powerlink Queensland

### 6.3.1 Bay Marshalling Kiosks



+D05-A10 marshallling kiosk (used as an example for similar items on site)

### 6.3.2 Voltage Transformer Marshalling Kiosks



+KD3-A13 marshallling kiosk (8VT, used as an example for similar items on site)

Current version: 1/08/2022	INTERNAL USE	Page 11 of 27
	HARDCOPY IS UNCONTROLLED	© Powerlink Queensland

### 6.3.3 Other Marshalling Kiosks

The Power Quality Monitoring isolation kiosks +KD1-A13A, –A13B and –A13C appear of a lower specification and are affected by corrosion. These kiosks shall be replaced as part of a major secondary system replacement in that bay.



### 6.3.4 Control Building Termination Racks

There are no building termination racks at T065 Alligator Creek substation. Secondary system cables are installed and terminated directly between the indoor panels and outdoor marshalling kiosks.

## 6.4 Outdoor secondary system multicore cables

Visual inspection of outdoor multicore cables indicated that they are in fair condition and could be kept in service until 2048.

## 6.5 Indoor Secondary Systems

Condition assessment of secondary systems, including protection/control panel, equipment, internal components such as links, terminals, wirings, MCBs, fuses, cables is summarized in Appendix A.

### 6.5.1 Indoor Secondary systems panels and cabling

The secondary systems design is based on the standard modular approach where each bay protection panel has its own RTU covering for bay power supplies and control functions (bay AC/DC supplies, CT circuits, controls, indications, alarm). Standard swing frame panels are used, and all VTs and CTs are conventional

Current version: 1/08/2022	INTERNAL USE	Page 12 of 27
	HARDCOPY IS UNCONTROLLED	© Powerlink Queensland

units. The protection/control panels are designed to accommodate 19" rack mounted equipment, with all relay equipment being flush mounted. All inter-panel connections are implemented with multi-core cables.

All panels were installed in 2008 with the refurbishment of T065 Alligator Creek substation. This includes the in-service panels:

- +2A1 - 132kV 1 BZ panel
- +2A2 - 132kV 2 BZ panel
- +2A3 - 132kV 3 BZ panel
- +2A4 - 132kV Bay =D52 Cap Bank panel
- +2A5 - 132kV Bay = D53 1-3 Bus Coupler panel
- +2A6 - 132kV Bay =D54 Feeder 7152 panel
- +2A7 - 132kV Bay =D55 3Transformer panel
- +2A8 - 132kV Bay =D56 Feeder 7320 panel
- +2A9 - 132kV Bay =D51 Feeder 7336 panel
- +2A10 - 132kV Power Quality Monitoring panel
- 
- +2B1 - Station panel
- +2B2 - Communications A panel (including the Mux)
- +2B3 - Metering panel
- +2B4 - 132kV Bay = D3 1-2 Bus Coupler panel
- +2B5 - 132kV Bay =D1 Feeder 7319 panel
- +2B6 - 132kV Bay =D4 Feeder 7119 panel
- +2B7 - 132kV Bay =D5 2Transformer panel
- +2B8 - 132kV Bay =D6 Feeder 7175 panel
- +2B9 - 132kV Bay =D2 SVC CB Management panel
- +2B10 - Metering panel 2

Panels and associated cabling are in good condition, consequently condition based replacement has been recommended by 2048. However, screw CT links and terminals shall be upgraded under associated secondary system replacement to mitigate associated safety risks according to SU0049 New physical disconnect terminal for CT circuits.



Typical swing frame protection/control panel

Current version: 1/08/2022	<b>INTERNAL USE</b>	Page 13 of 27
	<b>HARDCOPY IS UNCONTROLLED</b>	© Powerlink Queensland



AC lighting servicing secondary system panels should be replaced with DC lighting as part of a major secondary system replacement.

## 6.5.2 Control, Protection, Auxiliary and Ancillary Equipment

Health indices and recommended replacement timeframes for substation secondary system equipment and associated ancillary equipment are tabled in Appendix A.

### 6.5.2.1 132kV switchyard related Bay specific Secondary Systems: Feeders, Bus Bars, Power Transformers, Capacitor Bank

The protection, control, auxiliary and ancillary equipment for Feeders 7319, 7320, 7152, 7119, 7175 and 7336, Bus Zones 1, 2 and 3, Transformers 2 and 3 as well as Capacitor Bank C1 are detailed in the table below.

Functional Loc.	Description	Manufacturer	Model number	Start-up date	Obsolescence (Yes / No)	Spare Qty	Material	Eff. Age	HI
T065-SSS-7319-BAYCONT	REMOTE TERMINAL UNIT FOXBORO C50	FOXBORO		23/04/2008	Yes		27350	16	7.43
T065-SSS-7319-XPROT	CURR DIFF RELAY ALSTOM P543 + 2ND PORT	AREVA		23/04/2008	Yes	0	26127	16	7.43
T065-SSS-7319-YPROT	RELAY DISTANCE SEL 311C 1A	SCHWEITZER		23/04/2008	Yes	16	25388	16	7.43
T065-SSS-7320-BAYCONT	REMOTE TERMINAL UNIT FOXBORO C50	FOXBORO		28/03/2008	Yes	8	27350	16	7.46
T065-SSS-7320-XPROT	CURR DIFF RELAY ALSTOM P543 + 2ND PORT	AREVA		28/03/2008	Yes	10	26127	16	7.46
T065-SSS-7320-YPROT	RELAY DISTANCE SEL 311C 1A	SCHWEITZER		28/03/2008	Yes	13	25388	16	7.46
T065-SSS-7152-BAYCONT	REMOTE TERMINAL UNIT FOXBORO C50	FOXBORO		28/03/2008	Yes		27350	16	7.46
T065-SSS-7152-PSBLKA	RFL 9745 PROT SIG VF 2 TONE I/O 48-125v	RFL ELECTRONIC		28/03/2008	Yes	7	25542	16	7.46
T065-SSS-7152-PSBLKB	RFL 9745 PROT SIG VF 2 TONE I/O 48-125v	RFL ELECTRONIC		28/03/2008	Yes	as above	25542	16	7.46
T065-SSS-7152-PSDIT	DEWAR DM1200 PROT SIG VF 90-320V SUPPLY	DEWAR		28/03/2008	Yes	8	17266	16	7.46
T065-SSS-7152-XPROT	RELAY DISTANCE MICOM P442 (WITH R/PORT)	AREVA		28/03/2008	Yes	9	26268	16	7.46
T065-SSS-7152-YPROT	RELAY DISTANCE SEL 311C 1A	SCHWEITZER		13/02/2008	Yes	13	25388	16	8.02
T065-SSS-7119-BAYCONT	REMOTE TERMINAL UNIT FOXBORO C50	FOXBORO		25/08/2008	Yes		27350	16	7.26
T065-SSS-7119-PSBLKA	RFL 9745 PROT SIG VF 2 TONE I/O 48-125v	RFL ELECTRONIC		25/08/2008	Yes	7	25542	16	7.26
T065-SSS-7119-PSBLKB	RFL 9745 PROT SIG VF 2 TONE I/O 48-125v	RFL ELECTRONIC		25/08/2008	Yes	as above	25542	16	7.26
T065-SSS-7119-PSDIT	DEWAR DM1200 PROT SIG VF 90-320V SUPPLY	DEWAR		25/08/2008	Yes	8	17266	16	7.26
T065-SSS-7119-XPROT	RELAY CURR DIFF DISTANCE MICOM P546	SCHNEIDER		21/05/2015	Yes	14	28746	09	5.18
T065-SSS-7119-YPROT	RELAY DISTANCE SEL 311C 1A	SCHWEITZER		25/08/2008	Yes	13	25388	16	7.26
T065-SSS-7175-BAYCONT	REMOTE TERMINAL UNIT FOXBORO C50	FOXBORO		25/08/2008	Yes		27350	16	7.26
T065-SSS-7175-XPROT	RELAY DISTANCE MICOM P442 (WITH R/PORT)	AREVA		25/08/2008	Yes	9	26268	16	7.26
T065-SSS-7175-YPROT	RELAY DISTANCE SEL 311C 1A	SCHWEITZER		25/08/2008	Yes	13	25388	16	7.26
T065-SSS-7336-BAYCONT	REMOTE TERMINAL UNIT FOXBORO C50	FOXBORO		01/09/2009	Yes		27350	15	6.83
T065-SSS-7336-XPROT	RELAY CURR DIFF DISTANCE MICOM P546	AREVA		01/09/2009	Yes	14	28746	15	6.83
T065-SSS-7336-YPROT	RELAY DISTANCE SEL-421 (1A) (5U)	SCHWEITZER		01/09/2009	Yes	5	26126	15	6.83
T065-SSS-1BU4-BAYCONT	REMOTE TERMINAL UNIT FOXBORO C50	FOXBORO		11/04/2008	Yes		27515	16	7.44
*T065-SSS-1BU4-XPROT	RELAY CB FAIL BUS TRIP RACK	RMS		11/04/2008	Yes	22	26578	16	7.44
*T065-SSS-1BU4-XPROT	RELAY DIFF AREVA MFAC34 RANGE: 25-325VAC	AREVA		11/04/2008	Yes	9	13754	16	7.44
*T065-SSS-1BU4-XPROT	RELAY TRIPPING LOW BURDEN ALSTOM MVA13	AREVA		11/04/2008	Yes	11	26689	16	7.44
*T065-SSS-1BU4-XPROT	RELAY TRIPPING SUPPLY FAIL ALSTOM MVA12	AREVA		11/04/2008	Yes	6	26690	16	7.44
*T065-SSS-1BU4-YPROT	RELAY CB FAIL BUS TRIP RACK	RMS		11/04/2008	Yes	22	26578	16	7.44
*T065-SSS-1BU4-YPROT	RELAY DIFF AREVA MFAC34 RANGE: 25-325VAC	AREVA		11/04/2008	Yes	9	13754	16	7.44
*T065-SSS-1BU4-YPROT	RELAY TRIPPING LOW BURDEN ALSTOM MVA13	AREVA		11/04/2008	Yes	11	26689	16	7.44



## T065 Alligator Creek Secondary Systems Condition Assessment Report

Functional Loc.	Description	Manufacturer	Model number	Start-up date	Obsolescence (Yes / No)	Spare Qty	Material	Eff. Age	HI
*T065-SSS-1BU4-YPROT	RELAY TRIPPING SUPPLY FAIL ALSTOM MVAX12	AREVA		11/04/2008	Yes	6	26690	16	7.44
<b>*NOTE</b>	<b>* Bus Zones 2 and 3 panels have identical Secondary Systems devices to Bus Zone 1</b>								
T065-SSS-2TRF-CONTSYS	TRANSF 2 OLTC CONTROL	CONTSYS		01/07/1982	Yes			42	9.5
T065-SSS-442--BAYCONT	REMOTE TERMINAL UNIT FOXBORO C50	FOXBORO		14/11/2008	Yes		27350	16	7.15
T065-SSS-442--XPROT	RELAY POWER SUPPLY MODULE GE UR RH	GE		14/11/2008	Yes			16	9.53
T065-SSS-442--XPROT	RELAY TRANSF DIFF GE T60 (2.93)	GE		14/11/2008	Yes	2	27193	16	7.15
T065-SSS-442--YPROT	RELAY BIASED DIFF SEL-387-5 (1A) (3U)	SCHWEITZER		14/11/2008	Yes	2	25465	16	7.15
T065-SSS-3TRF-CONTSYS	TRANSF 3 OLTC CONTROL	CONTSYS		28/02/2008	Yes			16	7.5
T065-SSS-442--BAYCONT	REMOTE TERMINAL UNIT FOXBORO C50	FOXBORO		28/03/2008	Yes		27350	16	7.46
T065-SSS-443--XPROT	RELAY POWER SUPPLY MODULE GE UR RH	GE		23/05/2008	Yes			16	9.85
T065-SSS-443--XPROT	RELAY TRANSF DIFF GE T60 (2.93)	GE		28/03/2008	Yes	2	27193	16	7.46
T065-SSS-443--YPROT	RELAY BIASED DIFF SEL-387-5 (1A) (3U)	SCHWEITZER		28/03/2008	Yes	2	25465	16	7.46
T065-SSS-482--BAYCONT	REMOTE TERMINAL UNIT FOXBORO C50	FOXBORO		1/07/2009	Yes		27350	15	6.83
T065-SSS-482--XPROT	RELAY CB MGMT GE C60 (VER 2.93 FIRMWARE)	GE		1/07/2009	Yes	8	26931	15	6.83
T065-SSS-482--XPROT	RELAY POWER SUPPLY MODULE GE UR RH	GE		1/07/2009	Yes			15	9.11
T065-SSS-482--YPROT	RELAY CB MGMT SEL-451 1A, 125VDC	SCHWEITZER		1/07/2009	Yes	7	28752	15	6.83
T065-SSS-481--BAYCONT	REMOTE TERMINAL UNIT FOXBORO C50	FOXBORO		11/04/2008	Yes		27350	16	7.44
T065-SSS-481--POWAVE	RELAY POINT ON WAVE ABB E213	ABB		11/04/2008	Yes	1	25640	16	7.44
T065-SSS-481--XPROT	RELAY CAP PROT ABB SPAJ160C	ABB		11/04/2008	Yes		15980	16	7.44
T065-SSS-481--XPROT	RELAY CB MGMT GE C60 (VER 2.93 FIRMWARE)	GE		11/04/2008	Yes	8	26931	16	7.44
T065-SSS-481--XPROT	RELAY OC & EF ABB SPAJ140C	ABB		11/04/2008	Yes	2	12182	16	7.44
T065-SSS-481--XPROT	RELAY POWER SUPPLY MODULE GE UR RH	GE		11/04/2008	Yes			16	9.92
T065-SSS-481--YPROT	RELAY CBMAN SEL-351-1 (1A)	SCHWEITZER		11/04/2008	Yes	8	25466	16	7.44

The majority of secondary systems equipment in the building were commissioned in 2008 and are now obsolete. The health indices show that these assets will reach the end of technical life and require replacement by 2028. Foxboro [REDACTED] range of RTUs are discontinued products and technical support for them has ended.

### 6.5.2.2 SVC related Secondary Systems

The protection, control, auxiliary and ancillary equipment for the SVC are detailed in the table below.

Functional Loc.	Description	Manufacturer	Model number	Start-up date	Obsolescence (Yes / No)	Spare Qty	Material	Eff. Age	HI
T065-SSS-2SVC-3HFXPROT	RELAY CAPACITOR/FILTER TRENCH CPR04	TRENCH		31/07/2009	No	0	29840	14.5	6.79
T065-SSS-2SVC-3HFXPROT	RELAY CAPACITOR/FILTER TRENCH CPR04	TRENCH		31/07/2009	No	0	29840	14.5	6.79
T065-SSS-2SVC-3HFYPROT	RELAY MULTIFUNCTION DIFF SIEMENS 7SJ61	SIEMENS		31/07/2009	Yes	0	31288	14.5	6.79
T065-SSS-2SVC-5HFXPROT	RELAY CAPACITOR/FILTER TRENCH CPR04	TRENCH		31/07/2009	Yes	0	29840	14.5	6.79
T065-SSS-2SVC-5HFYPROT	RELAY MULTIFUNCTION DIFF SIEMENS 7SJ61	SIEMENS		31/07/2009	Yes	0	31288	14.5	6.79
T065-SSS-2SVC-BICOOL	INTERFACE MODULE (SU200:1)	SIEMENS		31/07/2009	Yes	1	31647	14.5	6.79

Current version: 1/08/2022

INTERNAL USE

Page 15 of 27

HARDCOPY IS UNCONTROLLED

© Powerlink Queensland



## T065 Alligator Creek Secondary Systems Condition Assessment Report

Functional Loc.	Description	Manufacturer	Model number	Start-up date	Obsolescence (Yes / No)	Spare Qty	Material	Eff. Age	HI
T065-SSS-2SVC-BICTRLAN	INTERFACE MODULE (SU200:12)	SIEMENS		31/07/2009	Yes	3	31646	14.5	6.79
T065-SSS-2SVC-BICTRLAN	INTERFACE MODULE (SU200:13)	SIEMENS		31/07/2009	Yes	as above	31646	14.5	6.79
T065-SSS-2SVC-BIPROT	INTERFACE MODULE (SU200:3)	SIEMENS		31/07/2009	Yes	as above	31646	14.5	6.79
T065-SSS-2SVC-BIPROT	INTERFACE MODULE (SU200:4)	SIEMENS		31/07/2009	Yes	as above	31646	14.5	6.79
T065-SSS-2SVC-BIPROT	INTERFACE MODULE (SU200:5)	SIEMENS		31/07/2009	Yes	as above	31646	14.5	6.79
T065-SSS-2SVC-BISTN	INTERFACE MODULE (SU200:14)	SIEMENS		31/07/2009	Yes	as above	31646	14.5	6.79
T065-SSS-2SVC-BISYARD	INTERFACE MODULE (SU200:16)	SIEMENS		31/07/2009	Yes	as above	31646	14.5	6.79
T065-SSS-2SVC-BISYARD	INTERFACE MODULE (SU200:17)	SIEMENS		31/07/2009	Yes	as above	31646	14.5	6.79
T065-SSS-2SVC-BISYARD	INTERFACE MODULE (SU200:8)	SIEMENS		31/07/2009	Yes	as above	31646	14.5	6.79
T065-SSS-2SVC-BUSXPROT	RELAY MULTIFUNCTION DIFF SIEMENS 7SJ62	SIEMENS		31/07/2009	Yes	1	31289	14.5	6.79
T065-SSS-2SVC-BUSYPROT	RELAY MULTIFUNCTION DIFF SIEMENS 7SJ62	SIEMENS		31/07/2009	Yes	as above	31289	14.5	6.79
T065-SSS-2SVC-CONTSYS	CLOSED LOOP CONTROL UNIT	SIEMENS		31/07/2009	Yes	0	31543	14.5	8.11
T065-SSS-2SVC-DATCONV	DATA CONVERTER COMPUTER	IPCOMM		31/07/2009	Yes	0	31630	14.5	9.5
T065-SSS-2SVC-DISTREC	TRANSIENT FAULT RECORDER (=X2+SB2-A4)	IBA		31/07/2009	Yes	0	31618	14.5	6.79
T065-SSS-2SVC-DISTREC	TRANSIENT FAULT RECORDER (=X2+SB2-A5)	IBA		31/07/2009	Yes	0	31618	14.5	6.79
T065-SSS-2SVC-DISTREC	TRANSIENT FAULT RECORDER (=X2+SB2-A6)	IBA		31/07/2009	Yes	0	31618	14.5	6.79
T065-SSS-2SVC-EMVI	ELECTRONIC CURRENT TRANSDUCER RECEIVER	RITZ		31/07/2009	Yes	1	31607	14.5	6.79
T065-SSS-2SVC-EMVI	ELECTRONIC CURRENT TRANSDUCER RECEIVER	RITZ		31/07/2009	Yes	as above	31607	14.5	6.79
T065-SSS-2SVC-EMVI	ELECTRONIC CURRENT TRANSDUCER RECEIVER	RITZ		31/07/2009	Yes	as above	31607	14.5	6.79
T065-SSS-2SVC-HMI	HMI COMPUTER	SIEMENS		31/07/2009	Yes	8	29902	14.5	13.58
T065-SSS-2SVC-HMI	MONITOR	FUJITSU SIEMENS		31/07/2009	Yes	1	34314	14.5	6.79
T065-SSS-2SVC-OWCOVERT	DC/DC CONVERTER	PHOENIX		31/07/2009	No	1	27643	14.5	6.79
T065-SSS-2SVC-OWINVERT	INVERTER 125VDC/240VAC 1800W	LATRONICS		31/07/2009	Yes	5	25941	14.5	6.79
T065-SSS-2SVC-OWNTWK	SWITCH (=X1+SB1-A5)	RUGGEDCOM		31/07/2009	Yes	2	29868	14.5	9.5
T065-SSS-2SVC-OWPRINT	PRINTER	HEWLETT PACKARD		31/07/2009	Yes		26840	14.5	6.79
T065-SSS-2SVC-OWPSA	CHECK POINT 1200R IPS RUGGED APPLIANCE	CHECKPOINT		4/03/2019	No		39989	5	2
T065-SSS-2SVC-RTU	REMOTE TERMINAL UNIT FOXBORO C50	FOXBORO		31/07/2009	Yes	17	27353	14.5	6.79
T065-SSS-2SVC-SERVPC	SERVICE COMPUTER	SIEMENS		31/07/2009	Yes	8	29902	14.5	9.6
T065-SSS-2SVC-SVCNTWK	SWITCH (=X1+SB1-A3)	RUGGEDCOM		31/07/2009	Yes	2	29868	14.5	9.6
T065-SSS-2SVC-TCR1VBE	VALVE CONTROL UNIT (VBE)	SIEMENS		31/07/2009	Yes	4	29930	14.5	6.79
T065-SSS-2SVC-TCR1XPRO	RELAY MULTIFUNCTION DIFF SIEMENS 7UT612	SIEMENS		31/07/2009	Yes	0	31290	14.5	6.79
T065-SSS-2SVC-TCR1YPRO	RELAY MULTIFUNCTION DIFF SIEMENS 7SJ61	SIEMENS		31/07/2009	Yes	0	31288	14.5	6.79
T065-SSS-2SVC-TIMING	GPS CLOCK	SIEMENS		31/07/2009	Yes	0	29871	14.5	6.79
T065-SSS-2SVC-TRFXPROT	RELAY MULTIFUNCTION DIFF SIEMENS 7UT635	SIEMENS		31/07/2009	Yes	0	31291	14.5	6.79
T065-SSS-2SVC-TRFYPROT	RELAY MULTIFUNCTION DIFF SIEMENS 7UT635	SIEMENS		31/07/2009	Yes	As above	31291	14.5	6.79
T065-SSS-2SVC-TSC1VBE	VALVE CONTROL UNIT (VBE)	SIEMENS		31/07/2009	Yes	4	29930	14.5	6.79
T065-SSS-2SVC-TSC1XPRO	RELAY CAPACITOR/FILTER TRENCH CPR04	TRENCH		31/07/2009	Yes	0	29840	14.5	6.79
T065-SSS-2SVC-TSC1XPRO	RELAY MULTIFUNCTION DIFF SIEMENS 7UT612	SIEMENS		31/07/2009	Yes	0	31290	14.5	6.79
T065-SSS-2SVC-TSC1YPRO	RELAY MULTIFUNCTION DIFF SIEMENS 7SJ61	SIEMENS		31/07/2009	Yes	0	31288	16	7.26
T065-SSS-2SVC-VCOOLCON	SVC COOLING WATER SYSTEM	GUNTNER		31/07/2009	Yes			16	7.26



## 6.6 Revenue Metering Equipment

There is a total of 6 MNIs allocated: one for each of the following metering points:

- Metering panel 1 (+2B3) catering for Feeders 7319, 7320, 7336 and the SVC bay (this arrangement shall be reviewed during the next Secondary Systems refurbishment). The three feeders' metering is consistent with the TNCP (Transmission Network Connection Point) Connection and Access Agreement between Powerlink Queensland and Energy Queensland.
- Metering panel 2 (+2B10) catering for 2T and 3T with both transformers currently utilising CT and VT signals from the Energy Queensland 33kV side. This shall be reviewed during the next Secondary Systems refurbishment, so that such signals will be from the transformers' HV side.

T065 Alligator Creek Substation metering equipment detailed in the table below was installed in 2008.

Functional Loc.	Description	Manufacturer	Model number	Start-up date	Obsolescence (Yes / No)	Spare Qty	Material	Eff. Age	HI
T065-SSS-METR-2TRFCHK	ENERGY METER (CHECK) +2B10	SCHWEITZER		5/04/2022	No		42268	2	4.23
T065-SSS-METR-2TRFREV	ENERGY METER (REVENUE) +2B10	SCHWEITZER		4/04/2022	No		42268	2	4.23
T065-SSS-METR-3TRFCHK	ENERGY METER (CHECK) +2B10	SCHWEITZER		30/03/2022	No		42268	2	4.23
T065-SSS-METR-3TRFREV	ENERGY METER (REVENUE) +2B10	SCHWEITZER		31/03/2022	No		42268	2	4.23
T065-SSS-METR-REVMETA4	METER KWH/KVARH EDMI	EDMI		27/11/2009	Yes	5	15879	15	6.63
T065-SSS-METR-REVMETA4	METER KWH/KVARH EDMI	EDMI		27/11/2009	Yes	5	15879	15	6.63
T065-SSS-METR-REVMETS5	METER KWH/KVARH EDMI	EDMI		27/11/2009	Yes	5	15879	15	6.63
T065-SSS-METR-REVMETS5	METER KWH/KVARH EDMI 2000-0400 CL 0.5	EDMI		27/11/2009	Yes	5	15879	15	6.63
T065-SSS-METR-REVMET6	KWH/KVARH EDMI 2000-0400 CL 0.5 (CHECK)	EDMI		1/07/2009	Yes	5	15879	15	6.83
T065-SSS-METR-REVMET6	KWH/KVARH EDMI 2000-0400 CL 0.5 (REV)	EDMI		1/07/2009	Yes	5	15879	15	6.83
T065-SSS-METR-REVMET7	KWH/KVARH EDMI 2000-0400 CL 0.5 (REV)	EDMI		31/07/2009	Yes	5	15879	15	6.79
T065-SSS-METR-REVMET7	METER KWH/KVARH EDMI 2000-0400 CL 0.5	EDMI		31/07/2009	Yes	5	15879	15	6.79

The risk of revenue meter failure affecting the transmission network is considered to be moderate. The older EDMi metering equipment in +2B3 (Feeders 7319, 7320, 7336, SVC) can be kept in service until 2028, and are recommended to be replaced as part of the secondary system replacement project by 2028. The newer metering equipment in +2B10 (2T, 3T) can be kept in service until 2042.

Current version: 1/08/2022	INTERNAL USE	Page 17 of 27
	HARDCOPY IS UNCONTROLLED	© Powerlink Queensland



Metering panels +2B3 (left) and +2B10 (right)


## 6.7 SCADA and Automation

The NSC1 and NSC2 are identical C50 RTUs providing the interface between the substation control system and the Network Switching Centre (NSC) at Virginia. The dual RTUs arrangement provide fully redundant communication paths between the substation and NSC. They are used for communicating measurements, indications and alarms from the substation as well as for substation remote control from Virginia. The RTUs communicate to the NSC using DNP3 protocol via serial ports.

This equipment should be replaced as part of the secondary systems replacement project i.e. by 2028.

The HMI interface in each substation building, responsible for local control and monitoring of the secondary system, event connection, and remote access to the HMI system via OpsWAN, should be updated during any project work to show the correct operational state.

Functional Loc.	Description	Manufacturer	Start-up date	Obsolescence (Yes / No)	Spare Qty	Material	Eff. Age	HI
T065-SSS-NBAY-INVERT1	INVERTER 48VDC/240VAC 1800W	LATRONICS	1/07/2009	Yes	2	25938	15	6.83
T065-SSS-NBAY-LCFINT	REMOTE TERMINAL UNIT FOXBORO C50	FOXBORO	27/10/2004	Yes	0	26044	20	9.17
T065-SSS-NBAY-LCFINT2	REMOTE TERMINAL UNIT FOXBORO C50	FOXBORO	28/03/2008	Yes	0	26044	15	7.46
T065-SSS-NBAY-NSCLNK12	REMOTE TERMINAL UNIT FOXBORO C50	FOXBORO	9/09/2004	Yes	0	26044	20	9.24
T065-SSS-NBAY-NSCLNK22	REMOTE TERMINAL UNIT FOXBORO C50	FOXBORO	28/03/2008	Yes	0	26044	16	7.46
T065-SSS-NBAY-OWSERV	MONITOR/KEYBOARD	ICP GLOBAL	1/07/2009	Yes	0	27630	15	6.83
T065-SSS-NBAY-RTUCOM1	REMOTE TERMINAL UNIT FOXBORO C50	FOXBORO	1/07/2009	Yes	1	27352	15	6.83
T065-SSS-NBAY-RTUCOM2	REMOTE TERMINAL UNIT FOXBORO C50	FOXBORO	28/03/2008	Yes	1	27352	16	7.46
T065-SSS-NBAY-RTUNPS	REMOTE TERMINAL UNIT FOXBORO C50 SPECIAL	FOXBORO	27/06/2007	Yes	0		17	7.84


**NSC1/NSC2/LCF and common RTU in building +2**


## 6.8 Power System Monitoring

### 6.8.1 High Speed Monitoring and Power Quality Monitoring

Power Quality Monitoring (PQM) has been installed in building +2 panel +2A10.

Functional Loc.	Description	Manufacturer	Model number	Start-up date	Obsolescence (Yes / No)	Spare Qty	Material	Eff. Age	HI
T065-SSS-NBAY-PWRQUAL1	PQ ANALYSER UNIPOWER T065PQOA	UNIPOWER		5/06/2013	No	0	33423	11	6.71
T065-SSS-NBAY-PWRQUAL2	PQ ANALYSER UNIPOWER T065PQOB	UNIPOWER		27/07/2016	No	3	37441	18	8.3



### 6.8.2 WAMPAC – Wide Area Monitoring Protection And Control

WAMPAC scheme across the network has been utilised to maintain the system stability by shedding load blocks. Load blocks at T065 Alligator Creek would not be potentially required for WAMPAC schemes. As such, no WAMPAC is required at this stage at T065 Alligator Creek substation.

### 6.9 Integrated Operation and Network Service (IONS, former OpsWAN)

IONS, former OpsWAN systems and equipment at this site were installed in 2007 as detailed in a table below.

Functional Loc.	Description	Manufacturer	Model number	Start-up date	Obsolescence (Yes / No)	Spare Qty	Material	Eff. Age	Hi
T065-SSS-IONS-HDWR	AXIS ETHERNET CAMERA ASSEMBLY T065WCOA	Take a Look		1/03/2019	No	14	33869	5	6.52
T065-SSS-IONS-NTWK2	FIREWALL 1	CHECKPOINT		12/08/2020	No	1	39989	4	1.27
T065-SSS-IONS-NTWK2	FIREWALL 2	CHECKPOINT		12/08/2020	No	1	39989	4	1.27
T065-SSS-IONS-NTWK2	METER A ROUTER +2B10	CISCO		7/04/2022	No	4	42182	2	0.45
T065-SSS-IONS-NTWK2	METER A SWITCH +2B10	CISCO		7/04/2022	No	21	40228	2	1.53
T065-SSS-IONS-NTWK2	METER A SWITCH +2B3	CISCO		7/04/2022	No	34	39260	2	0.45
T065-SSS-IONS-NTWK2	METER B ROUTER +2B10	CISCO		7/04/2022	No	4	42182	2	0.45
T065-SSS-IONS-NTWK2	METER B SWITCH +2B10	CISCO		7/04/2022	No	21 (as above)	40228	2	1.53
T065-SSS-IONS-NTWK2	METER B SWITCH +2B3	CISCO		7/04/2022	No	34 (as above)	39260	2	0.45
T065-SSS-NBAY-OWCAM2	AXIS ETHERNET CAMERA ASSEMBLY T065WC0B	Take a Look		10/12/2019	No	14	33869	5	1.61
T065-SSS-NBAY-OWCAM3	AXIS ETHERNET CAMERA ASSEMBLY T065WC0C	Take a Look		28/11/2019	No	As above	33869	5	6.52
T065-SSS-NBAY-OWNTWK1	ROUTER [REDACTED] OPSWAN	CISCO		1/07/2009	Yes	3	27651	15	6.83
T065-SSS-NBAY-OWNTWK1	SWITCH ETHERNET 3 x 8 PORT	ALLOY		1/07/2009	Yes	5	27632	15	6.83
T065-SSS-NBAY-OWNTWK2	SERVER SERIAL PORT	PERLE		28/03/2008	Yes	6	27733	16	7.46
T065-SSS-NBAY-OWNTWK2	SWITCH 8PORT	RUGGEDCOM		28/03/2008	No	16	27400	16	7.46
T065-SSS-NBAY-OWSERV	TERMINAL SERVER	ICP ELECTRONICS		1/07/2009	Yes	5	27636	15	6.38

IONS/OpsWAN systems have an important role in operation and maintenance.

Indoor IONS/OpsWAN systems in buildings +1 and +2 are recommended to be replaced as part of the secondary systems replacement i.e. by 2028.

Current version: 1/08/2022	INTERNAL USE	Page 20 of 27
	HARDCOPY IS UNCONTROLLED	© Powerlink Queensland



OpsWAN Cubicle +1.2.3.3

The three OpsWAN cameras (outdoor OpsWAN equipment), two of which were installed in 2009, shall be replaced under a secondary system refurbishment project by 2028. This shall include relocating all related devices from the OpsWAN camera housing at the top of the pole to the camera patch box at the base of the pole according to the ETR 10434041 OpsWAN Camera Lowering Device Trial – Task Report (Objective ID: A4982111).



OpsWAN camera

Current version: 1/08/2022	INTERNAL USE	Page 21 of 27
	HARDCOPY IS UNCONTROLLED	© Powerlink Queensland

## 6.10 Auxiliary Supply

### 6.10.1 AC Auxiliary Supply

Two 3 x phase 400kVA Station Transformers 132kV/400V installed in 2008 provide the LV AC supplies via a changeover board.

There is no permanent diesel generator, yet the existing changeover board has a connection available for such generator

A stand-alone emergency generator plug-in box (+U-A22, refer H-153095-002) located outside building +1 entrance, allows the connection of a mobile generator to power-up specific critical loads.

This arrangement complies with the current Powerlink substation AC supply specification.



One of the two station transformers shown above

The outdoor main AC changeover board manufactured in 2007 and installed in 2008 is located near building +1. As part of the Secondary Systems refurbishment, this board shall be assessed for compliance with the current AS/NZS 3000 Wiring Rules, current Powerlink design standards and applicable Standard Updates (including Arc Flash risk and labelling). Once compliance assessed, this board would remain in operation until 2048.

Current version: 1/08/2022	<b>INTERNAL USE</b>	Page 22 of 27
	<b>HARDCOPY IS UNCONTROLLED</b>	© Powerlink Queensland



Main AC changeover board +U-A01

The AC distribution board in the building +1 has been installed in 1982 with the building (ref. N\_408505-001). Consideration shall be given to upgrading the board.

The AC distribution board in the demountable building +2 installed in 2008 is in good condition. Similar to the AC change over board, as part of the Secondary Systems refurbishment, this board shall be assessed for compliance with the current AS/NZS 3000 Wiring Rules, current Powerlink design standards and applicable Standard Updates (including Arc Flash risk and labelling). Once compliance assessed, this board would remain in operation until 2048.



Current version: 1/08/2022	<b>INTERNAL USE</b>	Page 23 of 27
	<b>HARDCOPY IS UNCONTROLLED</b>	© Powerlink Queensland

### Building +2 400VAC distribution board +2C10

The AC distribution board in the SVC building +3 installed in 2009 is in good condition. As part of an SVC Secondary Systems refurbishment, this board shall be assessed for compliance with the current AS/NZS 3000 Wiring Rules, current Powerlink design standards and applicable Standard Updates (including Arc Flash risk and labelling). Once compliance assessed, this board would remain in operation until 2049.



SVC Building +3 400VAC distribution board DB-NE2+SN23

#### 6.10.2 DC Systems

T065 Alligator Creek substation includes several DC Systems as described below.

Building +1 single (X) 125V DC rectifier was installed in 2003, it is past its design life and shall be replaced as a matter of priority. Its battery bank installed in January 2013 will approach its end of design life soon and shall be replaced by 2028.

Building +1 dual (A and B) 50V DC system: The A rectifier was installed in 2003, B rectifier in 2008 shall both be replaced by 2028. Its dual A/B battery bank installed in January 2017 shall be replaced by 2031

Building +2 dual (X and Y) 125V DC system rectifiers were installed in 2008 with building +2 and shall be replaced by 2028. Its dual X/Y battery bank installed in January 2017 shall be replaced by 2031.

Note for information only: 50V DC dual supplies in building +2 are provided via 125V DC / 50V DC converters.

Current version: 1/08/2022	<b>INTERNAL USE</b>	Page 24 of 27
	<b>HARDCOPY IS UNCONTROLLED</b>	© Powerlink Queensland



Building +2 125VDC battery banks and chargers

SVC Building +3 dual (X and Y) 125V DC system rectifiers were installed in 2009 with the SVC and shall be replaced by 2029. Its dual X/Y battery bank installed in January 2019 shall be replaced by 2034.

## 7 Foreseeable Primary Plant Replacement Plan

Apart from selective primary plant replacement in bays D05 and D06 (under CP.02800 – yet to be approved in February 2024) there is no foreseeable other primary plant replacement planned at T065 Alligator Creek in the next 10 years.

## 8 Conclusion

This report details the condition of T065 Alligator Creek substation secondary systems and equipment. The primary objective of the optimal replacement timeframe is to ensure the network reliability and availability and to minimise operational and compliance risks associated with secondary systems assets.

Based on the condition assessment, the main recommendations for the replacement of secondary systems equipment at T065 Alligator Creek are:

**Stage 1 - Conduct the following 132kV Switchyard related secondary system replacements by 2028:**

- Implement SU0049 throughout the Secondary Systems at site;
- Replace CT links and terminals of all marshalling cubicles;
- Replace the protection and control equipment and associated CT links/terminals in relation to 132kV Feeders 7319, 7320, 7152, 7119, 7175 and 7336;
- Replace the protection and control equipment and associated CT links/terminals in relation to 132kV Bus Couplers 4112 and 4122
- Replace the protection and control equipment and associated CT links/terminals in relation to 132kV Transformers 2T and 3T
- Replace the protection and control equipment and associated CT links/terminals in relation to 132kV 1CAP
- Replace the protection and control equipment and associated CT links/terminals in relation to 132kV 4822 connection bay to the SVC

Current version: 1/08/2022	<b>INTERNAL USE</b>	Page 25 of 27
	<b>HARDCOPY IS UNCONTROLLED</b>	© Powerlink Queensland



- Replace 132kV revenue metering equipment and associated CT links and terminals according to current standard; On 2T and 3T revenue metering, consider utilising CT/VT sources from the transformers' HV side;
- Replace all C50 RTUs associated with OptoNet ring including NSC1, NSC2, LCF RTU and common RTU;
- Replace the timing system;
- Replace HMI Sun Workstation;
- Upgrade SCADA DNP serial to DNP over TCP/IP;
- Replace all IONS (OpsWAN) equipment and relocate all devices (except the camera) from the OpsWAN camera housing at the top of the pole to the camera patch box at the base of the pole;
- Review and replace CT Links as necessary in the PQM panel
- Change the indoor Secondary Systems panels lighting from AC to DC as per the current Powerlink standard;
- Review the suitability (capacity) of the LV AC supplies;
- Review the AC Supply enclosures and ensure Arc Flash compliance;
- Upgrade the AC board in building +1;
- Consider removing the +1 single 125V DC or transfer it to Energy Queensland to support their secondary systems;
- Replace the +1 dual A/B 50V DC chargers and associated monitoring system
- Replace the +2 dual X/Y 125V DC chargers and associated monitoring system

**Stage 2 – Carry out replacement on the SVC control system by 2029:**

- Implement SU0049 throughout the SVC Secondary Systems at site;
- Replace CT links and terminals of all marshalling kiosks;
- Replace the protection and control equipment and associated CT links/terminals in relation to the SVC, including the TDC and SVC cooling control system;
- Replace the timing system as applicable;
- Replace [REDACTED];
- Upgrade SCADA DNP serial to DNP over TCP/IP;
- Change the indoor Secondary Systems panels lighting from AC to DC as per the current Powerlink standard;
- Review the AC Supply enclosures and ensure Arc Flash compliance;
- Upgrade the SVC AC Changeover System and the AC distribution board in the SVC building +3;
- Replace the +3 dual X/Y 125V DC chargers and monitoring system,

**Stage 3 - Conduct the following replacements by 2031:**

- Replace the 50V DC A and B battery banks in building +1
- Replace the 125V DC X and Y battery banks in building +2

**Stage 4 - Conduct the following SVC System related equipment replacements by 2034:**

- Replace the 125V DC X and Y battery banks in the SVC building +3 by 2034

Current version: 1/08/2022	INTERNAL USE	Page 26 of 27
	HARDCOPY IS UNCONTROLLED	© Powerlink Queensland

---

## 9 Appendix A



T065 Alligator  
Creek v2.0 Appendix

---

## 10 Distribution List

Divisional Distribution	Contact details
Chief Executive	N/A
Delivery and Technical Solutions	Manager Secondary System Design Team Leader Commissioning
Finance and Governance	N/A
Network and Business Development	Manager Asset Strategies
Operations and Service Delivery	Team Leader Secondary System Support
People and Corporate Services	N/A

Current version: 1/08/2022	INTERNAL USE	Page 27 of 27
	HARDCOPY IS UNCONTROLLED	© Powerlink Queensland

Planning Report		30 May 2025
Title	CP.02800 Alligator Creek Substation Reinvestment	
Zone	North	
Need Driver	Emerging critical issues with 132kV bays arising from condition and obsolescence of Alligator Creek's ageing primary and secondary systems.	
Network Limitations and statutory requirements	Alligator Creek Substation is required to meet Powerlink Queensland's N-1-50MW/600MWh Transmission Authority reliability standard.	
Pre-requisites	None	

## Executive Summary

Ageing and obsolete primary and secondary systems at Alligator Creek Substation are increasingly at risk of failing to comply with Schedule 5.1.9(c) of the National Electricity Rules and AEMO's Power System Security Guidelines<sup>1</sup>.

Energy Queensland and Aurizon forecasts confirm there is an enduring need to maintain electricity supply into the Alligator Creek area. The removal or reconfiguration of the Alligator Creek 132/33kV Substation due to secondary system failure or primary plant obsolescence would violate Powerlink's N-1-50MW/600MWh Transmission Authority reliability standard.

The preferred network solution for Powerlink to continue to meet its statutory obligations is the replacement of the at-risk primary plant and secondary systems.

<sup>1</sup> AEMO, Power System Operating Procedure SO\_OP\_3715, Power System Security Guidelines, V95, September 2019 (the Rules require AEMO to develop and publish Power System Operating Procedures pursuant to clause 4.10.1(b) of the Rules, which Powerlink must comply with per clause 4.10.2(b)).

## Table of Contents

Executive Summary .....	1
1. Introduction .....	3
2. Alligator Creek Substation configuration .....	4
3. Alligator Creek Demand Forecast.....	5
4. Statement of Investment Need .....	6
5. Network Risk .....	7
6. Non Network Options .....	9
7. Network Options.....	9
7.1    Proposed Option to address the identified need.....	9
7.2    Option Considered but Not Proposed .....	9
6.2.1    Do Nothing .....	9
8. Recommendations.....	10
9. References.....	11

## 1. Introduction

T065 Alligator Creek substation was established in the early 1980s. It is a 132/33kV bulk supply point for the southern Mackay region providing supply to the Aurizon Oonooie and Mackay Ports connections, the Hay Point and Dalrymple Bay coal loading terminals and surrounding communities via the Ergon Energy network.

Figure 1 shows the geographic location of the Alligator Substation within the North Queensland zone.




Figure 1. Alligator Creek Substation location

Primary plant from the original substation establishment is aged over 40 years and the Condition Assessment [1] indicates emerging critical issues with equipment in the 132kV bays. Similarly, the condition assessment of the secondary systems [2] identified that the protection and control devices for the 132kV bays will reach the end of their technical asset life in 2028.

In addition to the site-specific impacts of obsolescence at Alligator Creek 132kV Substation, it is also important to note the compounding impact of equipment obsolescence occurring across the fleet of secondary systems assets installed in the Powerlink network. Running multiple secondary systems to failure across the network increases the likelihood of concurrent systemic faults with significant implications for network reliability and safety.


This report assesses the impact that removal of the at-risk systems would have on the performance of the network and Powerlink's statutory obligations. It also establishes the indicative requirements of any potential alternative solutions to the current services provided by Alligator Creek Substation.

## 2. Alligator Creek Substation configuration

The Alligator Creek Substation consists of:

1. A 132kV switchyard which provides 2 x 132/33kV transformer bays, 2 x 132kV feeders for Aurizon loads Mackay Ports and Oonooie, and 2 x 132/33kV transformer ended feeders for Ergon, and
2. Two 132/33kV feeders from Pioneer Valley and Nebo Substations.

Figure 2 shows the existing connection configuration of the Alligator Creek Substation and primary plant at-risk.



Primary Plant to be replaced under CP.02800

Figure 2. Alligator Creek 132/33kV Substation Line Diagram

The scope of the at-risk secondary system equipment is outlined in the Project Scope Report [3], but in summary encompasses all feeder, coupler and reactive plant bays together with bus sections.

### 3. Alligator Creek Demand Forecast

Figure 3 shows that the historical and maximum demand forecasts for the loads supplied from the Alligator Creek Substation. The loads are expected to gradually increase in coming years.




Figure 3. Alligator Creek 110kV Maximum Demand

Figure 4 is the duration curve for the loads connected to Alligator Creek 132kV.




Figure 4. Alligator Creek 132kV Load Duration Curve

Powerlink is not aware of any major additional loads proposed or committed in the Southern Mackay area.

#### 4. Statement of Investment Need

The Alligator Creek substation serves as a critical bulk supply point for the southern Mackay region. It provides electricity to the Aurizon Oonooie and Mackay Ports connections, the Hay Point and Dalrymple Bay coal loading terminals, and adjacent communities through the Ergon network. Removing the functionality of this substation would impact the reliability of supply to the loads in the Southern Mackay area.

As shown in Figure 2 there are only 2 x 132/110kV feeder bays supplying power into the Alligator Creek 132kV whilst there are 6 x 132kV feeder/transformer bays supplying power out to Energy Queensland bulk supply points and Aurizon loads. Given only 2 x 132kV sources of power it is not feasible to configure circuits to supply all of the load connections without a 132kV bus.

Therefore, the Alligator creek Substation must retain the 132kV bus. Additionally, removing individual feeder bays would have significant impact on the reliability of supply to Ergon Energy's Mackay area bulk supply points. In all cases load would be at risk for the next credible contingency.

The secondary systems are required to operate the Alligator Creek Substation. Therefore, the secondary systems at Alligator Creek Substation are required to avoid system failures that would result in loss of load in excess of Powerlink's N-1-50MW / 600MWh Transmission Authority reliability standard.

## 5. Network Risk

The table below presents the load at risk as well as the energy at risk for loads connected to the Alligator Creek Substation at 132kV.

Table 1. Network Load at Risk

At Risk	Contingency	Metric	2024/25	2024/25 + PV	2034/35	2034/35 + PV
Alligator Creek, Louisa Creek, Mackay Ports and Oonooie	Outage of 7152 (sec sys) followed by outage of 7119 caused by sec sys or trip	Max (MW)	63.6	101.7	67.3	104.2
		Average (MW)	34.8	46.0	34.7	44.3
	Outage of 7119 (sec sys) followed by outage of 7152 caused by sec sys or trip	24h Energy Unserved Max (MWh)	1270	1596	1448	1637
		24h Energy Unserved Average (MWh)	836	1105	832	1064
Alligator Creek 33kV	Outage of 2T (CB 4422 or sec sys) followed by outage of 3T (sec sys or trip)	Max (MW)	37.7	69.3	32.5	69.2
		Average (MW)	10.8	22.0	10.9	19.1
		24h Energy Unserved Max (MWh)	753	1041	679	880
		24h Energy Unserved Average (MWh)	259	527	261	458
Alligator Creek 132kV (Louisa Creek)	Outage of 7319 (CVT, isolator, sec sys) followed by outage of 7320 (CVT, sec sys or trip)	Max (MW)	41.4	82.7	41.1	73.4
		Average (MW)	19.7	30.9	20.9	30.6
	Outage of 7320 (CVT, sec sys) followed by outage of 7319 (CVT, isolator or trip)	24h Energy Unserved Max (MWh)	854	1196	778	999
		24h Energy Unserved Average (MWh)	473	742	501	734
Mackay Ports (Aurizon)	Outage of 7336 (CVT, sec sys)	Max (MW)	7.0	7.0	6.2	6.2
		Average (MW)	1.7	1.7	1.8	1.8
		24h Energy Unserved Max (MWh)	80	80	81	81
		24h Energy Unserved Average (MWh)	41	41	43	43
Oonooie (Aurizon)	Outage of 7175 (CVT, isolators, CB)	Max (MW)	10.1	10.1	8.1	8.1
		Average (MW)	2.7	2.7	2.6	2.6
		24h Energy Unserved Max (MWh)	129	129	100.4	100.4
		24h Energy Unserved Average (MWh)	65	65	62.7	62.7
1/2 Alligator Creek 33kV and 1/2 Louisa Creek	Outage 4122 <sup>(1)</sup> (sec sys) followed by outage of 3T (sec sys, trip) or outage of 7152 (sec sys, trip)	Max (MW)	19	34	16	34
		Average (MW)	5.4	11	5.4	9.5
	Outage 4122 <sup>(1)</sup> (sec sys) followed by outage of 2T (sec sys, CB, trip) or outage of 7119 (sec sys, trip)	24h Energy Unserved Max (MWh)	377	520	340	440
		24h Energy Unserved Average (MWh)	129	263	130	229

1/2 Alligator Creek 33kV and 1/2 Louisa Creek	Outage 4112 <sup>(1)</sup> (sec sys) followed by outage of 2T (sec sys, CB, trip) or outage of 7119 (sec sys, trip)	Max (MW)	19	34	16	34
	Average (MW)	5.4	11	5.4	9.5	
	24h Energy Unserved Max (MWh)	377	520	340	440	
	24h Energy Unserved Average (MWh)	129	263	130	229	

Note:

- (1) For an outage of either coupler CB 4112 or CB 4122, then the 33kV bus at Alligator Creek and Louisa Creek substations are split

## 6. Non Network Options

The Alligator Creek Substation supplies Ergon Energy and Aurizon loads in the southern Mackay area (Louisa Creek, Alligator Creek 33kV, Mackay Ports and Oonooie).

To meet the Alligator Creek substation demand, the non-network solution must be capable of delivering up to 67MW and 1448MWh per day.

Powerlink is not aware of any Demand Side Solutions (DSM) in the Mackay area supplied from Alligator Creek Substation. However, Powerlink will consider any proposed solution that can contribute significantly to the requirements of ensuring that Powerlink continues to meet its required reliability of supply obligations as part of the formal RIT-T consultation process prior to project approval.

## 7. Network Options

### 7.1 Proposed Option to address the identified need

The recommended option is to replace the at-risk primary and secondary systems reaching end of life at Alligator Creek Substation.

This option ensures that all reliability of supply and asset condition criteria are met as well as maintaining the supply reliability into the Southern Mackay area.

### 7.2 Option Considered but Not Proposed

This section discusses alternative options that Powerlink has investigated but does not consider technically and/or economically feasible to address the above identified issues and thus are not considered credible options.

#### 6.2.1 Do Nothing

“Do Nothing” would not be an acceptable option as the primary driver (secondary systems condition and obsolescence) and associated safety, reliability and compliance risks would not be resolved. Furthermore, the “Do Nothing” option would not be consistent with good industry practice and would result in Powerlink breaching their obligations with the requirements of the System Standards of the National Electricity Rules and its Transmission Authority.

## 8. Recommendations

Powerlink has reviewed the condition of the primary and secondary systems at Alligator Creek Substation.

The preferred network solution for Powerlink to continue to meet its statutory obligations is the replacement of the at-risk primary plant and secondary systems.

Retaining Alligator Creek Substation will allow Powerlink to continue to meet its (N-1- 50MW/600MWh) Transmission Authority reliability standard.

Powerlink is currently unaware of any feasible alternative options to minimise or eliminate the load at risk at Alligator Creek but will, as part of the formal RIT-T consultation process, seek non-network solutions that can contribute to reduced overall investment needs whilst ensuring Powerlink continues to meet its reliability of supply obligations.

## 9. References

1. T065 Alligator Creek Primary Plant Condition Assessment Report – April 2025
2. Alligator Creek Secondary System Condition Assessment Report – May 2024
3. CP.02800 Alligator Creek Substation Reinvestment – Project Scope Report
4. 2025 Transmission Annual Planning Report (A6049612)
5. Asset Planning Criteria - Framework (ASM-FRA-A2352970)
6. Powerlink Queensland's Transmission Authority T01/98



## Project Scope Report

### Network Portfolio

# Project Scope Report

**CP.02800**

## Alligator Creek Substation Reinvestment

Concept – Version 5

### Document Control

#### Change Record

Issue Date	Revision	Prepared by	Reviewed by	Approved by	Background
30 May 2025	5	[REDACTED]		[REDACTED]	Update to include earth switch and isolators in bay D01 PIF reference updated Removed 50V DC system replacement from scope
19 Mar 2025	4	[REDACTED]	[REDACTED]	[REDACTED]	Ver. 4 – added CVT and secondary replacement works
8 Oct 2021	3	[REDACTED]	[REDACTED]	[REDACTED]mith	Ver. 3 - Revert to concept, include additional scope and rebuild options
22 Apr 2021	2	[REDACTED]	[REDACTED]	[REDACTED]	Ver. 2 - Include metering requirement
3 Aug 2020	1	[REDACTED]	[REDACTED]	[REDACTED]	Ver. 1 - Proposal initial issue

### Related Documents

Issue Date	Responsible Person	Objective Document Name
14 March 2025	[REDACTED]	PIF_T065 Alligator Creek Selective Primary Plant Replacement [A5792391]
29 May 2024	[REDACTED]	T065 132kV Alligator Creek Secondary Systems Replacement [A5503733]

## Document Purpose

The purpose of this Project Scope Report is to define the business (functional) requirements that the project is intended to deliver. These functional requirements are subject to Powerlink's design and construction standards and prevailing asset strategies, which will be detailed in documentation produced during the detailed scoping and estimating undertaken by DTS (or OSD), i.e. it is not intended for this document to provide a detailed scope of works that is directly suitable for estimating.

## Project Contacts

Project Sponsor	[REDACTED]
Connection & Development Manager (Aurizon)	[REDACTED]
Connection & Development Manager (Ergon)	[REDACTED]
Strategist – Primary	[REDACTED]
Strategist – Secondary Systems	[REDACTED]
Planner – Main/Regional Grid	[REDACTED]
Manager Projects	[REDACTED]
Project Manager	TBA
Design Manager	TBA

## Project Details

### 1. Project Need & Objective

T065 Alligator Creek substation was established in the early 1980s. It is a 132/33kV bulk supply point for the southern Mackay region providing supply to the Aurizon Oonooie and Mackay Ports connections, the Hay Point and Dalrymple Bay coal loading terminals and surrounding communities via the Ergon network.

Primary plant from the original substation establishment is aged over 40 years and maintenance records indicate emerging critical issues with equipment in the 132kV bays. Instrument transformers from the original installation are in reasonable condition for their age apart from minor oil leaks, however are porcelain-housing type, and based on available statistical data have increased probability of catastrophic failure presenting high safety risk.

Installed capacitive voltage transformers, manufactured by Trench, are known for their high failure rate, leading to unplanned outages and negatively affecting the reliability of the network.

Selected circuit breakers are now operating with reduced reliability due to age related condition issues, including recurring SF6 leaks. Manufacturer support is no longer available and there are limited spares, resulting in increased risk of failure with extended repair duration. A number of disconnectors and earth switches have high contact resistance and corrosion of various parts requiring increased maintenance. There are also potential electrical clearance issues in bay D05, necessitating replacement of the transformer circuit breaker and the current transformers with a Dead Tank Circuit Breaker (DTCB).

A condition assessment of the secondary systems was carried out in 2024 and identified that the protection and control devices for the 132kV bays will reach the end of their technical asset life in 2028.

The objective of this project is to replace selected 132kV primary plant and secondary systems at Alligator Creek substation, including relocation of the metering point to the 132kV side of Transformer 2, by October 2028.

This project will follow the two (2) stage approval process and is subject to a RIT-T.

## 2. Site Overview and Project Drawing





Figure 1: Location of Alligator Creek Substation



*Figure 1: Alligator Creek Existing Line Diagram H-117167-001*



*Figure 2: Alligator Creek Substation Aerial View*

### 3. Deliverables

The following deliverables are to be provided in response to this Project Scope Report. The requirement dates for these deliverables will be communicated separately.

This project will follow the two stage approval process. The following deliverables are to be provided for the purposes of options analysis as required under the RIT-T:

1. Preliminary feasibility assessment for each option, including inputs from design, construction and commissioning.
2. A report (e.g. Concept Estimate Report) detailing the works to be delivered, high level staging, resource requirements and availability, and outage requirements and constraints for each option. This report should include the findings and recommendations from the preliminary feasibility assessment.
3. A class 5 estimate (minimum) for each option.
  - Works associated with the Oonooie feeder bay (D06) are to be estimated as a separable portion.
4. A basis of estimate document and risk table, detailing the key estimating assumptions and delivery risks for each option.
5. Outline staging and outage plans for each option.
6. Provide a high level project schedule for each option and identify any requirements for early funding to meet the commissioning date (e.g. procurement of long lead time equipment).

## 4. Project Scope

### 4.1. Original Scope

The following scope presents a functional overview of the desired outcomes of the project. The proposed solution presented in the estimate must be developed with reference to the remaining sections of this Project Scope Report, in particular *Section 7 Special Considerations*.

Briefly, the project involves replacement of selected 132kV primary plant and secondary systems at Alligator Creek substation, including relocation of the metering point to the 132kV side of Transformer 2.

#### 4.1.1. Options

Two credible options have been identified and are summarised in Table 1 below. Standalone concept estimates are required for each option to inform feasibility and cost assessments.

**Table 1 - Options summary**

Option	Strategy	Project Scope	Comm. Date
1	In situ replacement	<p>In situ replacement of selected primary plant, including relocation of metering point to the 132kV side of Transformer 2.</p> <p>In situ replacement of selected secondary systems within the existing building.</p>	Oct 2028
2	Mix of in situ / full bay replacement	<p>In situ replacement of selected primary plant for bays D56, D51, D1, D5 and 1 Bus VT, including relocation of metering point to the 132kV side of Transformer 2.</p> <p>Full bay replacement in adjacent vacant position for bay D06 (Oonooie feeder bay)</p> <p>In situ replacement of selected secondary systems within the existing building.</p>	Oct 2028

The scope requirements for each of the options are described as follows.

### 4.2. Option 1 - In Situ Replacement

#### 4.2.1. Transmission Line Works

Not applicable

#### 4.2.2. T065 Alligator Creek Substation Works

##### Primary Works

Design, procure, construct and commission the replacement of the selected 132kV primary plant listed in Attachment 1 and shown in Figure 1, with consideration of the following:

- New metering for Transformer 2 is to be installed as close as practicable to the connection point. The connection point is on the high voltage side of the transformers. (Existing metering utilises EQL 33kV CTs and VTs) Refer to Attachment 2.
- For bays requiring both CB and CT replacement, consideration should be given to utilising dead tank circuit breakers to achieve required electrical clearances;
- Point on Wave functionality is required for Transformer 2; and
- Existing structures and foundations are to be reused where possible, ensuring they are fit for purpose for a minimum of 40 years.

##### Secondary Works:

Design, procure, construct and commission in-situ replacement of 132kV secondary systems within the existing control buildings for the following plant:

- 132kV 1, 2 and 3 Buses;
- 132kV Feeders 7320 (D56) & 7319 (D1) to Louisa Creek (EQ) including revenue metering;
- 132kV Feeder 7152 (D54) to Pioneer Valley;
- 132kV Feeder 7119 (D4) to Nebo;
- 132kV Feeder 7175 (D6) to Oonooie;
- 132kV Feeder 7336 (D51) to QR Mackay Ports including revenue metering;
- 132kV M01 Capacitor Bank (D52);
- 132/33kV Transformer 2 (D5) including relocation of metering to transformer HVs (meters do not require replacement until 2042);
- 132/33kV Transformer 3 (D55) (meters do not require replacement until 2042);
- 132kV M02 SVC bay (D2) including revenue metering;
- 132kV Bus Coupler bays (D03 and D53);
- Review PQM panel and replace CT links as necessary;
- SCADA to provide for control and monitoring requirements including conversion from serial to DNP over TCP/IP
- OpsWAN equipment (except the camera) and relocate devices (except the camera) from the OpsWAN camera housing at the top of the pole to the camera patch box at the base of the pole;
- Change indoor secondary systems panels lighting from AC to DC;
- Confirm suitability of the existing AC supplies;

- Replace 125V (building +2) DC Systems (50V DC system is planned for replacement in 2025 under CP.02977);
- Existing single 125V DC system (building +1) is to be decommissioned or transferred to Energy Queensland;
- Modify AC and DC distribution as required to facilitate the replacement works; and
- Modify and upgrade telecommunications equipment as required to support the new secondary systems;

Decommission and recover all redundant equipment, and update drawing records, SAP records, config files, etc. accordingly.

#### 4.2.3. Remote End Substation Works

Modify protection, control, automation and communications systems as required at all impacted remote end substations.

Remote end works at Oonooie to be coordinated with CP.02320 Oonooie Substation Reinvestment if possible.

#### 4.2.4. Telecoms Works

Telecoms works included under Substation Works.

Telecommunications works are to be coordinated with CP.02811 Telecommunication Network Consolidation RAN 2 and CP.02513 OpsWAN and MPLS Replacement RAN 2.

#### 4.2.5. Easement/Land Acquisition & Permits Works

Not applicable

### 4.3. Option 2 – Mix of In Situ and Full Bay Replacement

#### 4.3.1. Transmission Line Works

Design, procure, construct and commission any line works required to facilitate the rebuild of the Oonooie feeder bay (D06) in an adjacent spare bay location.

#### 4.3.2. T065 Alligator Creek Substation Works

As per scope of Option 1, with the exception of the 132kV Oonooie feeder bay (D06) as follows:

- design, procure, construct, test and commission full bay replacement of 132kV switching bay D06 in the adjacent spare bay location.
- New bay to be positioned in such a way that facilitates future expansion of the substation to the south.

#### 4.3.3. Remote End Substation Works

As per Option 1.

#### 4.3.4. Telecoms Works

As per Option 1.

#### 4.3.5. Easement/Land Acquisition & Permits Works

Not applicable

### 4.4. Key Scope Assumptions

- Alligator Creek SVC Secondary Systems will be replaced under a separate project.

#### 4.5. Variations to Scope (post project approval)

Not applicable

### 5. Key Asset Risks

From an asset risk perspective, priority is to be given to replacement of bay D06 due to the porcelain instrument transformers that have increased probability of catastrophic failure presenting a high safety risk.

Asset risk management shall be in accordance with the Asset Risk Management Process Guideline ([A4870713](#)).

### 6. Project Timing

#### 6.1. Project Approval Date

The anticipated date by which the project will be Stage 1 approved is November 2025.

#### 6.2. Site Access Date

Site access is immediately available for Powerlink construction works to commence.

#### 6.3. Commissioning Date

The latest date for the commissioning of the new assets included in this scope and the decommissioning and removal of redundant assets, is 31<sup>st</sup> October 2028.

The project team is to assess the earliest possible delivery date for these works (as close as possible to the proposed commissioning date) as part of the Concept Estimate and provide a schedule of key milestones and funding requirements to meet this date. The project team are to advise the Sponsor as soon as possible if preapproval funding is required to procure long lead time equipment before completion of the estimate to meet the proposed commissioning date.

## 7. Special Considerations

- Preference is to install a separate CT/VT metering unit in the Transformer 2 bay (D05) if there is sufficient space.
- Project works to include recovery and return to Powerlink stores of the SF6 CTs and the CB in bay D05.
- In developing the delivery strategy, consideration should be given to minimising customer impacts including reducing outage duration for cutovers, and minimising return to service requirements.
- Panels, marshalling kiosks and associated cabling are in good condition and consequently, condition-based replacement is not required until 2048. However, screw CT links and terminals shall be upgraded under associated secondary system replacement to mitigate associated safety risks according to SU0049 New physical disconnect terminal for CT circuits.
- In September 2020, the CTs in Bay D05 were replaced with SF6 type under emergency works due to the risk of failure and operational constraints with associated Restricted Access Zones. Project works include recovery of the SF6 CTs and their return to Powerlink stores.

## 8. Asset Management Requirements

Equipment shall be in accordance with Powerlink equipment strategies. The preferred equipment strategy is to utilise dead tank circuit breakers based on lowest lifecycle cost and significantly reduced safety risks.

The preferred equipment strategy for voltage transformers is to use capacitor voltage transformers.

Unless otherwise advised Pat Tighe will be the Project Sponsor for this project. The Project Sponsor must be included in any discussions with any other areas of Network and Business Development.

Craig Bennett will provide the primary customer interface with Aurizon and Jay Tencate for Ergon Energy. The Project Sponsor should be kept informed of any discussions with the customers.

## 9. Asset Ownership

The works detailed in this project will be Powerlink Queensland assets.

## 10. System Operation Issues

Operational issues that should be considered as part of the scope and estimate include:

- Interaction of project outage plan with other outage requirements;
- An outage of the transformers will involve the Township of Alligator Creek (population~1300) and surrounding areas and put load at risk. Load transfers to Mackay will need to be investigated to permit long recall times;

- An outage of feeder 7175 (Bay D06) involves a complete outage of T105 Oonooie which is an Aurizon substation, complete with SVC. Outages will likely be restricted to Aurizon maintenance days and require negotiation with the customer.
- likely impact of project outages upon grid support arrangements; and
- likely impact of project outages upon the optical fibre network.

## 11. Options

An estimate is required for each of the options as described in Section 4 above.

## 12. Division of Responsibilities

A Division of Responsibilities document is required to cover the changes to the interface boundaries with Ergon Energy at Alligator Creek. The Project Manager is required to draft the document and consult with the Project Sponsor to arrange sign-off between Powerlink and Ergon Energy.

## 13. Related Projects


Project No.	Project Description	Planned Comm Date	Comment
Pre-requisite Projects			
CP.02977	DC System Replacement – 2024 and 2025	2025	Project to replace Alligator Creek 50V System
Co-requisite Projects			
CP.02320	Oonooie Substation Reinvestment	2028	Definition
Other Related Projects			
C55.1443	Alligator Creek SVC Sec Sys Refurbishment	TBA	
CP.02812	CP.02812 Telecommunication Network Consolidation RAN 3	2029	
CP.02514	OpsWAN and MPLS Replacement RAN 3	2029	

Attachment 1: Primary Plant to be replaced under CP.02800

Functional Location	Object Type	Manufacturer
T065-D01-7319-1VTA	SUBS0009 [CVT]	TRENCH ELECTRIC
T065-D01-7319-1VTB	SUBS0009 [CVT]	TRENCH ELECTRIC
T065-D01-7319-1VTC	SUBS0009 [CVT]	TRENCH ELECTRIC
T065-D01-7319-73190	SUB_ES	
T065-D01-7319-73191	SUB_IS	
T065-D01-7319-73193	SUB_IS	
T065-D05-442--2TRFCTA	SUBS0015 [CT]	ASEA
T065-D05-442--2TRFCTB	SUBS0015 [CT]	ASEA
T065-D05-442--2TRFCTC	SUBS0015 [CT]	ASEA
T065-D05-4422	SUBS0010 [CIRCUIT BREAKER]	ABB Sweden
T065-D06-7175-5VTA	SUBS0009 [CVT]	HAEFELY
T065-D06-7175-5VTB	SUBS0009 [CVT]	HAEFELY
T065-D06-7175-5VTC	SUBS0009 [CVT]	TRENCH ELECTRIC
T065-D06-7175-71750	SUBS0016 [EARTH SWITCH]	SIEMENS
T065-D06-7175-71751	SUBS0021 [DISCONNECTOR]	SIEMENS
T065-D06-7175-71752	SUBS0010 [CIRCUIT BREAKER]	MITSUBISHI
T065-D06-7175-71753	SUBS0021 [DISCONNECTOR]	SIEMENS
T065-D06-7175-7175CTA	SUBS0015 [CT]	MODERN PRODUCTS
T065-D06-7175-7175CTB	SUBS0015 [CT]	MODERN PRODUCTS
T065-D06-7175-7175CTC	SUBS0015 [CT]	MODERN PRODUCTS
T065-D06-7175-7175SAA	SUBS0031 [SA (GAPLESS)]	Hitachi
T065-D06-7175-7175SAB	SUBS0031 [SA (GAPLESS)]	Hitachi
T065-D06-7175-7175SAC	SUBS0031 [SA (GAPLESS)]	Hitachi
T065-D51-7336-11VTA	SUBS0009 [CVT]	TRENCH ELECTRIC
T065-D51-7336-11VTB	SUBS0009 [CVT]	TRENCH ELECTRIC
T065-D51-7336-11VTC	SUBS0009 [CVT]	TRENCH ELECTRIC
T065-D56-7320-10VTA	SUBS0009 [CVT]	TRENCH ELECTRIC
T065-D56-7320-10VTB	SUBS0009 [CVT]	TRENCH ELECTRIC
T065-D56-7320-10VTC	SUBS0009 [CVT]	TRENCH ELECTRIC
T065-KD--KD1--12VTA	SUBS0009 [CVT]	TRENCH ELECTRIC
T065-KD--KD1--12VTB	SUBS0009 [CVT]	TRENCH ELECTRIC
T065-KD--KD1--12VTC	SUBS0009 [CVT]	TRENCH ELECTRIC

---

Attachment 2: T065 Alligator Creek Customer Connections





# CP.02800 Alligator Creek Substation Reinvestment

## Concept Estimate

Current version: 19/06/2025	INTERNAL USE	Page 1 of 12
Next revision due: 19/06/2025	<b>HARDCOPY IS UNCONTROLLED</b>	© Powerlink Queensland



## Table of Contents

<b>1. Executive Summary .....</b>	<b>3</b>
1.1 <i>Project Estimate</i> .....	3
1.2 <i>Project Financial Year Cash Flows</i> .....	4
<b>2. Project and Site-Specific Information.....</b>	<b>5</b>
2.1 <i>Project Dependencies &amp; Interactions</i> .....	5
2.2 <i>Site Specific Issues</i> .....	5
<b>3. Project Scope.....</b>	<b>6</b>
3.1 <i>Substations Works – T065 Alligator Creek</i> .....	6
3.2 <i>Substation Works - Remote Ends</i> .....	7
3.3 <i>Major Scope Assumptions</i> .....	9
3.4 <i>Scope Exclusions</i> .....	9
<b>4. Project Execution .....</b>	<b>10</b>
4.1 <i>Project Schedule</i> .....	10
4.2 <i>Impacts</i> .....	10
4.3 <i>Resourcing</i> .....	10
<b>5. Project Asset Classification .....</b>	<b>11</b>
<b>6. References.....</b>	<b>12</b>



## 1. Executive Summary

This concept estimate has been developed based on the CP.02800 Alligator Creek Substation Reinvestment Project Scope Report – Version 5. For this project option 2 has been chosen as this is expected to be the preferred option as it significantly reduces the required outage of Aurizon's Oonooie substation and SVC.

T065 Alligator Creek substation was established in the early 1980s. It is a 132/33kV bulk supply point for the southern Mackay region providing supply to the Aurizon Oonooie and Mackay Ports connections, the Hay Point and Dalrymple Bay coal loading terminals and surrounding communities via the Ergon network.

Primary plant from the original substation establishment is aged over 40 years and maintenance records indicate emerging critical issues with equipment in the 132kV bays. Instrument transformers from the original installation are in reasonable condition for their age apart from minor oil leaks, however are porcelain-housing type, and based on available statistical data have increased probability of catastrophic failure presenting high safety risk.

Installed capacitive voltage transformers, manufactured by Trench, are known for their high failure rate, leading to unplanned outages and negatively affecting the reliability of the network.

Selected circuit breakers are now operating with reduced reliability due to age related condition issues, including recurring SF6 leaks. Manufacturer support is no longer available and there are limited spares, resulting in increased risk of failure with extended repair duration. A number of disconnectors and earth switches have high contact resistance and corrosion of various parts requiring increased maintenance. There are also potential electrical clearance issues in bay D05, necessitating replacement of the transformer circuit breaker and the current transformers with a Dead Tank Circuit Breaker (DTCB).

A condition assessment of the secondary systems was carried out in 2024 and identified that the protection and control devices for the 132kV bays will reach the end of their technical asset life in 2028.

The objective of this project is to replace selected 132kV primary plant and secondary systems at Alligator Creek substation, including relocation of the metering point to the 132kV side of Transformer 2.

*The assessment in this proposal has established that the project can be delivered by October 2028.*

The project will follow the two (2) stage approval process.

### 1.1 Project Estimate

No escalation costs have been considered in this estimate.

		Total (\$)
Estimate Class	5	
Base Estimate – Un-Escalated (2025/2026)		26,309,102
<b>TOTAL</b>		<b>26,309,102</b>

Current version: 19/06/2025	INTERNAL USE	Page 3 of 12
Next revision due: 19/06/2025	HARDCOPY IS UNCONTROLLED	© Powerlink Queensland



## 1.2 Project Financial Year Cash Flows

No escalation costs have been considered in this estimate.

DTS Cash Flow Table	Un-Escalated Cost (\$)
To June 2027	1,187,602
To June 2028	5,683,295
To June 2029	14,008,645
To June 2030	5,289,690
To June 2031	139,870
<b>TOTAL</b>	<b>26,309,102</b>

Current version: 19/06/2025	INTERNAL USE	Page 4 of 12
Next revision due: 19/06/2025	HARDCOPY IS UNCONTROLLED	© Powerlink Queensland



## 2. Project and Site-Specific Information

### 2.1 Project Dependencies & Interactions

This project is dependent on the completion delivery of the following projects:

Project No.	Project Description	Planned Commissioning Date	Comment
Dependencies			
CP.02977	DC System Replacement – 2024 and 2025	December 2025	Project to replace Alligator Creek 50V DC System
CP.02929	Sumner Secondary Systems Replacement	September 2026	First project to utilise the in-panel replacement methodology.
Interactions			
CP.02320	Oonooie Substation Reinvestment	2028	Currently in Concept phase
Other Related Projects			
CP.02812	CP.02812 Telecommunication Network Consolidation RAN 3	2029	Currently in Concept phase
CP.02514	OpsWAN and MPLS Replacement RAN 3	2029	Future project

### 2.2 Site Specific Issues

The following site-specific issues are to be resolved:

- T065 Alligator Creek Substation is located at Bruce Highway Alligator Creek (Mackay - Qld), Sarina. It is located 15km south of Mackay just after the Hay Point turnoff, travelling south. The substation is on the west side of the Bruce Highway.
- The substation was established in the early 1980s. It is a 132/33kV bulk supply point for the southern Mackay region providing supply to the Aurizon Oonooie and Mackay Ports connections, the Hay Point and Dalrymple Bay coal loading terminals and surrounding communities via the Ergon network.
- The Mackay area is subject to the following average number of days of rain. Consideration was given to this when developing the project schedule:

Current version: 19/06/2025	INTERNAL USE	Page 5 of 12
Next revision due: 19/06/2025	HARDCOPY IS UNCONTROLLED	© Powerlink Queensland




Figure 1 - Number of Days of Rain >10mm Mackay (Source: Bureau of Meteorology 28th June 2025)

- Asbestos containing material (ACM) has been identified at T065 Alligator Creek Substation in the communications room and presumed to be present in the ceiling of the existing control building. The risk rating is assessed as low. If major refurbishment works are undertaken within the building, care will be taken to prevent ACM exposure.
- From an asset risk perspective, priority is to be given to replacement of bay D06 due to the porcelain instrument transformers that have increased probability of catastrophic failure presenting a high safety risk.

### 3. Project Scope

#### 3.1 Substations Works – T065 Alligator Creek

The project involves replacement of selected 132kV primary plant and secondary systems at Alligator Creek substation.

- Design, procure, construct, test and commission the in-situ replacement of selected primary plant for bays D56, D51, D01, D05 and 1 Bus VT.
- Relocation of the metering point to the 132kV side of Transformer 2.
- Design, procure, construct, test and commission full bay replacement of 132kV Oonooie switching bay D06 in the adjacent spare bay location.
- Design, procure, construct, test and commission the line work to facilitate the switching replacement of 132kV Oonooie D06 to the adjacent spare bay location.
- Design, procure, construct, test and commission selected secondary system replacements in-situ within the existing building for the following plant:
  - 132kV 1, 2 and 3 Buses;
  - 132kV Feeders 7320 (D56) & 7319 (D1) to Louisa Creek (EQ) including revenue metering;
  - 132kV Feeder 7152 (D54) to Pioneer Valley;
  - 132kV Feeder 7119 (D4) to Nebo;

Current version: 19/06/2025	INTERNAL USE	Page 6 of 12
Next revision due: 19/06/2025	<b>HARDCOPY IS UNCONTROLLED</b>	© Powerlink Queensland



- 132kV Feeder 7175 (D6) to Oonooie;
- 132kV Feeder 7336 (D51) to QR Mackay Ports including revenue metering;
- 132kV M01 Capacitor Bank (D52);
- 132/33kV Transformer 2 (D5) including relocation of metering to transformer HVs (meters do not require replacement until 2042);
- 132/33kV Transformer 3 (D55) (meters do not require replacement until 2042);
- 132kV M02 SVC bay (D2) including revenue metering; and
- 132kV Bus Coupler bays (D03 and D53).
- Coordinate modification of protection, control, automation and communications systems for Energy Queensland assets at T065 Alligator Creek (free-issue of secondary systems relays).
- Decommission and recover all redundant equipment.
- Update drawing records, SAP records, config files accordingly.

### 3.2 Substation Works - Remote Ends

Coordinate modification of protection, control, automation and communications systems for:

- Feeder 7119 from H011 Nebo
- Feeder 7152 from T141 Pioneer Valley
- Feeder 7175 from T105 Oonooie
- Feeder 7336 from T192 Mackay Ports
- At the following Energex substations (free-issue of secondary systems relays).
  - T176 Louisa Creek

Current version: 19/06/2025	INTERNAL USE	Page 7 of 12
Next revision due: 19/06/2025	HARDCOPY IS UNCONTROLLED	© Powerlink Queensland



The below Single Line Diagram highlights the equipment to be replaced under this Project Scope Report:




Figure 2 - Alligator Creek Existing Line diagram (H-117167-001)

Current version: 19/06/2025	INTERNAL USE	Page 8 of 12
Next revision due: 19/06/2025	HARDCOPY IS UNCONTROLLED	© Powerlink Queensland

### 3.3 Major Scope Assumptions

The following key assumptions have been made:

- There is insufficient space to install a new CT/VT unit in bay =D05.
- The metering for Transformer 2 will be moved from the LV to the HV side of the transformer via connection to the new dead tank circuit breaker CTs in bay =D05 and new 3 phase bus CVTs to replace the 1 phase CVT.
- The new dead tank circuit breaker in bay =D05 will have CT cores suitable for revenue metering.
- A new revenue metering panel will be included in the existing building.
- A new 132Kv Oonooie Feeder Bay will be constructed in the spare space adjacent to the existing bay =D06 and the feeder will be switched over to the new bay. The existing bay will be retained under this project. The new bay layout, with a view to future expansion, will be addressed in the GA design.
- The existing CVTs in bays =D01, will be replaced in-situ on new foundations and structures.
- Replacement of the secondary systems as outlined in the scope report constitutes a full secondary system replacement within the existing building utilising existing yard cabling which will be re-connected to the new panels. Allowance has been made for assumed necessary new cables.
- 50V DC system will be replaced under CP.02977 DC System Replacement.
- The Alligator Creek SVC Secondary Systems will be replaced under a separate project.
- No Restricted Access Zone will be deployed on this site during construction.
- Outages will be available on request. Please refer to Section 4.2 Network Impacts for further details.
- MSP resources will be available in the timeframes identified in the project schedule.

### 3.4 Scope Exclusions

The following items are excluded from the Project Estimate:

- The existing platform has been constructed on a fill platform of up to 2m height, so rock has not been considered.
- The estimate excludes upgrades to any existing element of the substation not detailed. This includes but not limited to internal building, amenities, roads, lights, fences and gates.
- Excavation, handling, treatment, and disposal of contaminated materials.

Current version: 19/06/2025	INTERNAL USE	Page 9 of 12
Next revision due: 19/06/2025	HARDCOPY IS UNCONTROLLED	© Powerlink Queensland

## 4. Project Execution

### 4.1 Project Schedule

This project will follow the two (2) stage approval process.

A High-Level Project Schedule has been developed for the project stages:

Milestones	High-Level Timing
Class 3 Project Proposal Submission	April 2026
<i>Stage 1 Approval (PAN1)</i> includes funds for design & procurement	June 2026
Long Lead Procurement Orders	June 2026
RIT-T (assumed 26 weeks)	June 2026 – December 2026
Project Development Phase 1 & Phase 2	June 2026 – December 2026
Reconcile Estimate and Submit PMP for Stage 2 Approval	February 2027
<i>Stage 2 Approval (PAN2)</i>	April 2027
SPA Contract Award	April 2027
Site Access Date	August 2027
Procurement Deliveries	September 2027
Construction	September 2027
Project Commissioning	October 2028

### 4.2 Impacts

The following network impact will need to be considered in outage planning:

- F7319 and F7320: Any outage putting T176 Louisa Creek at risk must be negotiated with the customer as disruption to supply may result in significant consequences to customer operations.
- An outage of feeder 7175 (Bay D06) involves a complete outage of T105 Oonooie which is an Aurizon substation, complete with SVC. Outages will likely be restricted to Aurizon maintenance days and require negotiation with the customer.
- Aurizon are extremely sensitive to outages, and therefore it is very important that they are notified of outages per the required timeframes (i.e. 13 months in advance).
- An outage of T2 (Bay D05) will involve the Township of Alligator Creek (population~1300) and surrounding areas and put load at risk. Load transfers to Mackay will need to be investigated to permit long recall times.

### 4.3 Resourcing

Design for the project will be completed by internal design resources. The construction works will be completed by a combination of the Maintenance Service Providers and Substation Panel contractors.

Current version: 19/06/2025	<b>INTERNAL USE</b>	Page 10 of 12
Next revision due: 19/06/2025	<b>HARDCOPY IS UNCONTROLLED</b>	© Powerlink Queensland



## 5. Project Asset Classification

Asset Class	Base (\$)	Base (%)
Substation Primary Plant	6,749,470	25
Substation Secondary Systems	18,341,289	70
Telecommunications	1,218,342	5
Overhead Transmission Line	-	0
<b>TOTAL</b>	<b>26,309,102</b>	<b>100</b>

Current version: 19/06/2025	INTERNAL USE	Page 11 of 12
Next revision due: 19/06/2025	HARDCOPY IS UNCONTROLLED	© Powerlink Queensland



---

## 6. References

Document name and hyperlink (as entered into Objective)	Version	Date
<a href="#">Project Scope Report</a>	5	30/05/2025

Current version: 19/06/2025	INTERNAL USE	Page 12 of 12
Next revision due: 19/06/2025	<b>HARDCOPY IS UNCONTROLLED</b>	© Powerlink Queensland



---

## Risk Cost Summary Report

### CP. 02800

## Alligator Creek Substation Reinvestment

---

### Document Control

#### Change Record

Issue Date	Revision	Prepared by
23/12/2025	1.0	Asset Strategies

#### Related Documents

Issue Date	Responsible Person	Objective Document Name

## Document Purpose

The purpose of this model is to quantify the base case and option risk cost profiles for equipment at the Alligator Creek Substation which are proposed for reinvestment under CP.02800. These risk cost profiles are then included as part of an overall cost-benefit analysis (CBA) to understand the economic benefit of the proposed upgrades. This process provides a benchmarking and internal gate process to support Powerlink in effectively identifying prioritised infrastructure upgrades.

The CBA was designed to demonstrate and quantify the value to be gained through specific infrastructure investments. To evaluate the CBA, an NPV is derived based on the present values of costs and benefits. The flow chart in Figure 4 below designates the methodology used in designing the CBA process.

Primary plant and Secondary systems have been assessed via independent models; however, their overall risk costs have been summed to produce a single analysis for the project.

## Key Assumptions

In calculating the risk cost arising from a failure of the ageing equipment at Alligator Creek Substation, the following modelling assumptions have been made:

### Primary Plant

- The functionality of the equipment is assumed to decay according to decay curves calculated by Powerlink, and associated probability of failure (PoF).
- Where equipment in scope is replaced, its associated Health Index (HI) score is reverted to one. Where refurbishment is undertaken, the health index is adjusted according to the target life extension.
- The likelihood of personnel within the substation in the event of explosive failure of equipment (used to calculate safety risk) is assumed to be 25% (based upon historic site entry averages), with the likelihood of resulting injury or death depending on the explosive radius of the equipment, its housing, and the total substation land area. The modelling also assumes that personnel are equally likely to be anywhere within the substation land area. No escalation to the likelihood has been made during construction as it is assumed appropriate risk assessments and risk mitigation measures are completed by the project team.
- In the event of an SF6 gas leak, it is assumed that the entire quantum of SF6 gas is leaked.
- For the purposes of the cost-benefit analysis, the total useful asset life of 40 years has been applied.
- A site-specific value of customer reliability (VCR) of \$22,110 has been applied when calculating network risks.

### Secondary Systems

- Whilst the re-investment scope of secondary systems contains a range of supporting devices (i.e monitoring equipment, revenue metering, firewalls and human machine interfaces), for simplicity of risk cost modelling only main protection relays, bay controllers and RTUs/control racks were considered.

- Spares for secondary system equipment have been assumed to be available prior to the point of expected spares depletion, which coincides with the expected technical asset life (20 years). After this point the cost and time to return the secondary system back to service increases significantly.
- Given secondary systems have a shorter asset life, risk cost benefits have been modelled out to 2045, whereas substations assets have been modelled to 2060. This is providing a conservative view of the secondary systems benefits.

## Base Case Risk Analysis

### Risk Categories

Four main categories of risk are assessed as part of this project as consistent with Powerlink's Asset Risk Management Framework:

- Financial Risk
- Safety Risk
- Network Risk (including market impact if applicable)
- Environmental

*Table 1: Risk categories*

Risk Category	Failure Types	Equipment in scope
<b>Substations Equipment</b>		
Safety Risk	Explosive failure	All equipment with the potential to fail explosively
Financial Risk	Peaceful failure	All equipment
	Explosive failure	All equipment with the potential to fail explosively
Network Risk	Peaceful failure	All equipment related to network elements identified in the planning statement
Environmental Risk	Peaceful failure	Circuit breakers and current transformers containing SF6
<b>Secondary Systems</b>		
Financial Risk	Failure of the equipment resulting in emergency onsite replacement	All equipment
Network Risk	Failure of equipment resulting in de-energisation of network elements after 24 hours	Main protection relays only

### Base Case Risk Cost

The modelled and extrapolated total base case risk costs are shown in the figures below.

Risk cost associated with the equipment in scope is expected to increase from \$7.31 million in 2026 to \$16.56 million in 2036 and \$32.99 million by 2045. Key highlights of the analysis include:

- Network risk accounts for approximately 89% of the total risk cost in 2030 reflecting its importance as a bulk supply point for load in the Mackay region.
- Financial risk is 10% of the total risk (at 2030), reflecting the cost of replacement of peaceful failures across both the primary and secondary systems assets.
- Safety risk accounts for 1% of the total risk (at 2030), reflecting a conservative assumption that personnel are unlikely to be in proximity of equipment during an explosive failure event.

A dip in risk cost can be observed in 2046 as the benefits associated with secondary systems assets roll off as highlighted in the assumptions listed above.



Figure 1: Total risk cost




Figure 2: Base case risk cost by contributions (2030)

### Option Risk Cost

The figures below set out the total project case risk cost, and associated risk cost savings incremental to the base case.




Figure 3: Project Option Risk Cost (compared to base case)

Following the year of investment (2029) the risk cost associated with the equipment in scope effectively reduces to approximately \$0.16m. By 2045, the risk cost of the project option is approximately \$0.59 million, compared with the base case risk cost of \$32.99 million.

## Cost Benefit Analysis

The methodology designed for this regulatory review is set out below.




Figure 4: CBA methodology

The project is estimated to cost approximately \$26.31 million.

Based on a baseline discount factor of 7%, the project has a net present value (NPV) of \$197.4 million over a 35-year period, and a benefit-cost ratio (BCR) of 10.84.

Table 2: Net Present Value and Benefit-Cost Ratio

		Present Value Table (\$m)		
Discount rate	%	3%	7%	10%
NPV of Net Gain/Loss	\$m	\$455.4	\$197.4	\$113.2
Benefit-Cost Ratio	ratio	20.48	10.84	7.30




Figure 5: Cost benefit summary

## Participation Factors

A sensitivity analysis was undertaken to determine the participation factors for key inputs to the risk cost models (i.e. to identify which inputs are most sensitive to overall risk cost).

The participation factor is defined as the ratio of percentage change in output (i.e. risk cost) to a percentage change in input (e.g. VCR). The participation factors for key model inputs are shown in the table below.

Due to the non-linear nature of the risk cost model (especially network risk costs, which are a function of concurrent failures), the participation factor can change depending on the magnitude of input percentage change.

The model is most sensitive to:

- **changes in value of customer reliability or changes in the restoration time** results in a decrease in risk cost of \$4.98 million (44.6%) and 4.82 (43.1%) million respectively in 2030, when individually halved.

Table 3: Participation Factors

Input	Baseline value	Sensitivity value (-50%)	Change in risk cost at 2030 (\$m)	Participation (%)
<b>Safety</b>				
Likelihood of personnel within substation	25%	12.5%	-0.05	-0.46%
Cost consequence of multiple fatality	\$11,400,000	\$5,700,000	-0.02	-0.14%
Cost consequence of single fatality	\$5,700,000	\$2,850,000	-0.01	-0.13%
Cost consequence of multiple serious injury	\$4,206,600	\$2,103,300	-0.01	-0.10%
<b>Financial</b>				
Emergency premium (peaceful failure)	20%	10%	-0.05	-0.43%
Emergency premium (explosive failure)	300%	150%	-0.03	-0.23%
Emergency replacement cost without spares – Relay (\$m)	0.09	0.05	-0.08	-0.7%
Emergency replacement cost without spares – Bay Controller (\$m)	0.20	0.10	-0.14	-1.3%
<b>Network</b>				
VCR (\$/MWh)	28,580	14,290	-4.98	-44.62%
Restoration Time (hrs)	72-720 (subs) Relay - no spare (10)	36-360 Relay - no spare (5)	-4.82	-43.14%