

Contact Officer: Kurt Stevens
Contact Phone: (02) 6243 1329
Our Ref: 54419

20 May 2015

Mr Vince Graham
Chief Executive Officer
Essential Energy
PO Box 5730
PORT MACQUARIE NSW 2444

Dear Mr Graham

Correcting errors in Essential Energy distribution determination 2015–16 to 2018–19

Through discussions with Essential Energy in early May 2015, we have identified the following errors in the Essential Energy distribution determination 2015–16 to 2018–19 (the distribution determination):

1. inaccurate description of metering in Appendix A to the Overview
2. inaccurate public lighting prices
3. parameter missing for control mechanism

Following those discussions, in which AER and Essential Energy staff agreed the errors should be corrected as soon as practicable, we sent a letter on 13 May 2015 proposing that we revoke and substitute the distribution determination to achieve this outcome.

In response to that letter, there were further discussions between AER and Essential Energy staff during in which Essential Energy's legal advisors raised concerns about the AER's ability under the National Electricity Rules to revoke and substitute the distribution determination and suggested we seek further legal advice.

We have sought further legal advice. As a result of this advice, we have decided not to revoke and substitute the distribution determination at this time.

We still intend to correct the above listed errors in the distribution determination as soon as practicable, in accordance with clause 6.13 of the National Electricity Rules. We anticipate this would occur no earlier than the latter of:

- A. the commencement of the next regulatory control period (1 July 2015); and
- B. once any appeal in relation to our distribution determinations is resolved.

As a result of our decision, the period for making an application for review of our decision does not change.

If you have any queries on this matter please contact Kurt Stevens on (02) 6243 1329.

Yours sincerely

A handwritten signature in black ink, appearing to read 'Paula Conboy', with a stylized flourish at the end.

Paula Conboy
AER Chair

Attachment

Inaccurate description of metering in Appendix A to the Overview

Appendix A of the Overview to our final decision for the distribution determination includes a table of constituent decisions, on which the distribution determination is predicated. The table includes a misdescription. It reads as if the type 5 and 6 unrecovered metering costs are defined as standard control services. However, the AER's reasons in Attachment 13 and Attachment 16 of the final decision make it clear that standard control services do not include the type 5 and 6 unrecovered metering cost. These are classified as part of alternative control services (as part of the type 5 and 6 metering provision).

We propose to correct this error to ensure that the type 5 and 6 unrecovered metering cost is classified as part of alternative control services, in line with our decision. We propose the following correction:

Overview, Appendix A, page 60, lines 7 and 8:

- Delete ", type 5 and 6 unrecovered meter cost."

Overview, Appendix A, page 60, lines 9 and 10:

- Delete "Alternative control services include metering types 5 and 6 provision, maintenance, reading, data services and transfer administration services, ancillary network services and public lighting."
- Insert " Alternative control services include:
 - types 5 and 6 meter provision, maintenance, reading, data services, transfer administration services (including type 5 and 6 unrecovered meter cost)
 - ancillary network services
 - public lighting."

Inaccurate public lighting prices

The Essential Energy public lighting prices in Attachment 16 of the Essential Energy final decision are incorrect. Essential Energy has advised that, in the model it developed and provided to us for the purposes of making the final decision, the starting point (or current tariff) from which net present value smoothing is applied was incorrect. The column within the model that was used to smooth prices contained a theoretical build-up of a tariff without overheads. This is a misapplication by Essential Energy of its model. As a result, Essential Energy's public lighting prices appear to be based upon false or materially misleading information.

We propose to correct this error to ensure that Essential Energy's public lighting prices are accurate, in line with our decision. We propose the following correction:

Attachment 16, page 16-33, lines 3 to 11:

- Delete Table 16.15
- Delete "Final decision prices for each light type are set out in appendix X."
- Insert:

Table 16.15 Total Revenue, \$ millions

	2015—16	2016—17	2017—18	2018—19
Initial Proposal	14.9	15.4	15.9	16.5
Revised Proposal	13.3	13.5	13.7	13.9
Final decision	10.7	12.3	14.2	16.4
change from previous year (percentage)	15	15	15	15

Source: AER analysis.

Final decision prices for each light type are set out in appendix A.2.”

Attachment 16, Appendix A.2, pages 16-79 to 16-113:

- Delete the appendix
- Insert Appendix A.2 to this letter.

Parameter missing for control mechanism

The revenue control formula in figure 14.1 of Attachment 14 of the final decision for Essential Energy, does not include a parameter for distribution use of system under and over recoveries from previous years. As our distribution determination uses a revenue cap, the revenue control formula should include this parameter.

We propose to correct this error so that the revenue control formula includes a parameter for distribution use of system under and over recoveries from previous years, in line with our decision. We propose the following correction:

Attachment 14, page 14-15, Figure 14.1:

- Delete the figure
- Insert:

Figure 14.1 Revenue cap formula

1. $TAR_t \geq \sum_{i=1}^n \sum_{j=1}^m p_t^{ij} q_t^{ij}$ $i=1, \dots, n$ and $j=1, \dots, m$ and $t=1, \dots, 5$
2. $TAR_t = AR_t \pm B_t \pm DUoS_t$
3. $AR_t = AR_{t-1}(1 + \Delta CPI_t)(1 - X_t)(1 + S_t)$

Where:

TAR_t is total annual revenue in year t.

p_t^{ij} is the price of component i of tariff j in year t.

q_t^{ij} is the forecast quantity of component i of tariff j in year t.

AR_t is the annual smoothed expected revenue for year t. For the 2015–16 regulatory year, AR_{t-1} is the annual smoothed expected revenue in the Post Tax Revenue Model for 2014–15.

B_t is:

- the approved pass through amounts (positive or negative) with respect to regulatory year t, as determined by the AER, plus
- the D-factor amounts we approve for 2013–14 (applies to Essential Energy's pricing proposal for the regulatory year 2015–16).

$DUoS_t$ is an annual adjustment factor related to the balance of the DUoS unders and overs account with respect to regulatory year t.

$$\Delta CPI_t = \left[\frac{CPI_{Mar,t-2} + CPI_{Jun,t-2} + CPI_{Sep,t-1} + CPI_{Dec,t-1}}{CPI_{Mar,t-3} + CPI_{Jun,t-3} + CPI_{Sep,t-2} + CPI_{Dec,t-2}} \right] - 1$$

CPI means the all groups index number for the weighted average of eight capital cities as published by the ABS, or if the ABS does not or ceases to publish the index, then CPI will mean an index which the AER considers is the best estimate of the index.

X_t the smoothing factor determined in accordance with the PTRM as approved in the AER's final decision, and annually revised for the return on debt update in accordance with the formula specified in the return on debt appendix I calculated for the relevant year.

S_t is the STPIS factor sum of the raw s-factors for all reliability of supply and customer service parameters (as applicable) to be applied in year t.¹ S_t for 2015–16 and 2016–17 are set at zero.

¹ In the formulas in the STPIS attachment, the AR_{t+1} is equivalent to AR_t in this formula. Calculations of the S factor adjustment are to be made accordingly.

Appendix

A.2 Public Lighting

Table 16.27 Public lighting 2015-16 Prices – Final decision

ANNUAL TARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
				Revised proposal	Final decision
FLU0010-ST-0990-001-B	1	STEEL POLE	1	\$ 151.85	\$ 173.05
FLU0050-ST-0010-001-B	1	SHARED OR NO POLE	1	\$ 62.62	\$ 67.34
FLU0050-ST-0740-001-B	1	SHARED OR NO POLE	2	\$ 69.93	\$ 76.35
FLU0060-ST-0010-001-B	1	SHARED OR NO POLE	1	\$ 64.93	\$ 72.52
FLU0060-ST-0810-001-B	1	WOOD POLE	1	\$ 117.05	\$ 131.87
FLU0060-ST-0990-001-B	1	STEEL POLE	1	\$ 154.25	\$ 178.27
FLU0080-ST-0010-001-B	1	SHARED OR NO POLE	1	\$ 70.26	\$ 83.15
FLU0100-ST-0010-001-B	1	SHARED OR NO POLE	1	\$ 62.48	\$ 67.29
FLU0130-ST-0010-001-B	1	SHARED OR NO POLE	1	\$ 61.14	\$ 65.88
FLU0130-ST-0740-001-B	1	SHARED OR NO POLE	2	\$ 68.45	\$ 74.90
FLU0130-ST-0810-001-B	1	WOOD POLE	1	\$ 113.26	\$ 125.23
FLU0130-ST-0990-001-B	1	STEEL POLE	1	\$ 150.47	\$ 171.63
FLU0130-ST-1000-001-B	1	STEEL POLE	2	\$ 150.95	\$ 178.19
FLU0140-ST-0010-001-B	1	SHARED OR NO POLE	1	\$ 62.45	\$ 69.79
FLU0140-ST-0810-001-B	1	WOOD POLE	1	\$ 114.57	\$ 129.13
FLU0190-ST-0010-001-B	1	SHARED OR NO POLE	1	\$ 67.52	\$ 71.61
FLU0240-ST-0010-001-B	1	SHARED OR NO POLE	1	\$ 66.00	\$ 67.63
FLU0350-ST-1620-001-B	1	SHARED OR NO POLE	1	\$ 81.39	\$ 73.72
HPS0010-ST-0040-001-B	1	SHARED OR NO POLE	1	\$ 89.34	\$ 75.38
HPS0010-ST-0360-001-B	1	STEEL POLE	1	\$ 178.67	\$ 181.13
HPS0010-TA-0090-001-B	1	SHARED OR NO POLE	1	\$ 89.86	\$ 71.13
HPS0010-TA-0140-001-B	1	WOOD POLE	1	\$ 141.98	\$ 130.47
HPS0010-TA-0170-001-B	1	STEEL POLE	1	\$ 179.18	\$ 176.87
HPS0010-TA-1210-001-B	1	WOOD POLE	2	\$ 144.35	\$ 139.93
HPS0020-ST-0040-001-B	1	SHARED OR NO POLE	1	\$ 92.50	\$ 76.43
HPS0020-ST-0350-001-B	1	WOOD POLE	1	\$ 144.63	\$ 135.78
HPS0020-ST-0360-001-B	1	STEEL POLE	1	\$ 181.83	\$ 182.17

ANNUALTARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
HPS0020-ST-0730-001-B	1	STEEL POLE	2	\$ 183.66	\$ 190.40
HPS0020-ST-0750-001-B	1	SHARED OR NO POLE	3	\$ 109.82	\$ 97.79
HPS0020-ST-0890-001-B	1	SHARED OR NO POLE	2	\$ 101.16	\$ 87.11
HPS0020-ST-0910-001-B	1	WOOD POLE	2	\$ 145.81	\$ 143.77
HPS0020-TA-0090-001-B	1	SHARED OR NO POLE	1	\$ 92.02	\$ 75.50
HPS0020-TA-0140-001-B	1	WOOD POLE	1	\$ 144.15	\$ 134.84
HPS0020-TA-0170-001-B	1	STEEL POLE	1	\$ 181.35	\$ 181.23
HPS0070-ST-0040-001-B	1	SHARED OR NO POLE	1	\$ 92.50	\$ 76.43
HPS0090-ST-0050-001-B	1	SHARED OR NO POLE	1	\$ 141.21	\$ 108.54
HPS0090-ST-0220-001-B	1	WOOD POLE	1	\$ 193.33	\$ 167.88
HPS0090-ST-0310-001-B	1	STEEL POLE	1	\$ 220.87	\$ 202.35
HPS0090-ST-0690-001-B	1	STEEL POLE	2	\$ 227.87	\$ 216.95
HPS0090-ST-0710-001-B	1	STEEL POLE	3	\$ 239.42	\$ 233.19
HPS0090-ST-0980-001-B	1	WOOD POLE	2	\$ 199.69	\$ 182.26
HPS0090-ST-1010-001-B	1	SHARED OR NO POLE	2	\$ 155.03	\$ 125.59
HPS0090-ST-1360-001-B	1	R/BOUT COLUMN	3	\$ 305.23	\$ 314.37
HPS0090-TA-0050-001-B	1	SHARED OR NO POLE	1	\$ 132.27	\$ 107.58
HPS0090-TA-0220-001-B	1	WOOD POLE	1	\$ 184.39	\$ 166.93
HPS0090-TA-0310-001-B	1	STEEL POLE	1	\$ 211.93	\$ 201.40
HPS0090-TA-0690-001-B	1	STEEL POLE	2	\$ 218.93	\$ 216.00
HPS0090-TA-1010-001-B	1	SHARED OR NO POLE	2	\$ 146.09	\$ 124.63
HPS0090-TA-1370-001-B	1	R/BOUT COLUMN	4	\$ 308.98	\$ 330.07
HPS0100-ST-0230-001-B	1	WOOD POLE	1	\$ 190.39	\$ 173.47
HPS0100-ST-0430-001-B	1	STEEL POLE	3	\$ 236.76	\$ 239.13
HPS0100-ST-0610-001-B	1	SHARED OR NO POLE	1	\$ 143.84	\$ 120.99
HPS0100-ST-1070-001-B	1	WOOD POLE	1	\$ 195.96	\$ 180.33
HPS0110-ST-0060-001-B	1	SHARED OR NO POLE	1	\$ 142.89	\$ 110.11
HPS0110-ST-0230-001-B	1	WOOD POLE	1	\$ 195.01	\$ 169.46
HPS0110-ST-0320-001-B	1	STEEL POLE	1	\$ 222.55	\$ 203.93
HPS0110-ST-0390-001-B	1	STEEL POLE	2	\$ 229.69	\$ 218.70
HPS0110-ST-0470-001-B	1	STEEL POLE	4	\$ 254.21	\$ 251.94
HPS0110-ST-0550-001-B	1	R/BOUT COLUMN	3	\$ 307.20	\$ 316.30
HPS0110-ST-0590-001-B	1	R/BOUT COLUMN	4	\$ 320.02	\$ 333.11

ANNUALTARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
HPS0110-ST-0610-001-B	1	SHARED OR NO POLE	1	\$ 148.46	\$ 116.98
HPS0110-ST-0760-001-B	1	WOOD POLE	2	\$ 201.51	\$ 184.00
HPS0110-ST-0930-001-B	1	WOOD POLE	3	\$ 212.99	\$ 200.33
HPS0110-ST-0960-001-B	1	SHARED OR NO POLE	2	\$ 156.85	\$ 127.34
HPS0110-ST-1070-001-B	1	WOOD POLE	1	\$ 200.58	\$ 176.32
HPS0110-ST-1120-001-B	1	STEEL POLE	1	\$ 228.12	\$ 210.79
HPS0110-ST-1160-001-B	1	WOOD POLE	2	\$ 212.65	\$ 197.74
HPS0110-ST-1450-001-B	1	R/BOUT COLUMN	4	\$ 342.30	\$ 360.59
HPS0110-TA-0060-001-B	1	SHARED OR NO POLE	1	\$ 132.79	\$ 104.98
HPS0110-TA-0230-001-B	1	WOOD POLE	1	\$ 184.91	\$ 164.32
HPS0110-TA-0320-001-B	1	STEEL POLE	1	\$ 212.45	\$ 198.79
HPS0110-TA-0390-001-B	1	STEEL POLE	2	\$ 219.59	\$ 213.57
HPS0110-TA-0590-001-B	1	R/BOUT COLUMN	4	\$ 309.93	\$ 327.98
HPS0110-TA-0960-001-B	1	SHARED OR NO POLE	2	\$ 146.75	\$ 122.21
HPS0110-TA-1120-001-B	1	STEEL POLE	1	\$ 218.02	\$ 205.66
HPS0110-TA-1450-001-B	1	R/BOUT COLUMN	4	\$ 332.20	\$ 355.46
HPS0140-ST-0070-001-B	1	SHARED OR NO POLE	1	\$ 142.27	\$ 118.29
HPS0140-ST-0330-001-B	1	STEEL POLE	1	\$ 221.93	\$ 212.11
HPS0140-ST-0400-001-B	1	STEEL POLE	2	\$ 233.07	\$ 231.82
HPS0140-ST-1030-001-B	1	SHARED OR NO POLE	2	\$ 160.23	\$ 140.46
HPS0160-ST-0070-001-B	1	SHARED OR NO POLE	1	\$ 150.94	\$ 124.73
HPS0160-ST-0240-001-B	1	WOOD POLE	1	\$ 203.06	\$ 184.08
HPS0160-ST-0330-001-B	1	STEEL POLE	1	\$ 230.60	\$ 218.55
HPS0160-ST-0620-001-B	1	SHARED OR NO POLE	1	\$ 149.48	\$ 122.94
HPS0160-ST-0770-001-B	1	WOOD POLE	2	\$ 213.56	\$ 203.56
HPS0170-ST-0070-001-B	1	SHARED OR NO POLE	1	\$ 151.23	\$ 119.42
HPS0170-ST-0240-001-B	1	WOOD POLE	1	\$ 203.36	\$ 178.76
HPS0170-ST-0330-001-B	1	STEEL POLE	1	\$ 230.89	\$ 213.23
HPS0170-ST-0400-001-B	1	STEEL POLE	2	\$ 242.04	\$ 232.94
HPS0170-ST-0600-001-B	1	R/BOUT COLUMN	4	\$ 340.37	\$ 357.22
HPS0170-ST-0620-001-B	1	SHARED OR NO POLE	1	\$ 149.77	\$ 117.62
HPS0170-ST-0660-001-B	1	SHARED OR NO POLE	2	\$ 166.28	\$ 137.98
HPS0170-ST-0770-001-B	1	WOOD POLE	2	\$ 213.85	\$ 198.24

ANNUALTARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
HPS0170-ST-0900-001-B	1	WOOD POLE	2	\$ 222.28	\$ 208.64
HPS0170-ST-1030-001-B	1	SHARED OR NO POLE	2	\$ 169.20	\$ 141.58
HPS0170-ST-1080-001-B	1	WOOD POLE	1	\$ 192.63	\$ 170.48
HPS0170-ST-1130-001-B	1	STEEL POLE	2	\$ 250.46	\$ 243.34
HPS0170-ST-1170-001-B	1	STEEL POLE	1	\$ 235.11	\$ 218.43
HPS0170-ST-1250-001-B	1	WOOD POLE	3	\$ 241.97	\$ 235.11
HPS0170-TA-0070-001-B	1	SHARED OR NO POLE	1	\$ 145.53	\$ 118.63
HPS0170-TA-0240-001-B	1	WOOD POLE	1	\$ 197.65	\$ 177.97
HPS0170-TA-0330-001-B	1	STEEL POLE	1	\$ 225.19	\$ 212.44
HPS0170-TA-0400-001-B	1	STEEL POLE	2	\$ 236.33	\$ 232.15
HPS0170-TA-0600-001-B	1	R/BOUT COLUMN	4	\$ 334.66	\$ 356.43
HPS0170-TA-1080-001-B	1	WOOD POLE	1	\$ 186.93	\$ 169.69
HPS0180-ST-0860-001-B	1	R/BOUT COLUMN	3	\$ 356.00	\$ 372.35
HPS0180-ST-0870-001-B	1	R/BOUT COLUMN	4	\$ 377.04	\$ 399.30
HPS0180-ST-1490-001-B	1	R/BOUT COLUMN	2	\$ 336.09	\$ 345.81
HPS0250-ST-0120-001-B	1	SHARED OR NO POLE	1	\$ 161.94	\$ 236.85
HPS0250-ST-0840-001-B	1	R/BOUT COLUMN	3	\$ 319.94	\$ 435.25
HPS0250-ST-0850-001-B	1	R/BOUT COLUMN	2	\$ 300.04	\$ 408.70
HPS0250-ST-1050-001-B	1	R/BOUT COLUMN	4	\$ 340.98	\$ 462.20
INC0030-ST-0010-001-B	1	SHARED OR NO POLE	1	\$ 45.91	\$ 82.41
INC0040-ST-0010-001-B	1	SHARED OR NO POLE	1	\$ 45.91	\$ 82.41
INC0050-ST-0010-001-B	1	SHARED OR NO POLE	1	\$ 45.91	\$ 82.41
INC0100-ST-0810-001-B	1	WOOD POLE	1	\$ 95.07	\$ 142.92
INC0100-ST-0990-001-B	1	STEEL POLE	1	\$ 132.27	\$ 189.32
LPS0030-ST-0040-001-B	1	SHARED OR NO POLE	1	\$ 102.00	\$ 90.52
LPS0030-ST-0350-001-B	1	WOOD POLE	1	\$ 154.13	\$ 149.86
LPS0030-ST-0360-001-B	1	STEEL POLE	1	\$ 191.33	\$ 196.26
LPS0030-ST-0890-001-B	1	SHARED OR NO POLE	2	\$ 110.66	\$ 101.20
LPS0040-ST-0050-001-B	1	SHARED OR NO POLE	1	\$ 119.37	\$ 111.42
LPS0040-ST-0220-001-B	1	WOOD POLE	1	\$ 171.50	\$ 170.77
LPS0040-ST-0310-001-B	1	STEEL POLE	1	\$ 199.03	\$ 205.24
LPS0050-ST-0060-001-B	1	SHARED OR NO POLE	1	\$ 122.26	\$ 114.64
LPS0050-ST-0230-001-B	1	WOOD POLE	1	\$ 174.39	\$ 173.99

ANNUALTARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
LPS0050-ST-0320-001-B	1	STEEL POLE	1	\$ 201.92	\$ 208.46
LPS0060-ST-0060-001-B	1	SHARED OR NO POLE	1	\$ 155.60	\$ 129.55
MHR0060-ST-0060-001-B	1	SHARED OR NO POLE	1	\$ 124.41	\$ 121.62
MHR0060-ST-0320-001-B	1	STEEL POLE	1	\$ 204.07	\$ 215.44
MHR0060-ST-0610-001-B	1	SHARED OR NO POLE	1	\$ 129.98	\$ 128.49
MHR0060-ST-1070-001-B	1	WOOD POLE	1	\$ 182.10	\$ 187.83
MHR0060-ST-1120-001-B	1	STEEL POLE	1	\$ 209.64	\$ 222.30
MHR0070-ST-0060-001-B	1	SHARED OR NO POLE	1	\$ 124.74	\$ 124.54
MHR0070-ST-0320-001-B	1	STEEL POLE	1	\$ 204.40	\$ 218.36
MHR0070-ST-0620-001-B	1	SHARED OR NO POLE	1	\$ 127.28	\$ 127.68
MHR0070-ST-1080-001-B	1	WOOD POLE	1	\$ 170.14	\$ 180.54
MHR0070-ST-1130-001-B	1	STEEL POLE	2	\$ 227.97	\$ 253.40
MHR0070-ST-1170-001-B	1	STEEL POLE	1	\$ 212.62	\$ 228.49
MVA0010-ST-0010-001-B	1	SHARED OR NO POLE	1	\$ 69.95	\$ 64.64
MVA0010-ST-0740-001-B	1	SHARED OR NO POLE	2	\$ 77.26	\$ 73.65
MVA0010-ST-0810-001-B	1	WOOD POLE	1	\$ 122.07	\$ 123.98
MVA0010-ST-0990-001-B	1	STEEL POLE	1	\$ 159.28	\$ 170.38
MVA0020-ST-0010-001-B	1	SHARED OR NO POLE	1	\$ 69.95	\$ 64.85
MVA0020-ST-0740-001-B	1	SHARED OR NO POLE	2	\$ 77.26	\$ 73.87
MVA0020-ST-0810-001-B	1	WOOD POLE	1	\$ 122.08	\$ 124.20
MVA0020-ST-0990-001-B	1	STEEL POLE	1	\$ 159.28	\$ 170.59
MVA0020-ST-1000-001-B	1	STEEL POLE	2	\$ 159.77	\$ 177.16
MVA0020-ST-1260-001-B	1	WOOD POLE	2	\$ 121.92	\$ 130.53
MVA0080-ST-0010-001-B	1	SHARED OR NO POLE	1	\$ 67.79	\$ 64.37
MVA0080-ST-0810-001-B	1	WOOD POLE	1	\$ 119.91	\$ 123.72
MVA0080-ST-0820-001-B	1	SHARED OR NO POLE	3	\$ 82.41	\$ 82.41
MVA0080-ST-0990-001-B	1	STEEL POLE	1	\$ 157.12	\$ 170.12
MVA0080-ST-1000-001-B	1	STEEL POLE	2	\$ 157.60	\$ 176.68
MVA0170-ST-0020-001-B	1	SHARED OR NO POLE	1	\$ 95.16	\$ 91.99
MVA0190-ST-0020-001-B	1	SHARED OR NO POLE	1	\$ 98.13	\$ 96.92
MVA0190-ST-0200-001-B	1	WOOD POLE	1	\$ 150.25	\$ 156.26
MVA0190-ST-0290-001-B	1	STEEL POLE	1	\$ 177.79	\$ 190.73
MVA0190-ST-0370-001-B	1	STEEL POLE	2	\$ 185.33	\$ 206.00

ANNUALTARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
MVA0190-ST-0940-001-B	1	SHARED OR NO POLE	2	\$ 112.49	\$ 114.63
MVA0220-ST-0030-001-B	1	SHARED OR NO POLE	1	\$ 110.04	\$ 112.82
MVA0220-ST-0210-001-B	1	WOOD POLE	1	\$ 162.17	\$ 172.17
MVA0220-ST-0300-001-B	1	STEEL POLE	1	\$ 189.71	\$ 206.64
MVA0220-ST-0380-001-B	1	STEEL POLE	2	\$ 197.40	\$ 222.10
MVA0220-ST-0950-001-B	1	SHARED OR NO POLE	2	\$ 124.56	\$ 130.73
MVA0250-ST-0300-001-B	1	STEEL POLE	1	\$ 178.03	\$ 191.86
FLU0010-ST-0010-002-B	2	SHARED OR NO POLE	1	\$ 43.60	\$ 43.96
FLU0010-ST-0990-002-B	2	STEEL POLE	1	\$ 57.25	\$ 56.34
FLU0040-ST-0010-002-B	2	SHARED OR NO POLE	1	\$ 48.27	\$ 45.63
FLU0050-ST-0010-002-B	2	SHARED OR NO POLE	1	\$ 43.70	\$ 43.99
FLU0050-ST-0990-002-B	2	STEEL POLE	1	\$ 57.34	\$ 56.38
FLU0060-ST-0010-002-B	2	SHARED OR NO POLE	1	\$ 46.00	\$ 49.18
FLU0060-ST-0740-002-B	2	SHARED OR NO POLE	2	\$ 46.00	\$ 49.18
FLU0060-ST-0810-002-B	2	WOOD POLE	1	\$ 60.94	\$ 62.65
FLU0060-ST-0830-002-B	2	SHARED OR NO POLE	4	\$ 46.00	\$ 49.18
FLU0060-ST-0990-002-B	2	STEEL POLE	1	\$ 59.65	\$ 61.56
FLU0060-ST-1000-002-B	2	STEEL POLE	2	\$ 52.82	\$ 59.11
FLU0070-ST-0010-002-B	2	SHARED OR NO POLE	1	\$ 48.64	\$ 54.48
FLU0080-ST-0010-002-B	2	SHARED OR NO POLE	1	\$ 51.33	\$ 59.80
FLU0080-ST-0990-002-B	2	STEEL POLE	1	\$ 64.98	\$ 72.19
FLU0100-ST-0010-002-B	2	SHARED OR NO POLE	1	\$ 43.56	\$ 43.94
FLU0100-ST-0990-002-B	2	STEEL POLE	1	\$ 57.20	\$ 56.33
FLU0100-ST-1000-002-B	2	STEEL POLE	2	\$ 50.38	\$ 53.88
FLU0130-ST-0010-002-B	2	SHARED OR NO POLE	1	\$ 42.21	\$ 42.54
FLU0130-ST-0740-002-B	2	SHARED OR NO POLE	2	\$ 42.21	\$ 42.54
FLU0130-ST-0810-002-B	2	WOOD POLE	1	\$ 57.15	\$ 56.02
FLU0130-ST-0990-002-B	2	STEEL POLE	1	\$ 55.86	\$ 54.92
FLU0130-ST-1000-002-B	2	STEEL POLE	2	\$ 49.04	\$ 52.47
FLU0140-ST-0010-002-B	2	SHARED OR NO POLE	1	\$ 43.52	\$ 46.44
FLU0140-ST-0740-002-B	2	SHARED OR NO POLE	2	\$ 43.52	\$ 46.44
FLU0140-ST-0830-002-B	2	SHARED OR NO POLE	4	\$ 43.52	\$ 46.44
FLU0140-ST-0990-002-B	2	STEEL POLE	1	\$ 57.17	\$ 58.83

ANNUALTARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
FLU0140-ST-1260-002-B	2	WOOD POLE	2	\$ 50.99	\$ 57.24
FLU0220-ST-0990-002-B	2	STEEL POLE	1	\$ 60.72	\$ 56.67
FLU0240-ST-0010-002-B	2	SHARED OR NO POLE	1	\$ 47.07	\$ 44.28
FLU0240-ST-0810-002-B	2	WOOD POLE	1	\$ 62.01	\$ 57.76
FLU0240-ST-0990-002-B	2	STEEL POLE	1	\$ 60.72	\$ 56.67
FLU0250-ST-0010-002-B	2	SHARED OR NO POLE	1	\$ 48.47	\$ 48.22
FLU0350-ST-1620-002-B	2	SHARED OR NO POLE	1	\$ 60.31	\$ 47.72
FLU0350-ST-1660-002-B	2	WOOD POLE	1	\$ 75.25	\$ 61.20
FLU0350-ST-1700-002-B	2	STEEL POLE	1	\$ 73.96	\$ 60.10
HPS0010-ST-0040-002-B	2	SHARED OR NO POLE	1	\$ 69.07	\$ 50.38
HPS0010-ST-0350-002-B	2	WOOD POLE	1	\$ 84.01	\$ 63.85
HPS0010-ST-0360-002-B	2	STEEL POLE	1	\$ 82.72	\$ 62.76
HPS0010-ST-0890-002-B	2	SHARED OR NO POLE	2	\$ 69.07	\$ 50.38
HPS0010-ST-0910-002-B	2	WOOD POLE	2	\$ 76.54	\$ 61.17
HPS0010-TA-0090-002-B	2	SHARED OR NO POLE	1	\$ 68.40	\$ 44.66
HPS0010-TA-0140-002-B	2	WOOD POLE	1	\$ 83.34	\$ 58.13
HPS0010-TA-0170-002-B	2	STEEL POLE	1	\$ 82.05	\$ 57.05
HPS0020-ST-0040-002-B	2	SHARED OR NO POLE	1	\$ 72.23	\$ 51.42
HPS0020-ST-0350-002-B	2	WOOD POLE	1	\$ 87.17	\$ 64.90
HPS0020-ST-0360-002-B	2	STEEL POLE	1	\$ 85.87	\$ 63.81
HPS0020-ST-0730-002-B	2	STEEL POLE	2	\$ 79.05	\$ 61.36
HPS0020-ST-0750-002-B	2	SHARED OR NO POLE	3	\$ 72.23	\$ 51.42
HPS0020-ST-0880-002-B	2	STEEL POLE	4	\$ 75.64	\$ 60.14
HPS0020-ST-0890-002-B	2	SHARED OR NO POLE	2	\$ 72.23	\$ 51.42
HPS0020-ST-0910-002-B	2	WOOD POLE	2	\$ 79.70	\$ 62.22
HPS0020-TA-0090-002-B	2	SHARED OR NO POLE	1	\$ 70.56	\$ 49.03
HPS0020-TA-0140-002-B	2	WOOD POLE	1	\$ 85.50	\$ 62.50
HPS0020-TA-0170-002-B	2	STEEL POLE	1	\$ 84.21	\$ 61.41
HPS0070-ST-0040-002-B	2	SHARED OR NO POLE	1	\$ 72.23	\$ 51.42
HPS0070-ST-0350-002-B	2	WOOD POLE	1	\$ 87.17	\$ 64.90
HPS0070-ST-0360-002-B	2	STEEL POLE	1	\$ 85.87	\$ 63.81
HPS0080-ST-0050-002-B	2	SHARED OR NO POLE	1	\$ 72.40	\$ 55.02
HPS0080-ST-0310-002-B	2	STEEL POLE	1	\$ 86.04	\$ 67.41

ANNUALTARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
HPS0090-ST-0050-002-B	2	SHARED OR NO POLE	1	\$ 106.10	\$ 65.23
HPS0090-ST-0220-002-B	2	WOOD POLE	1	\$ 121.04	\$ 78.71
HPS0090-ST-0310-002-B	2	STEEL POLE	1	\$ 119.75	\$ 77.62
HPS0090-ST-0690-002-B	2	STEEL POLE	2	\$ 112.92	\$ 75.17
HPS0090-ST-0710-002-B	2	STEEL POLE	3	\$ 110.65	\$ 74.35
HPS0090-ST-0720-002-B	2	STEEL POLE	4	\$ 109.51	\$ 73.94
HPS0090-ST-0980-002-B	2	WOOD POLE	2	\$ 113.57	\$ 76.02
HPS0090-ST-1010-002-B	2	SHARED OR NO POLE	2	\$ 106.10	\$ 65.23
HPS0090-ST-1360-002-B	2	R/BOUT COLUMN	3	\$ 110.65	\$ 74.35
HPS0090-ST-1370-002-B	2	R/BOUT COLUMN	4	\$ 109.51	\$ 73.94
HPS0090-TA-0050-002-B	2	SHARED OR NO POLE	1	\$ 97.16	\$ 64.27
HPS0090-TA-0220-002-B	2	WOOD POLE	1	\$ 112.10	\$ 77.75
HPS0090-TA-0310-002-B	2	STEEL POLE	1	\$ 110.81	\$ 76.66
HPS0100-ST-0060-002-B	2	SHARED OR NO POLE	1	\$ 103.02	\$ 70.64
HPS0100-ST-0230-002-B	2	WOOD POLE	1	\$ 117.96	\$ 84.12
HPS0100-ST-0320-002-B	2	STEEL POLE	1	\$ 116.67	\$ 83.03
HPS0100-ST-0390-002-B	2	STEEL POLE	2	\$ 109.84	\$ 80.58
HPS0100-ST-0610-002-B	2	SHARED OR NO POLE	1	\$ 103.02	\$ 70.64
HPS0100-ST-1070-002-B	2	WOOD POLE	1	\$ 117.96	\$ 84.12
HPS0100-ST-1120-002-B	2	STEEL POLE	1	\$ 116.67	\$ 83.03
HPS0100-ST-1160-002-B	2	WOOD POLE	2	\$ 110.49	\$ 81.43
HPS0110-ST-0060-002-B	2	SHARED OR NO POLE	1	\$ 107.64	\$ 66.63
HPS0110-ST-0230-002-B	2	WOOD POLE	1	\$ 122.58	\$ 80.10
HPS0110-ST-0320-002-B	2	STEEL POLE	1	\$ 121.28	\$ 79.01
HPS0110-ST-0390-002-B	2	STEEL POLE	2	\$ 114.46	\$ 76.57
HPS0110-ST-0430-002-B	2	STEEL POLE	3	\$ 112.19	\$ 75.75
HPS0110-ST-0470-002-B	2	STEEL POLE	4	\$ 111.05	\$ 75.34
HPS0110-ST-0510-002-B	2	R/BOUT COLUMN	2	\$ 114.46	\$ 76.57
HPS0110-ST-0550-002-B	2	R/BOUT COLUMN	3	\$ 112.19	\$ 75.75
HPS0110-ST-0590-002-B	2	R/BOUT COLUMN	4	\$ 111.05	\$ 75.34
HPS0110-ST-0610-002-B	2	SHARED OR NO POLE	1	\$ 107.64	\$ 66.63
HPS0110-ST-0650-002-B	2	SHARED OR NO POLE	2	\$ 107.64	\$ 66.63
HPS0110-ST-0760-002-B	2	WOOD POLE	2	\$ 115.11	\$ 77.42

ANNUALTARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
HPS0110-ST-0960-002-B	2	SHARED OR NO POLE	2	\$ 107.64	\$ 66.63
HPS0110-ST-0970-002-B	2	SHARED OR NO POLE	4	\$ 107.64	\$ 66.63
HPS0110-ST-1070-002-B	2	WOOD POLE	1	\$ 122.58	\$ 80.10
HPS0110-ST-1120-002-B	2	STEEL POLE	1	\$ 121.28	\$ 79.01
HPS0110-ST-1140-002-B	2	STEEL POLE	2	\$ 114.46	\$ 76.57
HPS0110-ST-1160-002-B	2	WOOD POLE	2	\$ 115.11	\$ 77.42
HPS0110-ST-1380-002-B	2	R/BOUT COLUMN	3	\$ 112.19	\$ 75.75
HPS0110-ST-1450-002-B	2	R/BOUT COLUMN	4	\$ 111.05	\$ 75.34
HPS0110-TA-0060-002-B	2	SHARED OR NO POLE	1	\$ 97.54	\$ 61.50
HPS0110-TA-0230-002-B	2	WOOD POLE	1	\$ 112.48	\$ 74.97
HPS0110-TA-0320-002-B	2	STEEL POLE	1	\$ 111.18	\$ 73.88
HPS0110-TA-0590-002-B	2	R/BOUT COLUMN	4	\$ 100.95	\$ 70.21
HPS0110-TA-1070-002-B	2	WOOD POLE	1	\$ 112.48	\$ 74.97
HPS0120-ST-0860-002-B	2	R/BOUT COLUMN	3	\$ 128.15	\$ 92.84
HPS0120-ST-1490-002-B	2	R/BOUT COLUMN	2	\$ 130.42	\$ 93.66
HPS0140-ST-0070-002-B	2	SHARED OR NO POLE	1	\$ 103.02	\$ 69.88
HPS0140-ST-0330-002-B	2	STEEL POLE	1	\$ 116.67	\$ 82.27
HPS0160-ST-0070-002-B	2	SHARED OR NO POLE	1	\$ 111.69	\$ 76.32
HPS0160-ST-0240-002-B	2	WOOD POLE	1	\$ 126.63	\$ 89.80
HPS0160-ST-0330-002-B	2	STEEL POLE	1	\$ 125.34	\$ 88.71
HPS0160-ST-0400-002-B	2	STEEL POLE	2	\$ 118.51	\$ 86.26
HPS0160-ST-0620-002-B	2	SHARED OR NO POLE	1	\$ 111.69	\$ 76.32
HPS0160-ST-1130-002-B	2	STEEL POLE	2	\$ 118.51	\$ 86.26
HPS0160-ST-1170-002-B	2	STEEL POLE	1	\$ 125.34	\$ 88.71
HPS0170-ST-0070-002-B	2	SHARED OR NO POLE	1	\$ 111.98	\$ 71.00
HPS0170-ST-0240-002-B	2	WOOD POLE	1	\$ 126.92	\$ 84.48
HPS0170-ST-0270-002-B	2	R/BOUT COLUMN	3	\$ 116.53	\$ 80.12
HPS0170-ST-0330-002-B	2	STEEL POLE	1	\$ 125.63	\$ 83.39
HPS0170-ST-0400-002-B	2	STEEL POLE	2	\$ 118.81	\$ 80.94
HPS0170-ST-0440-002-B	2	STEEL POLE	3	\$ 116.53	\$ 80.12
HPS0170-ST-0480-002-B	2	STEEL POLE	4	\$ 115.39	\$ 79.72
HPS0170-ST-0560-002-B	2	R/BOUT COLUMN	3	\$ 116.53	\$ 80.12
HPS0170-ST-0600-002-B	2	R/BOUT COLUMN	4	\$ 115.39	\$ 79.72

ANNUALTARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
HPS0170-ST-0620-002-B	2	SHARED OR NO POLE	1	\$ 111.98	\$ 71.00
HPS0170-ST-0660-002-B	2	SHARED OR NO POLE	2	\$ 111.98	\$ 71.00
HPS0170-ST-0770-002-B	2	WOOD POLE	2	\$ 119.45	\$ 81.80
HPS0170-ST-1030-002-B	2	SHARED OR NO POLE	2	\$ 111.98	\$ 71.00
HPS0170-ST-1080-002-B	2	WOOD POLE	1	\$ 111.98	\$ 71.00
HPS0170-ST-1130-002-B	2	STEEL POLE	2	\$ 118.81	\$ 80.94
HPS0170-ST-1170-002-B	2	STEEL POLE	1	\$ 125.63	\$ 83.39
HPS0170-TA-0600-002-B	2	R/BOUT COLUMN	4	\$ 109.69	\$ 78.92
HPS0180-ST-0870-002-B	2	R/BOUT COLUMN	4	\$ 135.21	\$ 101.00
HPS0190-ST-1470-002-B	2	R/BOUT COLUMN	1	\$ 161.15	\$ 124.49
HPS0250-ST-0120-002-B	2	SHARED OR NO POLE	1	\$ 95.74	\$ 155.19
HPS0250-ST-1050-002-B	2	R/BOUT COLUMN	4	\$ 99.15	\$ 163.90
INC0030-ST-0010-002-B	2	SHARED OR NO POLE	1	\$ 26.99	\$ 59.06
INC0030-ST-0810-002-B	2	WOOD POLE	1	\$ 41.93	\$ 72.54
INC0030-ST-0820-002-B	2	SHARED OR NO POLE	3	\$ 26.99	\$ 59.06
INC0030-ST-0990-002-B	2	STEEL POLE	1	\$ 40.63	\$ 71.45
INC0050-ST-0010-002-B	2	SHARED OR NO POLE	1	\$ 26.99	\$ 59.06
INC0050-ST-0810-002-B	2	WOOD POLE	1	\$ 41.93	\$ 72.54
INC0080-ST-0010-002-B	2	SHARED OR NO POLE	1	\$ 24.02	\$ 60.23
INC0090-ST-0010-002-B	2	SHARED OR NO POLE	1	\$ 24.02	\$ 60.23
INC0100-ST-0740-002-B	2	SHARED OR NO POLE	2	\$ 24.02	\$ 60.23
INC0110-ST-0010-002-B	2	SHARED OR NO POLE	1	\$ 24.02	\$ 60.23
INC0160-ST-0620-002-B	2	SHARED OR NO POLE	1	\$ 22.28	\$ 59.61
LPS0030-ST-0040-002-B	2	SHARED OR NO POLE	1	\$ 81.73	\$ 65.51
LPS0030-ST-0360-002-B	2	STEEL POLE	1	\$ 95.38	\$ 77.90
LPS0030-ST-0890-002-B	2	SHARED OR NO POLE	2	\$ 81.73	\$ 65.51
LPS0040-ST-0050-002-B	2	SHARED OR NO POLE	1	\$ 84.26	\$ 68.11
LPS0040-ST-0220-002-B	2	WOOD POLE	1	\$ 99.20	\$ 81.59
LPS0040-ST-0310-002-B	2	STEEL POLE	1	\$ 97.91	\$ 80.50
LPS0050-ST-0060-002-B	2	SHARED OR NO POLE	1	\$ 87.01	\$ 71.16
LPS0060-ST-0060-002-B	2	SHARED OR NO POLE	1	\$ 120.35	\$ 86.07
LPS0060-ST-0230-002-B	2	WOOD POLE	1	\$ 135.29	\$ 99.55
LPS0060-ST-0320-002-B	2	STEEL POLE	1	\$ 134.00	\$ 98.45

ANNUALTARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
LPS0060-ST-0390-002-B	2	STEEL POLE	2	\$ 127.17	\$ 96.00
LPS0060-ST-0590-002-B	2	R/BOUT COLUMN	4	\$ 123.76	\$ 94.78
LPS0060-ST-0960-002-B	2	SHARED OR NO POLE	2	\$ 120.35	\$ 86.07
LPS0090-ST-0070-002-B	2	SHARED OR NO POLE	1	\$ 120.35	\$ 86.07
MHR0010-ST-0040-002-B	2	SHARED OR NO POLE	1	\$ 67.10	\$ 67.29
MHR0010-ST-0360-002-B	2	STEEL POLE	1	\$ 80.75	\$ 79.67
MHR0010-ST-0730-002-B	2	STEEL POLE	2	\$ 73.92	\$ 77.22
MHR0030-ST-0050-002-B	2	SHARED OR NO POLE	1	\$ 84.61	\$ 76.50
MHR0030-ST-0310-002-B	2	STEEL POLE	1	\$ 98.25	\$ 88.89
MHR0030-ST-0690-002-B	2	STEEL POLE	2	\$ 91.43	\$ 86.44
MHR0030-ST-0710-002-B	2	STEEL POLE	3	\$ 89.16	\$ 85.62
MHR0060-ST-0060-002-B	2	SHARED OR NO POLE	1	\$ 89.16	\$ 78.13
MHR0060-ST-0320-002-B	2	STEEL POLE	1	\$ 102.80	\$ 90.52
MHR0060-ST-0390-002-B	2	STEEL POLE	2	\$ 95.98	\$ 88.07
MHR0060-ST-0590-002-B	2	R/BOUT COLUMN	4	\$ 92.57	\$ 86.85
MHR0060-ST-0610-002-B	2	SHARED OR NO POLE	1	\$ 89.16	\$ 78.13
MHR0060-ST-0650-002-B	2	SHARED OR NO POLE	2	\$ 89.16	\$ 78.13
MHR0060-ST-1070-002-B	2	WOOD POLE	1	\$ 104.10	\$ 91.61
MHR0060-ST-1120-002-B	2	STEEL POLE	1	\$ 102.80	\$ 90.52
MHR0060-ST-1160-002-B	2	WOOD POLE	2	\$ 96.63	\$ 88.93
MHR0070-ST-0060-002-B	2	SHARED OR NO POLE	1	\$ 89.49	\$ 81.06
MHR0070-ST-0320-002-B	2	STEEL POLE	1	\$ 103.14	\$ 93.45
MHR0070-ST-0390-002-B	2	STEEL POLE	2	\$ 96.32	\$ 91.00
MHR0070-ST-0470-002-B	2	STEEL POLE	4	\$ 92.90	\$ 89.78
MHR0070-ST-0620-002-B	2	SHARED OR NO POLE	1	\$ 89.49	\$ 81.06
MHR0070-ST-0660-002-B	2	SHARED OR NO POLE	2	\$ 89.49	\$ 81.06
MHR0070-ST-1080-002-B	2	WOOD POLE	1	\$ 89.49	\$ 81.06
MHR0070-ST-1170-002-B	2	STEEL POLE	1	\$ 103.14	\$ 93.45
MHR0100-ST-0120-002-B	2	SHARED OR NO POLE	1	\$ 95.53	\$ 154.38
MVA0010-ST-0010-002-B	2	SHARED OR NO POLE	1	\$ 51.02	\$ 41.29
MVA0010-ST-0810-002-B	2	WOOD POLE	1	\$ 65.96	\$ 54.77
MVA0010-ST-0990-002-B	2	STEEL POLE	1	\$ 64.67	\$ 53.68
MVA0010-ST-1000-002-B	2	STEEL POLE	2	\$ 57.84	\$ 51.23

ANNUALTARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
MVA0020-ST-0010-002-B	2	SHARED OR NO POLE	1	\$ 51.02	\$ 41.51
MVA0020-ST-0740-002-B	2	SHARED OR NO POLE	2	\$ 51.02	\$ 41.51
MVA0020-ST-0810-002-B	2	WOOD POLE	1	\$ 65.97	\$ 54.98
MVA0020-ST-0820-002-B	2	SHARED OR NO POLE	3	\$ 51.02	\$ 41.51
MVA0020-ST-0990-002-B	2	STEEL POLE	1	\$ 64.67	\$ 53.89
MVA0020-ST-1000-002-B	2	STEEL POLE	2	\$ 57.85	\$ 51.44
MVA0020-ST-1260-002-B	2	WOOD POLE	2	\$ 58.49	\$ 52.30
MVA0020-ST-1460-002-B	2	STEEL POLE	3	\$ 55.57	\$ 50.63
MVA0080-ST-0010-002-B	2	SHARED OR NO POLE	1	\$ 48.86	\$ 41.03
MVA0080-ST-0740-002-B	2	SHARED OR NO POLE	2	\$ 48.86	\$ 41.03
MVA0080-ST-0810-002-B	2	WOOD POLE	1	\$ 63.80	\$ 54.51
MVA0080-ST-0990-002-B	2	STEEL POLE	1	\$ 62.51	\$ 53.41
MVA0190-ST-0020-002-B	2	SHARED OR NO POLE	1	\$ 62.48	\$ 52.94
MVA0190-ST-0200-002-B	2	WOOD POLE	1	\$ 77.42	\$ 66.42
MVA0190-ST-0290-002-B	2	STEEL POLE	1	\$ 76.13	\$ 65.33
MVA0190-ST-0370-002-B	2	STEEL POLE	2	\$ 69.30	\$ 62.88
MVA0190-ST-0450-002-B	2	STEEL POLE	4	\$ 65.89	\$ 61.66
MVA0190-ST-0780-002-B	2	WOOD POLE	2	\$ 69.95	\$ 63.74
MVA0190-ST-0940-002-B	2	SHARED OR NO POLE	2	\$ 62.48	\$ 52.94
MVA0220-ST-0030-002-B	2	SHARED OR NO POLE	1	\$ 74.24	\$ 68.66
MVA0220-ST-0210-002-B	2	WOOD POLE	1	\$ 89.18	\$ 82.14
MVA0220-ST-0300-002-B	2	STEEL POLE	1	\$ 87.89	\$ 81.04
MVA0220-ST-0380-002-B	2	STEEL POLE	2	\$ 81.06	\$ 78.60
MVA0220-ST-0460-002-B	2	STEEL POLE	4	\$ 77.65	\$ 77.37
MVA0220-ST-0790-002-B	2	WOOD POLE	2	\$ 81.71	\$ 79.46
MVA0220-ST-0950-002-B	2	SHARED OR NO POLE	2	\$ 74.24	\$ 68.66
MVA0260-ST-0250-002-B	2	WOOD POLE	1	\$ 121.98	\$ 89.39
MVA0290-ST-1040-002-B	2	SHARED OR NO POLE	2	\$ 145.70	\$ 120.48
FLU0350-ST-1620-003-B	3	SHARED OR NO POLE	1	\$ 104.17	\$ 111.35
FLU0350-ST-1630-003-B	3	SHARED OR NO POLE	2	\$ 118.94	\$ 136.60
FLU0350-ST-1660-003-B	3	WOOD POLE	1	\$ 207.63	\$ 238.14
FLU0350-ST-1670-003-B	3	WOOD POLE	2	\$ 214.94	\$ 260.70
FLU0350-ST-1700-003-B	3	STEEL POLE	1	\$ 277.48	\$ 328.77

ANNUALTARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
FLU0350-ST-1710-003-B	3	STEEL POLE	2	\$ 285.43	\$ 351.57
FLU0355-ST-1980-003-B	3	SHARED OR NO POLE	1	\$ 108.56	\$ 112.77
FLU0355-ST-2060-003-B	3	STEEL POLE	1	\$ 281.87	\$ 330.19
HPS0010-TA-0090-003-B	3	SHARED OR NO POLE	1	\$ 119.40	\$ 111.19
HPS0010-TA-0140-003-B	3	WOOD POLE	1	\$ 222.87	\$ 237.97
HPS0010-TA-0170-003-B	3	STEEL POLE	1	\$ 292.71	\$ 328.61
HPS0020-ST-0040-003-B	3	SHARED OR NO POLE	1	\$ 120.48	\$ 114.52
HPS0020-ST-0350-003-B	3	WOOD POLE	1	\$ 223.94	\$ 241.31
HPS0020-ST-0360-003-B	3	STEEL POLE	1	\$ 293.79	\$ 331.94
HPS0020-ST-0730-003-B	3	STEEL POLE	2	\$ 306.14	\$ 354.20
HPS0020-ST-0890-003-B	3	SHARED OR NO POLE	2	\$ 139.65	\$ 139.23
HPS0020-TA-0090-003-B	3	SHARED OR NO POLE	1	\$ 121.57	\$ 115.63
HPS0020-TA-0140-003-B	3	WOOD POLE	1	\$ 225.03	\$ 242.42
HPS0020-TA-0170-003-B	3	STEEL POLE	1	\$ 294.88	\$ 333.06
HPS0090-ST-0050-003-B	3	SHARED OR NO POLE	1	\$ 184.80	\$ 166.59
HPS0090-ST-0220-003-B	3	WOOD POLE	1	\$ 288.26	\$ 293.38
HPS0090-ST-0310-003-B	3	STEEL POLE	1	\$ 339.67	\$ 360.84
HPS0090-ST-0690-003-B	3	STEEL POLE	2	\$ 364.03	\$ 398.15
HPS0090-TA-0220-003-B	3	WOOD POLE	1	\$ 279.32	\$ 292.54
HPS0090-TA-0310-003-B	3	STEEL POLE	1	\$ 330.73	\$ 360.00
HPS0110-ST-0060-003-B	3	SHARED OR NO POLE	1	\$ 186.67	\$ 168.42
HPS0110-ST-0230-003-B	3	WOOD POLE	1	\$ 290.13	\$ 295.21
HPS0110-ST-0320-003-B	3	STEEL POLE	1	\$ 341.54	\$ 362.67
HPS0110-ST-0390-003-B	3	STEEL POLE	2	\$ 366.23	\$ 400.39
HPS0110-ST-0590-003-B	3	R/BOUT COLUMN	4	\$ 547.70	\$ 635.37
HPS0110-ST-0610-003-B	3	SHARED OR NO POLE	1	\$ 199.61	\$ 184.65
HPS0110-ST-0760-003-B	3	WOOD POLE	2	\$ 314.17	\$ 332.70
HPS0110-ST-0960-003-B	3	SHARED OR NO POLE	2	\$ 218.18	\$ 208.60
HPS0110-ST-1070-003-B	3	WOOD POLE	1	\$ 303.07	\$ 311.44
HPS0110-ST-1120-003-B	3	STEEL POLE	1	\$ 354.48	\$ 378.89
HPS0110-TA-0060-003-B	3	SHARED OR NO POLE	1	\$ 176.57	\$ 163.33
HPS0110-TA-0230-003-B	3	WOOD POLE	1	\$ 280.03	\$ 290.12
HPS0110-TA-0320-003-B	3	STEEL POLE	1	\$ 331.44	\$ 357.57

ANNUALTARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
HPS0170-ST-0070-003-B	3	SHARED OR NO POLE	1	\$ 200.31	\$ 184.50
HPS0170-ST-0240-003-B	3	WOOD POLE	1	\$ 303.77	\$ 311.29
HPS0170-ST-0330-003-B	3	STEEL POLE	1	\$ 355.18	\$ 378.75
HPS0170-ST-0620-003-B	3	SHARED OR NO POLE	1	\$ 196.92	\$ 180.26
HPS0170-ST-1130-003-B	3	STEEL POLE	2	\$ 408.75	\$ 452.68
HPS0170-ST-1170-003-B	3	STEEL POLE	1	\$ 364.97	\$ 391.03
MHR0060-ST-0060-003-B	3	SHARED OR NO POLE	1	\$ 168.18	\$ 180.27
MHR0060-ST-0320-003-B	3	STEEL POLE	1	\$ 323.06	\$ 374.52
MHR0060-ST-0610-003-B	3	SHARED OR NO POLE	1	\$ 181.13	\$ 196.49
MHR0060-ST-1120-003-B	3	STEEL POLE	1	\$ 336.00	\$ 390.74
MHR0070-ST-0620-003-B	3	SHARED OR NO POLE	1	\$ 174.43	\$ 190.66
MVA0020-ST-0010-003-B	3	SHARED OR NO POLE	1	\$ 96.14	\$ 100.61
MVA0020-ST-0810-003-B	3	WOOD POLE	1	\$ 199.61	\$ 227.40
MVA0020-ST-0990-003-B	3	STEEL POLE	1	\$ 269.45	\$ 318.03
MVA0190-ST-0020-003-B	3	SHARED OR NO POLE	1	\$ 142.43	\$ 155.88
MVA0190-ST-0200-003-B	3	WOOD POLE	1	\$ 245.90	\$ 282.67
MVA0190-ST-0290-003-B	3	STEEL POLE	1	\$ 297.30	\$ 350.12
FLU0130-ST-0010-004-B	4	SHARED OR NO POLE	1	\$ 42.21	\$ 42.70
FLU0240-ST-0010-004-B	4	SHARED OR NO POLE	1	\$ 47.07	\$ 44.44
FLU0350-ST-1620-004-B	4	SHARED OR NO POLE	1	\$ 60.31	\$ 47.96
FLU0350-ST-1630-004-B	4	SHARED OR NO POLE	2	\$ 60.31	\$ 47.96
FLU0350-ST-1640-004-B	4	SHARED OR NO POLE	3	\$ 60.31	\$ 47.96
FLU0350-ST-1650-004-B	4	SHARED OR NO POLE	4	\$ 60.31	\$ 47.96
FLU0350-ST-1660-004-B	4	WOOD POLE	1	\$ 75.25	\$ 61.47
FLU0350-ST-1670-004-B	4	WOOD POLE	2	\$ 67.78	\$ 58.79
FLU0350-ST-1700-004-B	4	STEEL POLE	1	\$ 73.96	\$ 60.38
FLU0350-ST-1710-004-B	4	STEEL POLE	2	\$ 67.14	\$ 57.93
FLU0350-ST-1720-004-B	4	STEEL POLE	3	\$ 64.86	\$ 57.11
FLU0350-ST-1730-004-B	4	STEEL POLE	4	\$ 63.73	\$ 56.71
FLU0355-ST-1980-004-B	4	SHARED OR NO POLE	1	\$ 64.74	\$ 49.46
FLU0355-ST-2060-004-B	4	STEEL POLE	1	\$ 78.39	\$ 61.87
HPS0010-TA-0090-004-B	4	SHARED OR NO POLE	1	\$ 68.40	\$ 44.89
HPS0010-TA-0140-004-B	4	WOOD POLE	1	\$ 83.34	\$ 58.39

ANNUALTARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
HPS0010-TA-0170-004-B	4	STEEL POLE	1	\$ 82.05	\$ 57.31
HPS0020-ST-0040-004-B	4	SHARED OR NO POLE	1	\$ 72.23	\$ 51.67
HPS0020-ST-0350-004-B	4	WOOD POLE	1	\$ 87.17	\$ 65.18
HPS0020-ST-0360-004-B	4	STEEL POLE	1	\$ 85.87	\$ 64.08
HPS0020-ST-0730-004-B	4	STEEL POLE	2	\$ 79.05	\$ 61.64
HPS0020-ST-0880-004-B	4	STEEL POLE	4	\$ 75.64	\$ 60.41
HPS0020-ST-0890-004-B	4	SHARED OR NO POLE	2	\$ 72.23	\$ 51.67
HPS0020-ST-0910-004-B	4	WOOD POLE	2	\$ 79.70	\$ 62.50
HPS0020-TA-0090-004-B	4	SHARED OR NO POLE	1	\$ 70.56	\$ 49.33
HPS0020-TA-0140-004-B	4	WOOD POLE	1	\$ 85.50	\$ 62.85
HPS0020-TA-0170-004-B	4	STEEL POLE	1	\$ 84.21	\$ 61.75
HPS0090-ST-0050-004-B	4	SHARED OR NO POLE	1	\$ 106.10	\$ 65.52
HPS0090-ST-0220-004-B	4	WOOD POLE	1	\$ 121.04	\$ 79.02
HPS0090-ST-0310-004-B	4	STEEL POLE	1	\$ 119.75	\$ 77.93
HPS0090-ST-0690-004-B	4	STEEL POLE	2	\$ 112.92	\$ 75.48
HPS0090-ST-0710-004-B	4	STEEL POLE	3	\$ 110.65	\$ 74.66
HPS0090-ST-0720-004-B	4	STEEL POLE	4	\$ 109.51	\$ 74.25
HPS0090-ST-0980-004-B	4	WOOD POLE	2	\$ 113.57	\$ 76.34
HPS0090-ST-1010-004-B	4	SHARED OR NO POLE	2	\$ 106.10	\$ 65.52
HPS0090-ST-1360-004-B	4	R/BOUT COLUMN	3	\$ 110.65	\$ 74.66
HPS0090-TA-0050-004-B	4	SHARED OR NO POLE	1	\$ 97.16	\$ 64.68
HPS0090-TA-0310-004-B	4	STEEL POLE	1	\$ 110.81	\$ 77.09
HPS0110-ST-0060-004-B	4	SHARED OR NO POLE	1	\$ 107.64	\$ 66.94
HPS0110-ST-0230-004-B	4	WOOD POLE	1	\$ 122.58	\$ 80.44
HPS0110-ST-0320-004-B	4	STEEL POLE	1	\$ 121.28	\$ 79.35
HPS0110-ST-0390-004-B	4	STEEL POLE	2	\$ 114.46	\$ 76.90
HPS0110-ST-0430-004-B	4	STEEL POLE	3	\$ 112.19	\$ 76.09
HPS0110-ST-0470-004-B	4	STEEL POLE	4	\$ 111.05	\$ 75.68
HPS0110-ST-0550-004-B	4	R/BOUT COLUMN	3	\$ 112.19	\$ 76.09
HPS0110-ST-0590-004-B	4	R/BOUT COLUMN	4	\$ 111.05	\$ 75.68
HPS0110-ST-0610-004-B	4	SHARED OR NO POLE	1	\$ 107.64	\$ 66.94
HPS0110-ST-0650-004-B	4	SHARED OR NO POLE	2	\$ 107.64	\$ 66.94
HPS0110-ST-0760-004-B	4	WOOD POLE	2	\$ 115.11	\$ 77.76

ANNUALTARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
HPS0110-ST-0960-004-B	4	SHARED OR NO POLE	2	\$ 107.64	\$ 66.94
HPS0110-ST-0970-004-B	4	SHARED OR NO POLE	4	\$ 107.64	\$ 66.94
HPS0110-ST-1070-004-B	4	WOOD POLE	1	\$ 122.58	\$ 80.44
HPS0110-ST-1120-004-B	4	STEEL POLE	1	\$ 121.28	\$ 79.35
HPS0110-ST-1160-004-B	4	WOOD POLE	2	\$ 115.11	\$ 77.76
HPS0110-ST-1380-004-B	4	R/BOUT COLUMN	3	\$ 112.19	\$ 76.09
HPS0110-ST-1450-004-B	4	R/BOUT COLUMN	4	\$ 111.05	\$ 75.68
HPS0110-TA-0060-004-B	4	SHARED OR NO POLE	1	\$ 97.54	\$ 61.85
HPS0110-TA-0230-004-B	4	WOOD POLE	1	\$ 112.48	\$ 75.35
HPS0110-TA-0320-004-B	4	STEEL POLE	1	\$ 111.18	\$ 74.26
HPS0110-TA-0590-004-B	4	R/BOUT COLUMN	4	\$ 100.95	\$ 70.58
HPS0120-ST-0860-004-B	4	R/BOUT COLUMN	3	\$ 128.15	\$ 93.42
HPS0170-ST-0070-004-B	4	SHARED OR NO POLE	1	\$ 111.98	\$ 71.37
HPS0170-ST-0240-004-B	4	WOOD POLE	1	\$ 126.92	\$ 84.88
HPS0170-ST-0270-004-B	4	R/BOUT COLUMN	3	\$ 116.53	\$ 80.52
HPS0170-ST-0330-004-B	4	STEEL POLE	1	\$ 125.63	\$ 83.79
HPS0170-ST-0400-004-B	4	STEEL POLE	2	\$ 118.81	\$ 81.34
HPS0170-ST-0440-004-B	4	STEEL POLE	3	\$ 116.53	\$ 80.52
HPS0170-ST-0480-004-B	4	STEEL POLE	4	\$ 115.39	\$ 80.11
HPS0170-ST-0560-004-B	4	R/BOUT COLUMN	3	\$ 116.53	\$ 80.52
HPS0170-ST-0600-004-B	4	R/BOUT COLUMN	4	\$ 115.39	\$ 80.11
HPS0170-ST-0620-004-B	4	SHARED OR NO POLE	1	\$ 111.98	\$ 71.37
HPS0170-ST-0660-004-B	4	SHARED OR NO POLE	2	\$ 111.98	\$ 71.37
HPS0170-ST-0900-004-B	4	WOOD POLE	2	\$ 119.45	\$ 82.19
HPS0170-ST-1030-004-B	4	SHARED OR NO POLE	2	\$ 111.98	\$ 71.37
HPS0170-ST-1130-004-B	4	STEEL POLE	2	\$ 118.81	\$ 81.34
HPS0170-ST-1170-004-B	4	STEEL POLE	1	\$ 125.63	\$ 83.79
HPS0190-ST-1470-004-B	4	R/BOUT COLUMN	1	\$ 161.15	\$ 125.49
HPS0250-ST-1050-004-B	4	R/BOUT COLUMN	4	\$ 99.15	\$ 166.19
MHR0010-ST-0040-004-B	4	SHARED OR NO POLE	1	\$ 67.10	\$ 67.92
MHR0010-ST-0360-004-B	4	STEEL POLE	1	\$ 80.75	\$ 80.33
MHR0060-ST-0060-004-B	4	SHARED OR NO POLE	1	\$ 89.16	\$ 78.78
MHR0060-ST-0320-004-B	4	STEEL POLE	1	\$ 102.80	\$ 91.20

ANNUALTARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
MHR0060-ST-0390-004-B	4	STEEL POLE	2	\$ 95.98	\$ 88.75
MHR0060-ST-0610-004-B	4	SHARED OR NO POLE	1	\$ 89.16	\$ 78.78
MHR0070-ST-0060-004-B	4	SHARED OR NO POLE	1	\$ 89.49	\$ 81.77
MHR0070-ST-0320-004-B	4	STEEL POLE	1	\$ 103.14	\$ 94.19
MHR0070-ST-0620-004-B	4	SHARED OR NO POLE	1	\$ 89.49	\$ 81.77
MHR0070-ST-1170-004-B	4	STEEL POLE	1	\$ 103.14	\$ 94.19
MHR0100-ST-0120-004-B	4	SHARED OR NO POLE	1	\$ 95.53	\$ 156.63
MVA0010-ST-0010-004-B	4	SHARED OR NO POLE	1	\$ 51.02	\$ 41.47
MVA0010-ST-0990-004-B	4	STEEL POLE	1	\$ 64.67	\$ 53.89
MVA0020-ST-0010-004-B	4	SHARED OR NO POLE	1	\$ 51.02	\$ 41.69
MVA0020-ST-0740-004-B	4	SHARED OR NO POLE	2	\$ 51.02	\$ 41.69
MVA0020-ST-0810-004-B	4	WOOD POLE	1	\$ 65.97	\$ 55.19
MVA0020-ST-0990-004-B	4	STEEL POLE	1	\$ 64.67	\$ 54.11
MVA0020-ST-1000-004-B	4	STEEL POLE	2	\$ 57.85	\$ 51.66
MVA0190-ST-0020-004-B	4	SHARED OR NO POLE	1	\$ 62.48	\$ 53.23
MVA0190-ST-0200-004-B	4	WOOD POLE	1	\$ 77.42	\$ 66.74
MVA0190-ST-0290-004-B	4	STEEL POLE	1	\$ 76.13	\$ 65.64
MVA0190-ST-0570-004-B	4	R/BOUT COLUMN	4	\$ 65.89	\$ 61.97
MVA0220-ST-0030-004-B	4	SHARED OR NO POLE	1	\$ 74.24	\$ 69.19
MVA0220-ST-0210-004-B	4	WOOD POLE	1	\$ 89.18	\$ 82.71
FLU0350-ST-1620-005-B	5	SHARED OR NO POLE	1	\$ 154.13	\$ 135.03
HPS0010-ST-0040-005-B	5	SHARED OR NO POLE	1	\$ 161.31	\$ 142.63
HPS0010-ST-0360-005-B	5	STEEL POLE	1	\$ 334.69	\$ 277.36
HPS0020-ST-0040-005-B	5	SHARED OR NO POLE	1	\$ 164.46	\$ 145.84
HPS0020-ST-0350-005-B	5	WOOD POLE	1	\$ 293.63	\$ 247.45
HPS0020-ST-0360-005-B	5	STEEL POLE	1	\$ 337.85	\$ 280.57
HPS0020-ST-0730-005-B	5	STEEL POLE	2	\$ 365.81	\$ 301.54
HPS0020-ST-0750-005-B	5	SHARED OR NO POLE	3	\$ 234.04	\$ 201.66
HPS0020-ST-0890-005-B	5	SHARED OR NO POLE	2	\$ 199.25	\$ 173.75
HPS0020-ST-0910-005-B	5	WOOD POLE	2	\$ 320.95	\$ 267.76
HPS0070-ST-0040-005-B	5	SHARED OR NO POLE	1	\$ 164.46	\$ 145.84
HPS0090-ST-0050-005-B	5	SHARED OR NO POLE	1	\$ 228.01	\$ 203.32
HPS0090-ST-0220-005-B	5	WOOD POLE	1	\$ 357.18	\$ 304.93

ANNUALTARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
HPS0090-ST-0310-005-B	5	STEEL POLE	1	\$ 380.29	\$ 322.07
HPS0090-ST-0690-005-B	5	STEEL POLE	2	\$ 416.82	\$ 350.12
HPS0090-ST-0710-005-B	5	STEEL POLE	3	\$ 457.91	\$ 382.79
HPS0090-ST-0980-005-B	5	WOOD POLE	2	\$ 393.07	\$ 332.31
HPS0090-ST-1010-005-B	5	SHARED OR NO POLE	2	\$ 271.37	\$ 238.30
HPS0090-ST-1360-005-B	5	R/BOUT COLUMN	3	\$ 581.50	\$ 476.29
HPS0090-TA-0050-005-B	5	SHARED OR NO POLE	1	\$ 219.07	\$ 194.23
HPS0090-TA-0220-005-B	5	WOOD POLE	1	\$ 348.24	\$ 295.84
HPS0090-TA-0310-005-B	5	STEEL POLE	1	\$ 371.35	\$ 312.99
HPS0090-TA-0690-005-B	5	STEEL POLE	2	\$ 407.88	\$ 341.03
HPS0090-TA-1010-005-B	5	SHARED OR NO POLE	2	\$ 262.43	\$ 229.21
HPS0090-TA-1370-005-B	5	R/BOUT COLUMN	4	\$ 614.79	\$ 501.03
HPS0100-ST-0230-005-B	5	WOOD POLE	1	\$ 354.25	\$ 301.92
HPS0100-ST-0430-005-B	5	STEEL POLE	3	\$ 455.28	\$ 380.02
HPS0110-ST-0060-005-B	5	SHARED OR NO POLE	1	\$ 229.70	\$ 205.01
HPS0110-ST-0230-005-B	5	WOOD POLE	1	\$ 358.87	\$ 306.62
HPS0110-ST-0320-005-B	5	STEEL POLE	1	\$ 381.98	\$ 323.76
HPS0110-ST-0390-005-B	5	STEEL POLE	2	\$ 418.66	\$ 351.93
HPS0110-ST-0470-005-B	5	STEEL POLE	4	\$ 502.27	\$ 418.67
HPS0110-ST-0550-005-B	5	R/BOUT COLUMN	3	\$ 583.49	\$ 478.23
HPS0110-ST-0590-005-B	5	R/BOUT COLUMN	4	\$ 625.87	\$ 512.17
HPS0110-ST-0760-005-B	5	WOOD POLE	2	\$ 394.91	\$ 334.12
HPS0110-ST-0930-005-B	5	WOOD POLE	3	\$ 435.93	\$ 366.70
HPS0110-ST-0960-005-B	5	SHARED OR NO POLE	2	\$ 273.21	\$ 240.11
HPS0110-TA-0060-005-B	5	SHARED OR NO POLE	1	\$ 219.60	\$ 194.74
HPS0110-TA-0230-005-B	5	WOOD POLE	1	\$ 348.77	\$ 296.35
HPS0110-TA-0320-005-B	5	STEEL POLE	1	\$ 371.88	\$ 313.49
HPS0110-TA-0390-005-B	5	STEEL POLE	2	\$ 408.56	\$ 341.66
HPS0110-TA-0590-005-B	5	R/BOUT COLUMN	4	\$ 615.77	\$ 501.90
HPS0110-TA-0960-005-B	5	SHARED OR NO POLE	2	\$ 263.11	\$ 229.84
HPS0140-ST-0070-005-B	5	SHARED OR NO POLE	1	\$ 235.34	\$ 208.77
HPS0140-ST-0330-005-B	5	STEEL POLE	1	\$ 387.61	\$ 327.52
HPS0140-ST-0400-005-B	5	STEEL POLE	2	\$ 434.55	\$ 364.15

ANNUALTARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
HPS0140-ST-1030-005-B	5	SHARED OR NO POLE	2	\$ 289.10	\$ 252.33
HPS0160-ST-0070-005-B	5	SHARED OR NO POLE	1	\$ 244.01	\$ 217.59
HPS0160-ST-0240-005-B	5	WOOD POLE	1	\$ 373.17	\$ 319.19
HPS0160-ST-0330-005-B	5	STEEL POLE	1	\$ 396.28	\$ 336.34
HPS0160-ST-0770-005-B	5	WOOD POLE	2	\$ 419.46	\$ 355.16
HPS0170-ST-0070-005-B	5	SHARED OR NO POLE	1	\$ 244.30	\$ 217.88
HPS0170-ST-0240-005-B	5	WOOD POLE	1	\$ 373.46	\$ 319.49
HPS0170-ST-0330-005-B	5	STEEL POLE	1	\$ 396.57	\$ 336.64
HPS0170-ST-0400-005-B	5	STEEL POLE	2	\$ 443.51	\$ 373.26
HPS0170-ST-0600-005-B	5	R/BOUT COLUMN	4	\$ 671.22	\$ 550.42
HPS0170-ST-0770-005-B	5	WOOD POLE	2	\$ 419.76	\$ 355.46
HPS0170-ST-1030-005-B	5	SHARED OR NO POLE	2	\$ 298.06	\$ 261.45
HPS0170-TA-0070-005-B	5	SHARED OR NO POLE	1	\$ 238.60	\$ 212.08
HPS0170-TA-0240-005-B	5	WOOD POLE	1	\$ 367.76	\$ 313.69
HPS0170-TA-0330-005-B	5	STEEL POLE	1	\$ 390.87	\$ 330.84
HPS0170-TA-0400-005-B	5	STEEL POLE	2	\$ 437.81	\$ 367.46
HPS0170-TA-0600-005-B	5	R/BOUT COLUMN	4	\$ 665.52	\$ 544.62
LPS0030-ST-0040-005-B	5	SHARED OR NO POLE	1	\$ 173.97	\$ 155.50
LPS0030-ST-0350-005-B	5	WOOD POLE	1	\$ 303.13	\$ 257.11
LPS0030-ST-0360-005-B	5	STEEL POLE	1	\$ 347.35	\$ 290.23
LPS0030-ST-0890-005-B	5	SHARED OR NO POLE	2	\$ 208.76	\$ 183.41
LPS0040-ST-0050-005-B	5	SHARED OR NO POLE	1	\$ 206.18	\$ 181.12
LPS0040-ST-0220-005-B	5	WOOD POLE	1	\$ 335.34	\$ 282.73
LPS0040-ST-0310-005-B	5	STEEL POLE	1	\$ 358.45	\$ 299.87
LPS0050-ST-0060-005-B	5	SHARED OR NO POLE	1	\$ 209.08	\$ 184.04
LPS0050-ST-0230-005-B	5	WOOD POLE	1	\$ 338.24	\$ 285.64
LPS0050-ST-0320-005-B	5	STEEL POLE	1	\$ 361.35	\$ 302.79
LPS0060-ST-0060-005-B	5	SHARED OR NO POLE	1	\$ 242.42	\$ 217.94
MHR0060-ST-0060-005-B	5	SHARED OR NO POLE	1	\$ 211.22	\$ 186.22
MHR0060-ST-0320-005-B	5	STEEL POLE	1	\$ 363.50	\$ 304.97
MHR0070-ST-0060-005-B	5	SHARED OR NO POLE	1	\$ 211.56	\$ 186.56
MHR0070-ST-0320-005-B	5	STEEL POLE	1	\$ 363.83	\$ 305.31
FLU0350-ST-1620-005-B	5	SHARED OR NO POLE	1	\$ 154.13	\$ 135.03

ANNUALTARIFF_ID	Tariff Type	Dedicated Support Type	No. of Lights	SLUOS charge	
HPS0020-ST-0040-005-B	5	SHARED OR NO POLE	1	\$ 164.46	\$ 145.84
HPS0020-ST-0350-005-B	5	WOOD POLE	1	\$ 293.63	\$ 247.45
HPS0020-ST-0360-005-B	5	STEEL POLE	1	\$ 337.85	\$ 280.57
HPS0020-ST-0730-005-B	5	STEEL POLE	2	\$ 365.81	\$ 301.54
HPS0020-ST-0890-005-B	5	SHARED OR NO POLE	2	\$ 199.25	\$ 173.75
HPS0090-ST-0050-005-B	5	SHARED OR NO POLE	1	\$ 228.01	\$ 203.32
HPS0090-ST-0220-005-B	5	WOOD POLE	1	\$ 357.18	\$ 304.93
HPS0090-ST-0310-005-B	5	STEEL POLE	1	\$ 380.29	\$ 322.07
HPS0090-ST-0690-005-B	5	STEEL POLE	2	\$ 416.82	\$ 350.12
HPS0090-TA-0220-005-B	5	WOOD POLE	1	\$ 348.24	\$ 295.84
HPS0090-TA-0310-005-B	5	STEEL POLE	1	\$ 371.35	\$ 312.99
HPS0110-ST-0060-005-B	5	SHARED OR NO POLE	1	\$ 229.70	\$ 205.01
HPS0110-ST-0230-005-B	5	WOOD POLE	1	\$ 358.87	\$ 306.62
HPS0110-ST-0320-005-B	5	STEEL POLE	1	\$ 381.98	\$ 323.76
HPS0110-ST-0390-005-B	5	STEEL POLE	2	\$ 418.66	\$ 351.93
HPS0110-ST-0590-005-B	5	R/BOUT COLUMN	4	\$ 625.87	\$ 512.17
HPS0110-ST-0760-005-B	5	WOOD POLE	2	\$ 394.91	\$ 334.12
HPS0110-ST-0960-005-B	5	SHARED OR NO POLE	2	\$ 273.21	\$ 240.11
HPS0110-TA-0060-005-B	5	SHARED OR NO POLE	1	\$ 219.60	\$ 194.74
HPS0110-TA-0230-005-B	5	WOOD POLE	1	\$ 348.77	\$ 296.35
HPS0110-TA-0320-005-B	5	STEEL POLE	1	\$ 371.88	\$ 313.49
HPS0170-ST-0070-005-B	5	SHARED OR NO POLE	1	\$ 244.30	\$ 217.88
HPS0170-ST-0240-005-B	5	WOOD POLE	1	\$ 373.46	\$ 319.49
HPS0170-ST-0330-005-B	5	STEEL POLE	1	\$ 396.57	\$ 336.64
MHR0060-ST-0060-005-B	5	SHARED OR NO POLE	1	\$ 211.22	\$ 186.22
MHR0060-ST-0320-005-B	5	STEEL POLE	1	\$ 363.50	\$ 304.97
MVA0190-ST-0290-005-B	5	STEEL POLE	1	\$ 342.68	\$ 282.69